


NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
<u>BOOK 1</u>			
Kent's Corner-Old West Church Hist. Dist.	1205-1	79-A-120 80-A-30	
Bailey-Moser House	1205-2	79-A-105	
Balentine Barn	1205-3	79-A-106	
Lynch House	1205-4	79-A-52	
Old District #1 School-The Mill House	1205-5	79-A-52	
Old Sparrow Place-Sloan House	1205-7	79-A-52	
Fowler House	1205-8	79-A-52	
Bliss Tavern-Scott House	1205-9	79-A-52	
Leonard-Graham Farm	1205-10	79-A-52	
Liff Farm	1205-11	79-A-51	
Adamant Methodist Church	1205-12	79-A-51	
Adamant Community Club	1205-13	79-A-105	
Morreale House	1205-14	79-A-51	
LaFountain House	1205-15	79-A-51	
Aaron Tucker-Morse House	1205-16	79-A-52	
Aaron Tucker Farm-Morse Farm	1205-17	79-A-97	
Old Bruce Place-Bradley House	1205-18	79-A-51	
Laqueur House	1205-19	79-A-51	
Levi Robinson House-Cherington Farm	1205-20	79-A-51	
Old Van Ornam House-Ott House	1205-21	79-A-97	
George Kent Farm-Patrick Henry Farm	1205-22	79-A-98, 97	
Old Wheeler Place-Stevenson House	1205-23	79-A-98	
Wheeler-Persons Farm Gitana/Khona House	1205-24	79-A-98	
Old Wheelock Place	1205-25	79-A-98 82-A-290	
Bennett Farm-Murphy House	1205-26	79-A-97	
Maple Corner Historic District	1205-27	80-A-30	
Rossiter House	1205-28	79-A-97	
Burkis House	1205-29	79-A-97	


NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
Holt House	1205-30	79-A-97	
Savage House	1205-31	79-A-52	
Murray House	1205-32	79-A-51	
Davis Church-Calais Town Hall	1205-33	79-A-52	
Brook-Herriott House	1205-34	79-A-104	
Cameron Place-Fair House	1205-35	79-A-104	
North Calais School-Rinen House	1205-36	79-A-104	
Scribner Dam	1205-37	80-A-30 82-A-291	
Franklin/Scribner House	1205-38	79-A-105 79-A-104	
North Calais Historic District	1205-39	80-A-30	
Memorial Hall	1205-40	79-A-106	
Comolli House <i>Book II</i>	1205-41	79-A-106	
Altman House	1205-42	79-A-106	
Laing House	1205-43	79-A-106	
The Old Foster Homestead-Backman House	1205-44	79-A-104	
Backman House	1205-45	79-A-104	
Old Short School-Converse House	1205-46	79-A-98	
Neal Converse Farmstead <i>Old Shortt Home-</i> <i>Stead-Hersey House</i>	1205-47	79-A-120 80-A-30	
Flora George Farm	1205-48	79-A-52	
Maciejowski House	1205-49	79-A-98	
Lyman/Hsich House	1205-50	79-A-98	
Cliche House	1205-51	79-A-98	
Legare Farm	1205-52	79-A-98	
The Clough Place Pelton House	1205-53	79-A-98	
The Pekin School-Weller House	1205-54	79-A-52	
Bloom House	1205-55	79-A-104	
Slayton-Converse House	1205-56	79-A-52	
Old Lilley Farm-Tuller House	1205-57	79-A-105 79-A-106	

NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
Jacks-Woodard House	1205-58	79-A-105	
Tucker House	1205-59	79-A-120	
Thurston House	1205-60	79-A-98	
Old Peck Place-Knox House	1205-61	79-A-104 79-A-105	
Fifer's Ride-Brassage House	1205-62	79-A-104	
East Calais Historic District	1205-63	83-A-409 79-A-119	
Judge Charles Dana Place-Clark/Duke House	1205-64	79-A-120	
Batten Farm	1205-65	79-A-106	
Meiklejohn House	1205-66	79-A-106	
Ainsworth-Balentine Farm	1205-67	79-A-106 79-A-119	
Old McCarthy Place-Hayden House	1205-68	79-A-119	
Old Wilbur Place-Rolland House	1205-69	79-A-119	
Dutton House-Sunshine Cottage-Leach House	1205-70	80-A-30	
Leonard-Shedd Farm	1205-71	79-A-120	
Old Bliss Place-Pearce House	1205-72	79-A-106	
Ward House	1205-73	79-A-120	
Smithouse-Dennison/Makepeace Home	1205-74	79-A-120	
George House	1205-75	79-A-105	
Luce House	1205-76	79-A-105	
Max Gray Farm	1205-77	79-A-105	
Geisler Barn	1205-78	79-A-106	
Tonks House	1205-79	79-A-105	
Grand View Farm (Round Barn)-Grout House	1205-80	79-A-105	
Ides Homestead -Balles House	1205-81	79-A-105	
Scribner Hexagonal Silo	1205-82	79-A-105	
Bugbee Farm-Scribner House	1205-83	79-A-105	
Rockwood Farm-Hawkstead Farm	1205-84	79-A-105	
Madeline Wilkinson House	1205-85	79-A-105	
#6 School-Blachly House	1205-87	79-A-105	




BOUNDARY
 BOUNDARY
 VILLAGE
 (INCORPORATED)
 BOUNDARY
 CENTER
 WAYS

104 INSTALLATION




INSET ①
WORCESTER



INSET ②
MAPLE CORNER
27



INSET ③
NORTH CALAIS
39



INSET ④
EAST CALAIS

SCALE 0 0.1 0.2 MILE

10 300

00 50

Calais References

Hemenway, Abby Maria, Vermont Historical Gazetteer, Montpelier: Vermont Watchman and State Journal Press, 1882, Vol. IV, pp 127-173.

Hewitt, Arthur Wentworth, The Old Brick Manse, Harper & Row, New York, 1966.

Kelton, Lovel, Diaries and Journal (copy at VHS library)

Kent, Dorman B.F. History of Calais Vermont. 1875 manuscript.

Kent, Dorman B.F. History of Calais, The Vermonter; White River Junction: Charles R. Cummings, 1914, p. 163-172, 191-201.

The Vermonter, White River Junction: Charles R. Cummings, 1914 p.171.

Maps

Beer's Atlas, 1873

Walling Wall Map, 1858

Interviews

Elbridge, Toby - Adamant

Rachel Dwinell Rose

Neal Converse

Greg Belcher

Kristina Bielenberg

Elizabeth Kent Gay

Olivia Gay

Listed on State Register

VT ACHP: 2/15/89
Date: _____

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: A settlement on T.H.1 at cross roads with T.H.45 & T.H.25.
NAME OF DISTRICT: Kent's Corner - Old West Church H.D.
TYPE OF DISTRICT: Cross roads settlement
PHYSICAL CONDITION OF STRUCTURES: Excellent 90% Good 10 % Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:



STATEMENT OF SIGNIFICANCE:
Listed on the National Register of Historic Places (with the exception of the Forest Davis House, #19).
Kent's Corner is a relatively unspoiled 19th century Vermont crossroads hamlet, an example of the traditional "Vermontscape".
The tavern and mill offer educational resources for interpreting the water-powered industry and the farm lifestyles of the nineteenth century.
Numerous foundations exist from other houses and buildings connected with the many industries once located in the vicinity of the Corner. The area has maintained a large degree of historic integrity.

SURVEY NUMBER: 1205-1
NEGATIVE FILE NUMBER(S): 79-A-120, 80-A-30
UTM REFERENCES: Zone/Easting/Northing A18/700450/4916100 B18/700800/4915525 C18/699700/4914600 D18/699850/4915825
U.S.G.S. QUAD. MAP: Plainfield, Vt. Quad 15' Series 1953
COMPLEX INFORMATION ONLY
COMMON NAME:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX:
TYPES OF STRUCTURES:
PRESENT USE:
ORIGINAL USE:
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>

THREAT TO STRUCTURES: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The district extends .25 of a mile north, south, east and west along the four roads whose junction is designated Kent's Corner. The district's boundaries shall coincide with the rear property lines of all properties fronting on these roads for the prescribed distances. In addition to the above boundaries the district includes an extension of the south road, the width of the three rod right-of-way, for a distance of .6 miles to the south boundary of the property now owned by Forest and Elizabeth Davis.

REFERENCES: Lovel Kelton Diaries Journal (Copy V.H.S.) ref. building church other structures in Calais, Marshfield, E. Montpelier. Hemenway, Abby Maria. Vermont Historical Gazetteer.

RECORDED BY:
Betsy Bouton

ORGANIZATION:
Vt. Div. for Historic Preservation

DATE RECORDED:
Nov. 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX

(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: 1837	SURVEY NUMBER: 1205-1
FUNCTIONAL TYPE: Hotel		NEGATIVE FILE NUMBER: 79-A-120-#13
COMMON NAME: The Kent Tavern		OWNER: Vermont Historical Society

DESCRIPTION:
 A 5x5 bay, 2½-story brick (9 course) building (1837) with granite foundation, lintels and sills. Four interior end chimneys originally served eight fireplaces of which four remain. A wooden ell consists of the original cottage built by Abdiel Kent and a two story store building used as P.O. and general store & leather shop by Ira Kent. 12/12 sash are replacements; original old glass and sash were used in the restoration. Shaped transom lights above East and West doors appear in a number of other Calais houses of the early 1800's. Five panel doors appear to be original. A large ballroom is located on the second floor - the general store was built in 3 stages; a splayed wood lintel is above the double leaf store doors.

MAP NUMBER: 2	DATE BUILT: c.1860	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME: Kent Barn		OWNER: Vermont Historical Society

DESCRIPTION:
 A 2-story, gable roof barn with bracketed cornice and large track door on gable end. It has clapboard side walls, 6/6 window sash, sheet metal roof and recent 1979 concrete foundation.
 The barn was built for the Ira Kent house (#11).

MAP NUMBER: 3	DATE BUILT: c.1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-120#16
COMMON NAME: The White House or Kent Inn		OWNER: The Kent Inn Associates c/o Tim Hay-

DESCRIPTION: A 2½-story, 5-bay house with gable dormers built in the 1950's on both front and back slope of wood shingle roof. Windows have non-Montpelier original 12/12 sash. The shutters date from c.1875. Front door has double leaves with glass panels. The one story porch with turned posts and simple brackets was added in the 1880's. A long wooden ell is attached to the main block and a number of auxiliary buildings are on the grounds. The White House was originally built as a 2-family 1½-story cottage c.1825 for 2 families of harness makers. The front door was on the gable end. The building was raised, and the lower story added on the occasion of LeRoy and Blanche (Hollister) Kent's marriage in 1875.

MAP NUMBER: 4	DATE BUILT: 1797	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-120#17
COMMON NAME: Pioneer Cottage		OWNER: Elizabeth Kent Gay

DESCRIPTION:
 Small 1½-story cottage with porch across gable end and an attached 1 car garage/woodshed; it originally had a central chimney. Now it has a shed dormer on front roof slope and modern 6/6 sash in double and triple combination on the front facade. It stood originally on the site of the Ira Kent house (#11) and was moved to its present location when Kent built his house c.1810. The original floor plan, stairways and plank/doors remain intact.

OUTSTANDING COMPONENTS OF DISTRICT <input checked="" type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 5	DATE BUILT: c.1830	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER:	
COMMON NAME: "The Long House"	OWNER: Susan S. Manly, E. Calais RFD	
DESCRIPTION: A long, 1½-story house with a modern ell addition and modern porch. A small barn is on the property. A woodworking mill which made wooden knife handles once occupied this site. In her late years Blanche Kent owned both this house and Remember Kint's cabin, #4 and lived in them alternately.		
MAP NUMBER: 6	DATE BUILT: c.1850	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-120#19	
COMMON NAME:	OWNER: Gregory Belcher	
DESCRIPTION: A 1½-story, 3x2 bay house with modern ell containing kitchen and glassed in porch. The central eave door has 7/8 side lights and cornice head trim. Windows with 6/6 sash have peaked heads and shutters. This is an excellent example of a Classic Cottage.		
MAP NUMBER: 7	DATE BUILT: early 19th c.	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER:	
COMMON NAME: Roach Croft	OWNER: Kenneth & Margaret Smith	
DESCRIPTION: This early 19th c. structure was greatly altered in the 20th century to make it presently non-contributing to the historic character of the district.		430 W. 116 St. New York City 10027
MAP NUMBER: 8	DATE BUILT: 1855	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-120#14	
COMMON NAME:	OWNER: Stanley & Elaine Fitch	
DESCRIPTION: A "T" plan house with steep gables and corner porches. Each gable has a chimney. A one-story ell extends to the rear. The foundation is made of large granite blocks. Windows have 6/6 sash and cornice molding heads. Trim includes corner pilasters, wide eave board and eave returns. A good example of late Greek Revival architecture. Trees are an important aspect of the house site.		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 9	DATE BUILT: 1855	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Stanley & Elaine Fitch

DESCRIPTION:

A large gable roof barn with ventilator, vertical board sheathing, wooden silo and other addition.

MAP NUMBER:10	DATE BUILT: 1803	SURVEY NUMBER:
FUNCTIONAL TYPE: Mill		NEGATIVE FILE NUMBER:
COMMON NAME: The Robinson Sawmill		OWNER: The Aldrich Memorial Assoc. Inc.

DESCRIPTION:

A rectangular structure with a gable roof, of post and beam construction sheathed with wide unpainted boards. The first floor is used primarily to house the power takeoff equipment. On the north side of the building is the timber wheel house with vertical turbine. The head of water was supplied by the pond west of the mill. The stone dam was faced with concrete in 1961. The water is conducted from the dam to the turbine housing by an iron flume. The second floor is level with the stream bank and is the working floor of the mill.

MAP NUMBER: 11	DATE BUILT: 1810	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER: 79-A-120#12
COMMON NAME: Ira Kent House		OWNER: Cornelia Denker/Jeff Poister

DESCRIPTION:

A 1½-story, 5x2 bay house with 6/6 windows. A central eave side door has six panels and ½ sidelights. Two gable dormers have been built c.1975 on front slope of roof. A porch across the gable end has unique sawn plank columns.
It is interesting to note that the windows in the left front room were lowered apparently 1 foot during a mid-nineteenth century remodeling.
There is a small two-car modern garage on the property.

MAP NUMBER: 12	DATE BUILT: c.1880	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Anne David & Annette Scalzo

DESCRIPTION:

A 2 story, 4x3 bay house with ell and carriage barn with ventilator (cupola). 2/2 sash windows have cornice window heads. Gable end has modern entrance porch with gable roof, square posts and brick steps and floor. Door is double leaf with glass panels.
This house was built for Abdiel Kent's daughter, Josephine, at the time of her marriage to an Ide.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 13	DATE BUILT: c.1850	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-120#15	
COMMON NAME: Pearl Bullock House	OWNER: Louis & Laura Garcia	

DESCRIPTION: 1381 North Ave.
Burlington, VT
A 1½-story, 3x3 bay, temple front house with attached rear wing and small barn.
Corner pilasters and a cornice with deep fascia and returns frame the main block. The sidehall entrance has 2/3 sidelights and very plain cornice head. Most sash is 2/2. A shed-roofed wall dormer protrudes from the rear of the left side elevation.

MAP NUMBER: 14	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Atwater Kent Jr.	

DESCRIPTION: 150 Clark Ave.
Palm Beach, FL 33480
A small gable roofed barn in poor condition. Near this barn are foundations for the old Cheeler House. There is also a deep, beautifully constructed, stone water well.

MAP NUMBER: 15	DATE BUILT: c.1845	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling & Barns	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Christopher & Joyce Martin	

DESCRIPTION:
A Greek Revival style 1½-story house with side wing and woodshed. Corner pilasters and a cornice with deep fascia and returns frame the main block. Two-thirds side-lights flank the central door; a peaked lintel tops the door opening. Sash is 2/2 and 6/6. The wing has a wide porch with shed roof, turned rail and scroll brackets. This is a fine example of a Classic Cottage.
A 19th century gable-roofed barn with numerous appendages and vertical board sheathing lies behind the house. For many years, the property belonged to the Orr family.

MAP NUMBER: 16	DATE BUILT: 20th c.	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Judith Carbo	

DESCRIPTION:
Modern log cabin.

Non-contributing.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX

(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 17	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-120
COMMON NAME:		OWNER: Morse

DESCRIPTION: This house has a 5x2 bay, 2½-story main block and a rear 1½-story ell. The main block has peaked window and door heads and 2/2 sash. Corner pilasters, cornice and fascia frame the main block; the cornice returns on the gable ends. The ell may pre-date the main block. Its Classic Cottage form could stand alone. The central door on the ell has 2/3 sidelights and a full, but plain surround with simple cornice.

MAP NUMBER: 18	DATE BUILT: 1823	SURVEY NUMBER:
FUNCTIONAL TYPE: Meetinghouse		NEGATIVE FILE NUMBER: 79-A-120
COMMON NAME: Old West Church		OWNER:

DESCRIPTION:
The large 2½-story, frame meetinghouse has three entrance doors on the front gable end which are joined by a continuous entablature at their heads. Pilasters frame each individual entry. Corner boards and a simple cornice with returns frame the structure. Sash is 12/12, with many panes being original. The 3-stage steeple is composed of a square base w/ louvered lights, an octagonal second stage, and an octagonal upper stage with oval openings on each face and a multi-sided hip roof cap. A wooden finial atop the steeple supports a weathervane. The interior of the church retains its original box pews. It is heated by woodstoves. Above the raised pulpit, the following words appear on the wall, in letters composed of dried hemlock boughs: "Removeth not the ancient landmark which thy fathers have set". (Originally put up in the 1880's, the decoration was refurbished in the 1930's.)

MAP NUMBER: 18 cont.	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:
This meetinghouse, although of vernacular design, remains one of the finest in the state because of its near original condition. Its setting, on a dirt road with cemetery behind, evokes a very strong sense of the past.

MAP NUMBER: 19	DATE BUILT: early 19th c.	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 80-A-30
COMMON NAME: Forest Davis House		OWNER: Forest Davis

DESCRIPTION:
This 5x3 bay, 2½-story vernacular Greek Revival frame house has nearly full-length sidelights flanking the central door. Above the door a full entablature spans the opening. There are 2 interior chimneys. Sash is 6/6.
At one time this house served as the Town Poor Farm. It may have been constructed around the same time as the Church (1823).

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



1205-1
#3

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Kent Inn, 1205-1, #3
79-A-120 Betsy Bouton



1205-1
#1

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Kent Tavern, 1205-1, #1
79-A-120 Betsy Bouton



1205-1
#5

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
"Long House"/Manly House, 1205-1, #5
79-A-120 Betsy Bouton



1205-1
#4

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6.79
Kent's Corner/Old West Church HD:
Kent Pioneer Cabin, 1205-1, #4
79-A-120 Betsy Bouton



1205-1
#6

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Belcher House, 1205-1, #6
79-A-120 Betsy Bouton



1205-1
#8

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Fitch Farm, 1205-1, #8
79-A-120 Betsy Bouton



1205-1
#13

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Bullick-Garcia House, 1205-1, #13
79-A-120 Betsy Bouton



1205-1
#11

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Ira Kent/Bird House, 1205-1, #11
79-A-120 Betsy Bouton



1205-1
#15

80-A-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
Chris Martin Barns 1205-1 #15 W
80-A-30 Betsy Bouton



1205-1
#15

80-7-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
Chris Martin House 1205-1#15 W
80-A-30 Betsy Bouton



1205-1
#19

80-A-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
Forest Davis House 2501-1 #19 W
80-A-30 Betsy Bouton



1205-1
#18

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Kent's Corner/Old West Church HD:
Old West Church, 1205-1, #18
79-A-120 Betsy Bouton

Listed on State Register

VT ACHP

Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-2

NEGATIVE FILE NUMBER:

79-A-105(21)

UTM REFERENCES:

Zone/Easting/Northing

18/699650/4914050

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

Moser House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: "

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular

DATE BUILT:
c.1835

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.45, 1 miles
south of Kents Corner

COMMON NAME:

Old Bailey House

FUNCTIONAL TYPE: Dwelling

OWNER: N. Jeffrey & Donna Moser

ADDRESS: Adamant, Vermont

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block

c. Iron d. Steel e. Other: on wing

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: 9-course American Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other: main block wing

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2

Entrance Location: Center front

Approximate Dimensions: 30x37

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Two gable dormers have been added recently to the front slope of the roof. 12/12 sash replacement windows have wooden sills. The front door has eight panels, transom light and a granite sill. The door has a large box lock. Doors originally had latches.

Interior woodwork is molded with peaked cornices. Wallpaper used in this house is part of the Vermont Historical Society collection.

The four bay porch on the wing has slotted posts with ornate brackets that are also slotted. Wing and porch appear to date from c.1860. The house is a transitional Cape-Classic Cottage type.

RELATED STRUCTURES: (Describe)

Barn is now owned by Walter Balentine.

STATEMENT OF SIGNIFICANCE:


Moses Stone settled near this site in 1787. It later became one of the farms cleared by the Bliss family.

The house is a very good example of a vernacular late Cape or early Classic Cottage. It combines elements of each; the shallow roof slope and lack of a kneewall are typical Cape features, while the two interior chimneys (if original) indicate the plan of a Classic Cottage. The wood posts of the wing porch are fine examples of decorative detailing from the third quarter of the 19th century. The house is one of only a few small brick farmhouses in Calais.

REFERENCES:

Owner.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-2

79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Baily-Moser House, 1205-2
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.45, 1 mile south of Kents Corner
COMMON NAME:	Balentine Barn
FUNCTIONAL TYPE:	Barn
OWNER:	Walter & Carolyn Balentine
ADDRESS:	Adamant, Vt.
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other: Ramped entry

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5 bay (side) Entrance Location: Gable end

Approximate Dimensions: 55' long

SURVEY NUMBER:

1205-3

NEGATIVE FILE NUMBER:

79-A-106#1

UTM REFERENCES:

Zone/Easting/Northing

18/699700 /4914050

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Balentine Barn

ORIGINAL FORMAL NAME:

PRESENT USE: Barn

ORIGINAL USE: Barn

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1880

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A large gable roof structure with widely overhanging bracketed eaves (no returns). The barn has a gable roof ramped entry (also with board and batten siding), and a small adjoining milkhouse. The center of the ridge supports a rectangular cupola with a louvered opening on each side and a low, hipped roof.

RELATED STRUCTURES: (Describe)

1½-story brick house is now under separate ownership. See 1205-2

STATEMENT OF SIGNIFICANCE:


Barns are vanishing as the importance of farming has declined in central Vermont. This example represents the type built in the late 19th century. It is particularly attractive and in well-preserved condition.

REFERENCES:

MAP: (Indicate North in Circle)




1 MILE TO
KENTS' CORNER ↑



1205-2

TOWN HIGHWAY 45

BALENTINE BARN
1205-3



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Balentine Farm barn, 1205-3
79-A-106 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	North side of T.H.46 between T.H.45 & T.H.47 intersections
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Richard & Barbara Lynch
ADDRESS:	Adamant, Vermont
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x3 Entrance Location: Left front

Approximate Dimensions: 23x33

SURVEY NUMBER:

1205-4
NEGATIVE FILE NUMBER: 79-A-52
UTM REFERENCES: Zone/Easting/Northing 18/699500/4913800
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
PRESENT FORMAL NAME: Lynch House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Aaron Tucker?
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular Greek Revival
DATE BUILT: c.1850

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:
 The exterior has wide corner pilasters and eave returns. The front door has 5/6 sidelights, molded pilasters and pedimented head. The windows have peaked surrounds matching the woodwork trim of the carriage barn.

This house is constructed with double back plaster. Three panel doors have glass knobs. Windows have full length panelled aprons. A modern apartment is attached to the rear of the wing.

RELATED STRUCTURES: (Describe)

The carriage barn was built at the same time and with the same stylistic details as the dwelling.


STATEMENT OF SIGNIFICANCE:

This house is one of a small number of gable-front, sidehall plan houses in Calais. This one and the one owned by George Morse (1205-23) and possibly several others were built by Aaron Tucker. False mantles and plaster ceiling medallions in the parlors are common to both houses in addition to the basic plan.

The gable-front orientation of the plan and the classically derived details (e.g., cornice with returns) are the hallmark of the Greek Revival style in Vermont. In Calais, however, the Classic Cottage (5 bays across) seems to have been the preferred house type up to the end of the third quarter of the nineteenth century.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Brook (location on sawmill)

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-4

79-4-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Lynch House, barn, 1205-4 SW
79-A-52 Betsy Bouton



1205-4

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Lynch House, 1205-4 NW
79-A-52 Betsy Bouton

Listed on State Register

VT ACHP

Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Southeast corner of intersection of T.H.47 and T.H.46. East of Bliss Pond.
COMMON NAME:	The Mill House
FUNCTIONAL TYPE:	School
OWNER:	Richard & Barbara Lynch
ADDRESS:	Adamant
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input checked="" type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x2 Entrance Location: rear & side

Approximate Dimensions: 29x26

SURVEY NUMBER:

1205-5

NEGATIVE FILE NUMBER:

79-A-52

UTM REFERENCES:

Zone/Easting/Northing

18/699500/4913800

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Lynch House

ORIGINAL FORMAL NAME:

District 1 School

PRESENT USE: Residence

ORIGINAL USE: School

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1850

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has a mixture of window sash (2/2 and 12/8), cornice with fascia which returns on the gable ends, wide corner boards and a screened porch.

RELATED STRUCTURES: (Describe)

A shed east of the residence.


STATEMENT OF SIGNIFICANCE:

This former school and Miller's house was moved after 1873 from a location about 1/2 mile east on T.H.46. The school district was numbered #1 in 1826. Thadeus Stevens taught in the school. After the structure was moved, it housed the Miller who operated the saw mill on the outlet from Bliss Pond. This was located across the street from the Lynch House (1205-20). The building, although greatly altered, retains local historic significance for its association with the old mill.

REFERENCES:

Owner - Mrs. Lynch
Hemenway.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land
- Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential
- Commercial
- Agricultural
- Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-5

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
District 1 School/Mill House N
79-A-52 Betsy Bouton
1205-5

Listed on State Register
VT ACHP
Date: 12/15/1983

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.46, 1/6 mile south of T.H.45
COMMON NAME:	Old Sparrow Place
FUNCTIONAL TYPE:	Dwelling
OWNER:	Natalie Sloan
ADDRESS:	Adamant, Vt.
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x3 Entrance Location: Center front

Approximate Dimensions: 24x36 & ell

SURVEY NUMBER:

1205-7

NEGATIVE FILE NUMBER:

79-A-52 (14&15)

UTM REFERENCES:

Zone/Easting/Northing

18/699750/4913600

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Sloan House

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: "

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1840

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has wide corner boards, boxed cornice and returns. Windows have 6/6 sash. The front door with seven panels has 5/6 sidelights, plain geometric surround with corner blocks, granite sill and three granite steps. The wing has a recessed porch.

A modern stone terrace and pond are part of the contemporary landscape plan. Unusual wooden fence with granite posts.

RELATED STRUCTURES: (Describe)

Modern garage.

STATEMENT OF SIGNIFICANCE:

This is a good example of a Classic Cottage farmhouse with Greek Revival style details. The front door panelled surround with corner blocks is a key architectural and decorative feature in the design.

The house was formerly owned and restored by Vermont Life editor, Walter Hard, Jr.

REFERENCES:

MAP: (Indicate North in Circle)



← 1/6 MILE TO T.H. 45

TOWN HIGHWAY 46

1205-7

STONE WALL



GARAGE

WOODEN FENCE WITH
GRANITE POSTS

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

Pond

RECORDED BY:
Betsy Bouton

ORGANIZATION:
Vt. Div. for Historic Preservation

DATE RECORDED:
May 1979



1205-7

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Sloan House, detail, 1205-7 W
79-A-52 Betsy Bouton



1205-7

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Sloan House, 1205-7 W
79-A-52 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.46, 1/2 mile north of intersection with T.H.48.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Kenneth & Doris Fowler
ADDRESS:	Adamant
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3x5 (plus ell) Entrance Location: center front end

Approximate Dimensions: 25x38 (w/o ell)

SURVEY NUMBER:

1205-8
NEGATIVE FILE NUMBER: 79-A-52
UTM REFERENCES: Zone/Easting/Northing 18/699900/4913500
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Fowler House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Possibly Lovel Kelton
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c.1830

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The front door has massive granite steps, hand wrought iron foot scapers, 8 panel door, pilasters and 2/3 sidelights. Batten kitchen door has hand forged latch. Its pilasters and entablature appear to date from sometime after c.1850. Interior detail includes original wainscoting and doors. Center chimney stack remains in cellar but has been redesigned above.

Nineteenth century paint and trim (ochre with red trim) may have survived. Ell may be later than the main block of the house.

RELATED STRUCTURES: (Describe)


Chicken House
 Small 30x40 barn
 1 car garage across road

STATEMENT OF SIGNIFICANCE:

This house has been changed very little in recent years. It is a good example of the typical Vermont late Cape farmhouse.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-8

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Fowler House, 1205-8 N
79-A-52 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: West side of T.H.46 near intersection with T.H.48 and T.H.49
 COMMON NAME: Scott House
 FUNCTIONAL TYPE: Dwelling
 OWNER: Andrew & Jessie Scott
 ADDRESS: Adamant
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

SURVEY NUMBER: 1205-9
 NEGATIVE FILE NUMBER: 79-A-52
 UTM REFERENCES:
 Zone/Easting/Northing
18/700350/4912800
 U.S.G.S. QUAD. MAP:
Plainfield Quad., 15' Series
 PRESENT FORMAL NAME:
Scott House
 ORIGINAL FORMAL NAME:
Bliss Tavern
 PRESENT USE: Residence
 ORIGINAL USE: Tavern
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Vernacular
 DATE BUILT:
c.1800

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon Plank
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Modern--Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 5x3 Entrance Location: center front
 Approximate Dimensions: 25x30

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Cape type
 This house originally had a central chimney with three fireplaces. Current replacement chimney is of concrete block. The doors are made from planks.
 Broad metal roof
 Wide fascia board
 Cornice without returns
 Entrance -- Wide board trim
 No sidelight or transom
 Sash with plain trim

RELATED STRUCTURES: (Describe)


2-car garage across the road.

STATEMENT OF SIGNIFICANCE:

This plank house built on the first county road in Calais was used as a tavern by A. Bliss. The sign for the tavern dated 1823 pictures an eagle with seven arrows and "E Pluribus Unum". The sign was used by Louise Andrews Kent as a model for a sign used at the Kent Museum. The original is now in the Scott's kitchen. This house is one of the oldest in Calais and is a well-preserved and representative example of yeoman housing at the opening of the nineteenth century.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-9

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Bliss Tavern/Scott House, 1205-9 W
79-A-52 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	.18 mile easterly of T.H.46 & T.H.48 intersection on T.H.49.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

SURVEY NUMBER: 1205-10
NEGATIVE FILE NUMBER(S): 79-A-52, 106
UTM REFERENCES: Zone/Easting/Northing A18/699550/4912950 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Leonard-Graham Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: Agricultural
PRESENT USE: Dwelling
ORIGINAL USE: Agricultural
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>



STATEMENT OF SIGNIFICANCE:

This farm complex is on the site of one of the earliest farms in Calais. The house built c.1850 replaced an earlier log dwelling. The farm continued in production until the retirement of Harry Graham in the mid 1970's and retain buildings used in a variety of agricultural enterprises. The 1870's barn has been converted for dairy use. The house is a good example of the typical Greek Revival style farmhouse, and it has been well preserved.

THREAT TO STRUCTURES:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Annie Leonard and Harry & Muriel Graham as per the deeds recorded in office of the town clerk.

REFERENCES:

The Owner's Harry & Muriel Graham

RECORDED BY: Betsy Bouton	ORGANIZATION: Vt. Div. for Historic Preservation	DATE RECORDED: May 1979
------------------------------	-----------------------------------------------------	----------------------------

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: c.1850	SURVEY NUMBER: 1205-10
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-52
COMMON NAME:		OWNER: Annie Leonard, Harry & Muriel Graham

DESCRIPTION:

(Greek Revival Classic Cottage)
A 1½-story, 5x2 bay frame and clapboard house with a kneewall, panelled corner pilasters and a steeply-pitched widely overhanging roofline. Cornice returns.
Entrance -- Pilasters and entablature
Wide doorway with full-length sidelights
Wing -- 4 bays
Porch (2 bays) with slotted posts
Shed dormer
Shed attached to wing, with sliding/track door
Stone slab foundations 6/6 sash

MAP NUMBER: 2	DATE BUILT: ?	SURVEY NUMBER: 1205-10
FUNCTIONAL TYPE: Shed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

This shed is made of two components each with gable roofs which are joined at right angles at the corners.

MAP NUMBER: 3	DATE BUILT: c.1870	SURVEY NUMBER: 1205-10
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

This two story barn approximately 30x60 with gable roof came from Lanesborough in Marshfield. (This, once busy, lumber mill village retains only a few camps now.) The pieces were precut and put together on the site with square nails. The larger timbers were hand hewn and the planks cut with an up and down saw. The board and batten sheathing was originally painted buff. The barn's second floor is entered through an enclosed, ramped vestibule.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:



1205-10
#3

79-17-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Leonard/Graham Barn, 1205-10
79-A-106 Betsy Bouton



1205-10

#1

79-#52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Leonard/Graham Farm, 1205-10 W
79-A-52 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: On T.H.48, 1/2 mile north of T.H.46.
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent 100% Good % Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>
THEMES:

SURVEY NUMBER: 1205-11
NEGATIVE FILE NUMBER(S): 79-A-51
UTM REFERENCES: Zone/Easting/Northing A 18/700600/4914000 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Liff Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: Dwelling & barn
PRESENT USE: Dwelling & farm
ORIGINAL USE: Same
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>



STATEMENT OF SIGNIFICANCE:

This Greek Revival style house and unpainted, gable-roof barn are typical of the buildings of family farms in 19th century Vermont. They are important to the "Vermontscape" and are rich in historical associations.

THREAT TO STRUCTURES: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Sidney and Margaret Liff as per the deeds recorded in office at the town clerks.

REFERENCES:

Sidney Liff

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: c.1840	SURVEY NUMBER: 1205-II
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-51
COMMON NAME: Liff's House		OWNER: Sidney & Margaret Liff, Adamant

DESCRIPTION: A Classic Cottage, approximately 40x24 with Greek Revival cornice and frontispiece. There is a long 60' wing containing three open bays and a recessed porch. Originally, the house had 1/2 chimneys. It now has a modern fireplace chimney on the north end. Interior has five panel doors, some early hardware, wainscoting and chair rails on the interior. Windows have 6/6 sash. The house's other Greek Revival characteristics: 2/3 door sidelights, plain entablature with cornice returns, surrounds of molded trim with corner blocks, entablature with cornice returns, and wide corner boards.

MAP NUMBER: 2	DATE BUILT: c.1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 79-A-51
COMMON NAME: Liff Barn		OWNER: Sidney & Margaret Liff

DESCRIPTION:
 This large 50x60 3-story barn was one of a number of similar structures built in Calais after the Civil War. It is of post and beam construction with board and batten siding with a gable roof - the second floor housed cows and was reached by a ramped, covered vestibule. Manure was shoveled down to the first floor and was used by pigs. This multipurpose barn also housed poultry. A lean to addition has been added to the south side. Barn has unpainted vertical sheathing.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



1205-11
#2

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Liff Farm, 1205-11
79-A-51 Betsy Bouton



1205-11
#1

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Liff Farm, 1205-11
79-A-51 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1988

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Adamant Village S.W. of T.H.#6
COMMON NAME:	Adamant Methodist Church
FUNCTIONAL TYPE:	Church
OWNER:	Adamant Methodist Church
ADDRESS:	Adamant, Vt.
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input checked="" type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input checked="" type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 - Bonding Pattern: Other:
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:
- Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 4x3

Approximate Dimensions: 26x33

SURVEY NUMBER:

1205-12

NEGATIVE FILE NUMBER:

79-A-51

UTM REFERENCES:

Zone/Easting/Northing

18/698900/4911380

U.S.G.S. QUAD. MAP:

Montpelier Quad., 7.5' Series

PRESENT FORMAL NAME:

Adamant Church

ORIGINAL FORMAL NAME:

PRESENT USE: Church

ORIGINAL USE: Store

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Neo-Gothic Revival

DATE BUILT:

Prior to 1898

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This former store is composed of five closely joined sections: a 1 1/2-story main mass, a 2-story extension, a 2-bay shed addition on west, a shed roofed entrance to raised basement and a square side bell tower with crenellations and square corner spires. Both open entrance porches have been enclosed.

RELATED STRUCTURES: (Describe)

None

STATEMENT OF SIGNIFICANCE:

This church was founded by Dr. Arthur W. Hewitt May 24, 1908. The Methodist Church, Community Club building (1205-13), and Morreale House (1205-14) are the only surviving nineteenth century structures from a once important and thriving community. The bell tower, with its crenellations and pinnacles is the building's most noteworthy feature.


Adamant granite quarries were opened in the 1880's. At one time there were six quarries in the area.

Adamant was first named S. Calais and then Sodom before being renamed Adamant in 1905. This small community spawned progressive leadership. Washington Electric Coop., Adamant Coop. and the first state chartered Credit Union in Vermont were started by Adamant men.

REFERENCES:

Calais Historical Society Meeting reported that this structure was once a store, Eldridge Toby, Hewitt, The Old Brick Manse

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-12

79-751

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Adamant Methodist Church, 1205-12
79-A-51 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Adamant Village west of T.H. 53.
COMMON NAME:	Adamant Community Club
FUNCTIONAL TYPE:	School
OWNER:	Adamant Community Club
ADDRESS:	Adamant, Vt.
ACCESSIBILITY TO PUBLIC:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER:	1205-13
NEGATIVE FILE NUMBER:	79-A-105
UTM REFERENCES:	Zone/Easting/Northing 18/698780/4911480
U.S.G.S. QUAD. MAP:	Montpelier Quad., 7.5' Series
PRESENT FORMAL NAME:	Adamant Community Club, Inc.
ORIGINAL FORMAL NAME:	
PRESENT USE:	Community Center
ORIGINAL USE:	School
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Greek Revival Vernacular
DATE BUILT:	1895

GENERAL DESCRIPTION: Structural System poor condition

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1

Number of Bays: 2x4 Entrance Location: Paired, gable front

Approximate Dimensions: 26x33

THREAT TO STRUCTURE:	No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:
----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
------------------	----------------------------------------------------------------------------------------------------------------------

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Windows have 2/2 sash and peaked cornice moldings. A narrow platform with hip-roof extends across the gable front. The struts for the porch roof are chamfered. A flag pole extends from the center of the porch roof to the tip of the gable above. A small rectangular belfry and slender chimney with a corbelled cap straddle the ridge of the roof.

RELATED STRUCTURES: (Describe)

None


STATEMENT OF SIGNIFICANCE:

This is a representative one room rural school house, dating from the era when Adamant was a growing and prosperous community. The triangular gable panel, paired entrances diminutive belfry and corbelled chimney (late Victorian) are the building's distinctive features.

REFERENCES:

Elbridge Tobey

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979



1205-13

79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Adamant Community Club, 1205-13
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/18/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Adamant Village, .3 miles W. on T.H.53 from intersection T.H.56 & T.H.57.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Ben & Anita Morreale
ADDRESS:	Adamant, VT
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Stretcher Bond Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: central eave

Approximate Dimensions: 35x28 plus ell

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

SURVEY NUMBER:

1205-14

NEGATIVE FILE NUMBER:

79-A-51

UTM REFERENCES:

Zone/Easting/Northing

18/698680/4911460

U.S.G.S. QUAD. MAP:

Montpelier Quad., 7.5' Series

PRESENT FORMAL NAME:

Morreale House

ORIGINAL FORMAL NAME:

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1837

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This brick house with long clapboard wing containing a three bay porch and 3 bay garage has been extensively altered on the interior as well as the exterior. The exterior has granite lintels and a rough dressed granite foundation. The central door with moderate recess has 2/3 sidelights on panelled pedestals and a 7-light transom light across its entire length. There are two large gabled dormers on the front facade with paired windows and cornice returns. (Probably dating from end of 19th century). At the time of the survey, a large shed dormer was being installed on the rear slope of the roof exposing roof boards with up and down saw marks.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:


This brick house is one of a small number built in Calais in the first half of the 19th century. The bricks, according to Ralph Weeks, came from the same brick yard as those for A. Kents Hotel, (#1) on the road to Gospel Hollow.

Stylistically, the building is of interest as an example of the early Greek Revival. The bold, rectangular lintels, and the frontispiece reflect this while the floor plan and massing are more traditional.

REFERENCES:

Ralph Weeks, contractor

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land
- Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential
- Commercial
- Agricultural
- Industrial
- Roadside Strip Development
- Other: Pond

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979



1205-14

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Morreale House, 1205-14
79-A-51 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER: 1205-15
NEGATIVE FILE NUMBER: 79-A-51
UTM REFERENCES: Zone/Easting/Northing 18/697570/4911220
U.S.G.S. QUAD. MAP: Montpelier Quad., 7.5' Series
PRESENT FORMAL NAME: LaFountain House
ORIGINAL FORMAL NAME:
PRESENT USE: Dwelling
ORIGINAL USE: "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input checked="" type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c.1850

COUNTY: Washington
TOWN: Calais
LOCATION: North side of T.H.53 about 1/2 mile east of the County Rd. (T.H.1)
COMMON NAME:
FUNCTIONAL TYPE: Dwelling
OWNER: Robert & Barbara LaFountain ADDRESS: County Road, Calais
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon Plank construction
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2 plus wing Entrance Location: center, eaves side

Approximate Dimensions: 36x23 plus wing

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Large shed dormers (20th c.) are key features of the front facades of both the house and wing. The plain frontispiece has 2/3 sidelights without a transom. There is a wide porch in the wing. It is incorporated into the wing and does not stand as a separate structure. Present downstairs windows have 2/2 sash.

- Kneewall construction
- Wide fascia board
- Cornerboards
- Cornice returns
- Classic Cottage type

RELATED STRUCTURES: (Describe)

A small structure on the property, now used for storage and in very poor condition is a former blacksmith shop. The original portico approx. 12x15 has hand hewn timbers and may have been an early dwelling.


STATEMENT OF SIGNIFICANCE:

A representative example of the Classic Cottage house type during the second quarter of the nineteenth century.

REFERENCES:

Owner - Barbara LaFountain

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979



1205-15

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
LaFountain Place, 1205-15
79-A-51 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1988

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	County Road opposite Bliss Pond Rd.
COMMON NAME:	Cold Spring Farm
FUNCTIONAL TYPE:	Dwelling
OWNER:	George & Marjorie Morse
ADDRESS:	Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER:	1205-16
NEGATIVE FILE NUMBER:	79-A-52
UTM REFERENCES:	Zone/Easting/Northing 18/698340/4913845
U.S.G.S. QUAD. MAP:	Montpelier Quad., 7.5' Series
PRESENT FORMAL NAME:	Morse House
ORIGINAL FORMAL NAME:	Aaron Tucker House
PRESENT USE:	Residence
ORIGINAL USE:	Residence
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	Aaron Tucker
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular Greek Revival
DATE BUILT:	c.1851

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x3 Entrance Location: Front, corner, gable end

Approximate Dimensions: 21x30 plus e11

THREAT TO STRUCTURE:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house with a side hall plan has full-length windows in the parlor with 6/9 sash and peaked surrounds. The entrance door with full sidelights without a transom. The panels are shaped in Gothic arches. The house interior shows few recent alterations. The kitchen has match stick siding, reflecting the fashion at the turn-of-the-century. The shed dormers probably also reflect changes made at the turn-of-the-century. Corner pilasters support a full entablature (eaves sides). Cornice returns. Corbelled interior on-ridge chimney.

RELATED STRUCTURES: (Describe)

Attached carriage barn has tack room, grooming room, box stall, 2 straight stalls, pig pen and chicken house.


STATEMENT OF SIGNIFICANCE:

This house is one of a number built in Calais by Aaron Tucker c.1850. He was the first to live in this house and it remains in his family. Others he built are #20 (Lynch) and possibly those owned by Darby Bradley in Maple Corners and Louis Garcia in Kent's Corner (1205-1, map #13). These gable-front houses have many similarities. The parlors of this and the Lynch house have ornamental woodwork which includes false mantels. Plaster medallions adorn the ceilings. Stylistically, the Morse House shows a typical solution in Vermont to the design of a Greek Revival house. The full-length windows are an unusual feature, however, giving the house what would have been a fashionable elegance at the time the house was built.

REFERENCES:

Owners.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 8, 1979



1205-16

79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Tucker/Cold Spring Farm/Morse House
1205-16 W
79-A-52 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 10/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: West side of the County Road 1/4 mile north of Bliss Pond Rd. intersec- tion.
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent % Good 90% Fair 10% Poor %
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:

SURVEY NUMBER: 1205-17
NEGATIVE FILE NUMBER(S): 79-A-97 (1-4)
UTM REFERENCES: Zone/Easting/Northing A18/698320/4913925 B C D
U.S.G.S. QUAD. MAP: Montpelier Quad.. 7.5' Series COMPLEX INFORMATION ONLY
COMMON NAME: Morse Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME: Aaron Tucker Farm
TYPE OF COMPLEX: Agricultural
TYPES OF STRUCTURES: Dwelling & farm
PRESENT USE: Farm
ORIGINAL USE: "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Aaron Tucker
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

STATEMENT OF SIGNIFICANCE:



This farm complex with it's 1 1/2-story brick house was for most of its history owned by the same family as well as the adjoining property (#23). Both dwellings were built by Aaron Tucker and they served the same farm operation. Family members traded living quarters back and forth as the needs of different generations shifted. Although the house has a number of additions on its exterior dating from the turn-of-the-century (e.g., porch) it is one of the earliest (1825) brick houses remaining in Calais.

The extensive barns are still in use. Aaron Tucker was married to Rachel Bliss Kent, the daughter of Remember I and Rachel (Bliss) Kent.

THREAT TO STRUCTURES:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Stanley and Janice Morse as per the deeds recorded in the office of the town clerk.

REFERENCES:

George Morse, Hemenway

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input checked="" type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: 1825	SURVEY NUMBER: 1205-17
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-97#1	
COMMON NAME:	OWNER: Stanley & Janice Morse	
DESCRIPTION:		
<p>This 9-course brick, 1½-story, 5x2 bay house has a stone foundation and interior-end chimney on the front slope of the roof. Without its additions, the house is approximately 27x38. The front entrance with 4-pane transom light has been nearly obscured by a late Victorian porch with turned posts and molded rail which extends across the front of the building. A four window shed dormer has been added to the front slope of the roof and a wooden entry has been enclosed on the north. Sheds now form a continuous connection between the large complex of barns and the house.</p>		
MAP NUMBER: 2	DATE BUILT: early 20th	SURVEY NUMBER: 1205-17
FUNCTIONAL TYPE: Agricultural buildings	NEGATIVE FILE NUMBER: 79-A-97#2	
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>A three-story barn with a ramped vestibule entrance on the North end has a number of appendages which include sheds, calf barn and milkhouse.</p>		
MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER: 1205-17
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>3-bay tractor shed; shed roof, asphalt siding; deteriorated.</p>		
MAP NUMBER: 4	DATE BUILT: Prior 1873	SURVEY NUMBER: 1205-17
FUNCTIONAL TYPE: Shop	NEGATIVE FILE NUMBER: 79-A-97#4	
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>A small 2-story shop with gable roof and loft hoist door above a wide ground floor door.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 5&6	DATE BUILT:	SURVEY NUMBER: 1205-17
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER: 79-A-97
COMMON NAME:		OWNER: Stanley & Janice Morse

DESCRIPTION:

Two small buildings possibly a spring house and a stone culvert(?) between the two properties.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:



79-A-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Tucker/Morse Farm, barn, 1205-17
79-A-97 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: Town Highway #43
COMMON NAME: Old Brude Place
FUNCTIONAL TYPE: Dwelling
OWNER: Darby and Lisa Bradley
ADDRESS: Calais, Vt.
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
a. Wood Frame: Post & Beam Balloon
b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
a. Truss: Wood Iron Steel Concrete
b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:
Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:
Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:
Number of Stories: 1½
Number of Bays: 3x5
Approximate Dimensions: 28x28

SURVEY NUMBER: 1205-18
NEGATIVE FILE NUMBER: 79-A-51
UTM REFERENCES: Zone/Easting/Northing
18/697260/4914550
U.S.G.S. QUAD. MAP: Montpelier Quad. 7.5' Series
PRESENT FORMAL NAME: Bradley House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor
STYLE: Vernacular
DATE BUILT: c.1820

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

Entrance Location: Two: Front Center & Gable end

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has 2/2 window sash; a stone porch floor and a shed dormer across the back slope of the roof. The roof has a boxed cornice and widely overhanging eaves that return. Wide cornerboards.

The original central chimney of this house has been removed.

RELATED STRUCTURES: (Describe)


Modern 2-bay garage.
Small sheep barn.

STATEMENT OF SIGNIFICANCE:

This house had endured much neglect before it was reworked in the 1970's. The floor plan, slope of the roof and its low posting and the remains of a central chimney suggest that it is a Cape Cod style house from the first period of Calais settlement. The builder was probably Hersey, the name given to the hill on which it stands.

REFERENCES: A photograph shows this house with large addition that was used as a dance hall and later moved to Worcester. Maureen Russell.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979



1205-18

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Old Bruce/Russell House, 1205-18
79-A-51 Betsy Bouton

LISTED ON State Register
VT XCHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.42, about 1 mile NW of intersection with T.H.1 (County Road)
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Peter & Linda Laqueur
ADDRESS:	278 Old Sib Road Ridgefield, CT 06877
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System field stone

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 plus

Approximate Dimensions: 28x33

Entrance Location: Front, central

SURVEY NUMBER:

1205-19

NEGATIVE FILE NUMBER:

79-A-51#17

UTM REFERENCES:

Zone/Easting/Northing

18/697680/4914650

U.S.G.S. QUAD. MAP:

Montpelier Quad., 7.5' Series

PRESENT FORMAL NAME:

Laqueur House

ORIGINAL FORMAL NAME:

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1850

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The Greek Revival style characteristics of this ^{Classic Cottage} are the wide corner-boards, boxed eaves and returns and the central door with 2 / 3 sidelights, paneled pilasters and shaped corner blocks forming the surround. Windows have peaked or modified pediment heads. 6/1 sash in windows, fireplace and modern shed-roofed entrance porch have been added. The offset wing has a wide carriage shed entrance.

RELATED STRUCTURES: (Describe)


Small gable roof barn.
2-car garage.

STATEMENT OF SIGNIFICANCE:

This house is typical of the Greek Revival style which was a pervasive building type in Vermont in the mid 19th century. Its very wide carriage bay entrance in the wing (now infilled with vertical board sheathing) is quite unusual.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:
Betsy Bouton

ORGANIZATION:
Vt. Div. for Historic Preservation

DATE RECORDED:
April 1979



1205-19

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Laqueur House, 1205-19
79-A-51 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.42 (Cherington Rd.) 1/2 south of T.H.2.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent 100% Good % Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input type="checkbox"/> National <input checked="" type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:



This farm complex has a site in open fields on a height of land overlooking most of the town of Calais. The brick house was built by Levi Robinson in 1837 and is one of the few remaining brick structures in the town which date from the first half of the 19th century. Its construction, molded cornice, and attractive frontispiece make it an good example of its type.

THREAT TO STRUCTURES:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

SURVEY NUMBER: 1205-20
NEGATIVE FILE NUMBER(S): 79-A-51
UTM REFERENCES: Zone/Easting/Northing A 18/698600/4916040 B C D
U.S.G.S. QUAD. MAP: Montpelier Quad. 7.5' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Cherington Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME: Levi Robinson House
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: Dwelling, Barns
PRESENT USE:
ORIGINAL USE:
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Mary Cherington as per the deeds recorded in office at the town clerks.

REFERENCES: Mrs. Mildred Morse, E. Montpelier has orig. pencil drawing of farmhouse and extensions prior to 1900? Drawn by Robinson girl.
The owner, Mary Cherington

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: 1837	SURVEY NUMBER: 1205-20
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-51	
COMMON NAME:	OWNER: Mary Cherington	

DESCRIPTION: This 1½-story, 5x2 bay Greek Revival Classic Cottage with four interior-end chimneys and granite foundation and lintels has been sympathetically restored. There are two small gable dormers on the front facade. Wood shingle roof. Windows have 12/12 sash. Front entrance has sidelights. Originally there was a brick oven in the ell which preceeded the construction of the main mass.

Two recessed clapboarded wings extend from the NE end of the main block. The one closest the house has an infilled carriage bay opening. Wallpaper from the parlor of this home was reproduced by Strahan and used in the apt. of the Kent Museum (1205-1). It closely resembles P.30 in Wallpapers in Historic Preservation by C.L. Frangiamore.

MAP NUMBER: 2	DATE BUILT: ?	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 80-A-30	
COMMON NAME:	OWNER: Mary Cherington	

DESCRIPTION:

A large two-story barn plus hay loft. The gable roof has a ventilator and weather vane. Two small buildings form an ell shaped plan with the main barn.

MAP NUMBER: 3	DATE BUILT: 1920	SURVEY NUMBER:
FUNCTIONAL TYPE: Garage	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

Gable roof garage.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



1205-20

79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Robinson/Cherington Place, 1205-20
79-A-51 Besty Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: East side of T.H.42, just south
 of intersection with T.H.2.
 COMMON NAME:
 Old Van Ornam House
 FUNCTIONAL TYPE: Dwelling
 OWNER: Eleanor Ott
 ADDRESS: Calais, Vt.
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

SURVEY NUMBER:
 1205-21
 NEGATIVE FILE NUMBER:
 79-A-97(18)
 UTM REFERENCES:
 Zone/Easting/Northing
 18/698860/4916650
 U.S.G.S. QUAD. MAP:
 Mount Worcester Quad. 7.5' Series
 PRESENT FORMAL NAME:
 Ott House
 ORIGINAL FORMAL NAME:
 PRESENT USE: Residence
 ORIGINAL USE: Residence
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Vernacular
 DATE BUILT:
 c.1820

GENERAL DESCRIPTION:
 Structural System & concrete
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other: enclosed entrance
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 4x3 Entrance Location: Front, off-center
 Approximate Dimensions: 30x24

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This 3/4 house has a roof with little eaves overhang and shallow slope, 2/2 window sash with plain trim and corner boards.

RELATED STRUCTURES: (Describe)


A garage/shop.

STATEMENT OF SIGNIFICANCE:

T.H.42 has been relocated since this house was built. Its early location was south of the house. This house is a good example of a vernacular 3/4 Cape built in Central Vermont in the early 1800's.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-21

79-A-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Ott House, 1205-21
79-A-97 Betsy Bouton

Listed on State Register
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	TH64 overlooking Curtis Pond
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent 100% Good % Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	


SURVEY NUMBER:	1205-22
NEGATIVE FILE NUMBER(S):	79-A-97 (19,20) 79-A-98 (1)
UTM REFERENCES:	Zone/Easting/Northing A 18/699000/4916840 B C D
U.S.G.S. QUAD. MAP:	Mount Worcester Quad. 7.5' Series
COMPLEX INFORMATION ONLY	
COMMON NAME:	
PRESENT FORMAL NAME:	Patrick Henry Farm
ORIGINAL FORMAL NAME:	
TYPE OF COMPLEX:	Agricultural
TYPES OF STRUCTURES:	Dwellings & farm buildings
PRESENT USE:	Seasonal
ORIGINAL USE:	Agricultural
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

STATEMENT OF SIGNIFICANCE:
 This property, once the George Kent farm, has played a significant role in Calais' town history. One of the original pioneer cabins, the Robinson Cabin remains today as a guest cottage beside a 1879 house and a complex of barns built in the 1860's.

THREAT TO STRUCTURES:	No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:
-----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
------------------	-------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Patrick Henry as per the deeds recorded in office of the Calais Town Clerk.

REFERENCES:

Stanley Fitch

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)
 MAP NUMBER: 1 | DATE BUILT: c.1810 | SURVEY NUMBER: 1205-22
 FUNCTIONAL TYPE: Dwelling | NEGATIVE FILE NUMBER: 79-A-97(19)
 COMMON NAME: Robinson Pioneer Cabin | OWNER: Patrick Henry
 DESCRIPTION: This 3x2 bay, 27x27 cabin originally had a central chimney with Dutch oven. The basic lines and massing of the house have been retained as well as some features on the interior (vix., chair rail and hand hewn beams). The structure served various farm uses after the main house was built in 1879 to replace it. It was restored in the 1970's. It had original handprinted wallpaper.

MAP NUMBER: 2 | DATE BUILT: 1879 | SURVEY NUMBER: 1205-22
 FUNCTIONAL TYPE: Dwelling | NEGATIVE FILE NUMBER: 79-A-97(20)
 COMMON NAME: | OWNER:
 DESCRIPTION: This 2½-story 5x4 bay, 32x20 house has a wing with a pair of wall dormers (after 1850). A long shed attaches to the north side of the wing. This handsome, imposing house has standard features for large houses of the late 1860's and 1870's. Heavily profiled cornice moldings over its windows, a heavy entablature, a dramatic roofline which widely overhangs the gable-end walls, and on-ridge chimneys. The wing's paired wall dormers reflect the Gothic Revival in a highly derivative sense, while its porch beautifully illustrates a tendency of the Victorian period toward the elongation and abstraction of Classical details (e.g., porch posts). Entrance frontispiece appears to be a twentieth century reproduction of Federal-style design.

MAP NUMBER: 3 | DATE BUILT: 1865 | SURVEY NUMBER: 1205-22
 FUNCTIONAL TYPE: Barns | NEGATIVE FILE NUMBER: 79-A-98(1)
 COMMON NAME: | OWNER:
 DESCRIPTION:
 A large three-story barn with gable roof has another two-story barn at right angles to it forming a bridge from the farm road to the larger barn.

MAP NUMBER: | DATE BUILT: | SURVEY NUMBER:
 FUNCTIONAL TYPE: | NEGATIVE FILE NUMBER:
 COMMON NAME: | OWNER:
 DESCRIPTION:

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



1205-22
#1

79-~~A~~-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Patrick Henry Farm/Robinson Pioneer
Cabin, #1, 1205-22
79-A-97 Betsy Bouton



1205-22
#2

79-A-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Patrick Henry Farm, main house,
#2, 1205-22
79-A-97

Betsy Bouton



1205-22
#3

79-A-98

Vt. Div. of Historic Preservation
Washington County Calais 5/79
Patrick Henry Farm, barns, 1205-22
79-A-98 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1985

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:
1205-23

NEGATIVE FILE NUMBER:
79-A-98 (2-4)

UTM REFERENCES:
Zone/Easting/Northing
18/698690/4917960

U.S.G.S. QUAD. MAP:
Mount Worcester Quad., 7.5' Series

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

ORIGINAL USE:

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR: Orig. owner
Wheeler

PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:
c.1850

COUNTY: Washington

TOWN: Calais

LOCATION: N. side T.H.2, 1½ miles W
of Maple Corner

COMMON NAME:
The Old Wheeler Place

FUNCTIONAL TYPE:

OWNER: Hazel Stevenson
 ADDRESS: Worcester
 RD 05682

ACCESSIBILITY TO PUBLIC:
 Yes No Restricted

LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys metal
 Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x3 & wing Entrance Location: Gable end side

Approximate Dimensions: 30x44

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Gable front plan. Corner pilasters. The walls of this house were back plastered. The lath was hand split. A Dutch oven was removed from the ell which was probably the earliest portion of the structure. The interior woodwork is ornamental with five panel doors.

The entrance door has a granite sill, 2/3 sidelights and paneled reveal. Windows have 6/6 sash. Narrow pedimented gable dormers with peaked surrounds. Cornice returns.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:


The side hall plan of this structure has few examples in Calais and the Greek Revival details, exemplified by the doorway, woodwork and paneled pilasters are good examples of their type.

REFERENCES:

MAP: (Indicate North in Circle)



1205-23



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other: Pond

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-23

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Wheeler/Stevenson House, 1205-23
79-A-98 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:
 1205-24

NEGATIVE FILE NUMBER:
 79-A-98 (5-7)

UTM REFERENCES:
 Zone/Easting/Northing
 18/698300/4918130

U.S.G.S. QUAD. MAP:
 Mount Worcester Quad., 7.5' Series

PRESENT FORMAL NAME:
 Gitana/Khana House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: ell-Dance Hall

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor

STYLE: Vernacular

DATE BUILT:
 c.1820, c.1870 (ell)

COUNTY: Washington

TOWN: Calais

LOCATION: End of T.H.24 about .2 mi.
 from T.H.2, near Worcester line.

COMMON NAME:
 Wheeler-Persons Farm

FUNCTIONAL TYPE:

OWNER: Nina Gitana & T.S. Khanna
 ADDRESS: (Trustees)
 Worcester, VT.

ACCESSIBILITY TO PUBLIC:
 Yes No Restricted

LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon Ell-plank
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x2 Entrance Location: Central eave

Approximate Dimensions: 27x27 & ell

THREAT TO STRUCTURE:
 No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:
 Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A 1½-story frame and clapboard structure with a modified saltbox roof. Entrance at the corner of an end wall. Cornice without returns. Metal roof. Plain trim.

Large ell -- (c.1870) 1½-story, post and beam with plank (horizontal) construction. Roughly 22x45 with steeply-pitched gable roof. One on-ridge chimney. Widely overhanging gable end walls (without cornice returns). Asphalt shingle roof.

RELATED STRUCTURES: (Describe)

Barn -- Post and beam with plank siding; steeply pitched gable roof; approximately 25x40. Fair condition.


STATEMENT OF SIGNIFICANCE:

The plain structures are unusual examples of folk building approaches and do not follow standard design approaches of their time or locale. The ell is of historical significance locally as a popular dance hall. The dance hall was operated for many years by the Wheelers.

REFERENCES:

Estelle (Persons) Dodge, East Montpelier. (She has old photo of house)

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-24

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Person/Gitanna/Khanna House, 1205-24
79-A-98 Betsy Bouton



1205-24

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Person/Gitanna/Khanna House, 1205-24
79-A-98 Betsy Bouton



1205-24

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Person/Gitanna/Khanna House, 1205-24
79-A-98 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1988

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-25

NEGATIVE FILE NUMBER:

79-A-98 (8 & 9) 82-A-290

UTM REFERENCES:

Zone/Easting/Northing

18/698250/4916960

U.S.G.S. QUAD. MAP:

Mount Worcester Quad. 7.5' Series

PRESENT FORMAL NAME:

Wheelock House

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1810, c.1870

COUNTY: Washington

TOWN: Calais

LOCATION: South of TH 41 about 1/5 mile
from intersection with TH #2.

COMMON NAME:

Old Wheelock Place

FUNCTIONAL TYPE: Dwelling

OWNER: Raymond and Rosemary Wheelock

ADDRESS: 1335 Covington Drive
Ann Harbor, MI 48103

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4 x 2 +

Entrance Location: eave side

Approximate Dimensions: 27' x 22' plus addition

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The north end of the structure is a small Cape dwelling with a broad gable and central chimney. It may be one of the early Calais houses.

Attached to the older structure is a central gable front, 2 story addition with hip-roofed front porch. It was probably constructed in the late 19th century. Extending to the south of the central section is a 1½ story ell, which balances in composition the Cape section on the north.

RELATED STRUCTURES: (Describe)


Handsome barn with vertical siding and bridge to second story. It is in deteriorated condition.

STATEMENT OF SIGNIFICANCE:

The northern section of this structure represents an early 19th century farm house. The evolution of the structure is an interesting effort to reuse an earlier structure in a balanced new design.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY: Betsy Bouton

ORGANIZATION: VT Division for Historic Preservation

DATE RECORDED: May 1979



1205-25

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Wheelock House, 1205-25
79-A-98 Betsy Bouton



1205-25

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Wheelock House, 1205-25 W
82-A-290 Gina Campoli



1205-25

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Wheelock Barn, 1205-25 W
82-A-290 Gina Campoli



1205-25

79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Wheelock House, 1205-25
79-A-98 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-26

NEGATIVE FILE NUMBER:

79-A-97 #5

UTM REFERENCES:

Zone/Easting/Northing

18/698740/4914930

U.S.G.S. QUAD. MAP:

Montpelier Quad., 7.5' Series

PRESENT FORMAL NAME:

Murphy House

ORIGINAL FORMAL NAME:

COUNTY: Washington

TOWN: Calais

LOCATION: West side of the County Road
 (T.H.1) 1.2 miles north of T.H.46, the
 road to Bliss Pond.

COMMON NAME:

Bennett Farm

FUNCTIONAL TYPE: Dwelling

OWNER: Roger & Anna Murphy

ADDRESS: Calais

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

PRESENT USE: Dwelling

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
 Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1845

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2

Entrance Location: Central Front

Approximate Dimensions: 32x28

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

An enclosed entrance porch has been added to the ell of this ^{Classic Cottage} The application of aluminum siding has obscured or destroyed some of the Greek Revival style woodwork details on the exterior of the building. House retains boxed cornice and returns, and handsome entrance with 3-panel front door, 6" reveal, 2/3 sidelights, granite sill, pedimented head, and door knobs of silver glass.

A 1½-story gabled wing (with enclosed porch on north end and two carriage bays) connects the house to a 1½-story gable-front, clapboarded barn with 2 hay doors, sliding barn door and 12/12 gable window on front.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This house and the Martin House (1205-1#15) in Kent's Corner are very similar and may have been built by the same person. Both have very strong Greek Revival details. The symmetrical placement of wall openings in the parlors and the molded woodwork with pedimented heads and corner blocks are very good examples of the Greek Revival style.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-26

79-~~17~~-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Bennett-Murphy Farm, 1205-26
79-A-97 Betsy Bouton

Listed on State Register
 VT Act 111
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Maple Corner; the intersection of TH 1, 2 and 5
NAME OF DISTRICT:	Maple Corner Historic District
TYPE OF DISTRICT:	Residential, Commercial, Public
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 80 % Fair 20 % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:

This settlement grew up around the crossroads and the water power potential of Curtis Pond. An early sawmill and grist mill (1817) utilizing the water power were followed by a woolen mill and machine shop which produced horse rakes in 1873. A carriage factory was converted to a creamery serving over 60 farms in the 1910-1915 period. The Grange (Community Hall) was the social center for this area of Calais.

The pond adds to the scenic quality of this settlement and with 19th century farm-houses and barns, provides a significant pastoral landscape. The commerce has dwindled to a store and post office. There are few modern intrusions.

SURVEY NUMBER:	1205-27
NEGATIVE FILE NUMBER(S):	79-A-279, 82-A-290, 82-A-291
UTM REFERENCES:	Zone/Easting/Northing A 18 / 699650 / 4916500 B 18 / 699650 / 4916150 C 18 / 699400 / 4916150 D 18 / 699500 / 4916500
U.S.G.S. QUAD. MAP:	Plainfield Quad. 15'
COMPLEX INFORMATION ONLY	
COMMON NAME:	
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
TYPE OF COMPLEX:	
TYPES OF STRUCTURES:	
PRESENT USE:	
ORIGINAL USE:	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>


THREAT TO STRUCTURES:	No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other: <input type="checkbox"/>
-----------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other: <input type="checkbox"/>
------------------	--------------------------------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



MAPLE CORNER
HISTORIC DISTRICT



BOUNDARY DESCRIPTION:

See Continuation Sheet.

REFERENCES:

Hemenway, Neal Converse, Elizabeth Kent Gay, Olivia Gay

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

April, 1980

CONTINUATION SHEET

Survey Number: 1205-27

Boundary Description:

The boundary of the Maple Corner Historic District begins at Point A, located at the northeast corner of the C. Fitch Property (#3). It thence proceeds in a southeasterly direction along the rear (east) property lines of #'s 3, 4, 5, 6 and 7 and a southerly extension of the rear (east) property line of #7, across the brook to Point B, on the south bank of the brook. It thence proceeds in a southeasterly direction along the south bank of said brook to Point C, at the intersection of the southeast property line of the F. Fitch Property (#9). The boundary thence proceeds in a southwesterly direction, crossing Town Highway 1 to Point D, the southeasternmost corner of the Lamphere Property (#11). It thence proceeds in a northwesterly direction along the rear (south) property line of the Lamphere Property (#11) and a westerly extension thereof, crossing Town Highway 5, and continuing along the south property line of the Gay Property (#12) to Point E, the southwestern corner of the Gay Property (#12). The boundary thence proceeds in a northeasterly direction along the wester property line of the Gay Property (#12) to Point F, located at the intersection with the south bank of the brook. It thence proceeds in a northerly direction along the southwesterly bank of the brook to its junction with Curtis Pond, Point G. It thence proceeds in an easterly and northerly direction along the bank of Curtis Pond to Point H, at the intersection of the northern property line of the Remick Property (#1 and 2). The boundary thence proceeds in a southeasterly direction, crossing Town Highway 5, to Point A, the point of beginning.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/> COMPLEX <input type="checkbox"/>		
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1835	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-291
COMMON NAME:		OWNER: Paul and Emma Remick
DESCRIPTION: This Cape and rambling ell has had several alterations. A modern gabled entrance porch marks the front facade and a shed porch with square columns and a balustrade rail is across the south gable facade. Aluminum siding covers the house and a new picture window is in the south gable peak. The eaves are plain and almost flush. The cornice returns on the ell. Sash are primarily 2/2 and a gabled wall dormer is on the south facade of the ell. Attached to the rear of the ell is a 1½ story, clapboarded barn with two garage doors on the east facade.		
MAP NUMBER: 2	DATE BUILT: c.1885	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 82-A-291
COMMON NAME:		OWNER: Paul and Emma Remick
DESCRIPTION: This large gabled, clapboarded barn has an east gable end ramp leading to the second level entrance which consists of sliding doors topped by a multi-paned transom; an additional sliding door is on the west end. Added round metal ventilators are on the ridge. A small gabled ell is on the west end.		
MAP NUMBER: 2A	DATE BUILT: c.1900	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Carriage Barn		NEGATIVE FILE NUMBER: 82-A-291
COMMON NAME:		OWNER: Paul and Emma Remick
DESCRIPTION: Three large, polygonal openings mark the south eaves facade of this clapboard covered, gabled outbuilding. The middle and left bay has one-third light garage doors. A beltcourse runs between the first story and a hay-loft is above.		
MAP NUMBER: 2B	DATE BUILT:	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Sugarhouse		NEGATIVE FILE NUMBER: 82-A-291
COMMON NAME:		OWNER: Paul and Emma Remick
DESCRIPTION: Sheathed in vertical board, this gabled sugarhouse has a characteristic sugarhouse vent on the ridge and a shed-roofed woodshed on the east facade.		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX

(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 3	DATE BUILT: c.1860	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 82-A-290,291
COMMON NAME: C and R Farm		OWNER: Cedric and Emma Fitch

DESCRIPTION: The gabled bank barn has clapboard and vertical board sheathing, a sheet metal roof and a small detached metal silo. Track doors on the west gable ends are topped by a transom light; the west end has a stone ramp. To the rear is a shed-roofed addition. The barn was originally associated with #16.

MAP NUMBER: 4	DATE BUILT: c.1870	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Community Hall		NEGATIVE FILE NUMBER: 82-A-290,291
COMMON NAME: Community Hall		OWNER: Maple Valley Community Club

DESCRIPTION: This structure was used as a store (Bailey's Store) when it shared the site in Gospel Hollow with the Herriott's House (1205-34). About 1900, it was moved to Maple Corner to serve as a grange hall. The 2½ story, 4 x 2 bay building has a two-story, 1 x 2 bay, nearly flat roofed addition and a gable-roofed entrance porch (later addition) supported by square columns and square pilasters flanking the entrance. The foundation is concrete block and 2/2 sash mark the facade. The interior has a stage and meeting room on the second floor which also is a dance hall with a spring floor. The room is finished with pressed metal.

MAP NUMBER: 5	DATE BUILT: c.1858	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: School		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME: Maple Corner School		OWNER: Elizabeth Kent Gay

DESCRIPTION: This is a two-story, clapboarded building with irregular bays and cross-gable roof topped by a bell tower. The tower has a Gothic shaped, louvered window, bracketed cornice and metal bellcast roof. The structure has four (12/12 sash) extra large school windows on the second floor and 12/12 standard windows with peaked heads on the first floor. An outside stairway on the north wall is covered. Other details include: cornerboards with capitals, boxed eaves and returns, and a granite foundation, an Italianate bracketed door hood. The two schoolrooms are on the second floor. The first floor was originally used as community hall.

MAP NUMBER: 6	DATE BUILT: c.1885	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME: Old Vilbrin Place		OWNER: Elizabeth Kent Gay

DESCRIPTION: A 1½ story, gable-front house with aluminum siding and 2/2 sash windows. An open porch across the front and south side has a sheet metal roof and paired stick posts. Bargeboard decorates the front gable and a shed-roofed extension is on the south facade.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 7	DATE BUILT: c.1850	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER: Gregory Gallagher
DESCRIPTION: This 1½ story, Classic Cottage has a shed dormer on the south front facade. A porch across the front and west facades has square posts, some paired, set on a clapboarded rail. The front door is flanked by half-length sidelights. A wing and an attached clapboarded barn is on the east gable end. The ornamental bargeboard in the west gable peak should be noted.		
MAP NUMBER: 8	DATE BUILT: c.1885	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME: Old Creamery/Mrs. Bullock's House		OWNER:
DESCRIPTION: A 1½ story house with a rear exposed basement. It has aluminum siding and a porch across the front. The stove chimneys are near the end of the ridge. The structure was originally used as a skimming station for area farmers. The cream went to the creamery in North Montpelier. The skim milk was kept to feed pigs.		
MAP NUMBER: 8A	DATE BUILT: c.1880	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Shed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION: This saltbox shaped, one-story shed is sheathed in vertical board. Many of the 6/6 windows are broken. Swinging barn doors are on the south eaves front.		
MAP NUMBER: 9	DATE BUILT: c.1820	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER: Floyd and Beatrice Fitch
DESCRIPTION: A Cape type residence, with a wing and attached barn extending from the south facade. Clapboarded and very plainly trimmed. Sash have been replaced with 2/2's. A modern single-pane window, a gabled wall dormer and a turned porch, beneath the dormer, detail the wing. The bank barn has board and batten sheathing and small, multi-paned windows.		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 10	DATE BUILT:	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Elizabeth Lamphere

DESCRIPTION: This modern, one-story house sheathed in barnboard siding does not contribute to the historic district.

MAP NUMBER: 11	DATE BUILT: c.1850	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER: Elizabeth Lamphere

DESCRIPTION: This barn was originally associated with a house that burned and stood on the site of #10. It is a post and beam structure with vertical board sheathing and few small, square window openings.

MAP NUMBER: 11A	DATE BUILT: c.1880	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER:

DESCRIPTION: A small saltbox shaped barn with sliding barn doors on the south side, vertical board sheathing.

MAP NUMBER: 11B	DATE BUILT: c.1920	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Shed		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER:

DESCRIPTION: This small, gabled shed is characterized by deep eaves and novelty board siding.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 12	DATE BUILT: c.1835	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME: Kent's House/Dr. Bliss House		OWNER: Elizabeth Kent Gay
DESCRIPTION: This 1½ story, low-pitched, gable-front block has a long, gabled ell extending from the north facade. Trim includes a few corner pilasters, a narrow returning cornice and peaked lintel boards above a few of the 2/2 sash. Additions include shed dormers on the ell, a gabled hood above the ell entrance and a deck extending across the front facade. The house was built in 1835 by Ezekiel Kent, son of Remember Kent. It was known as the Van Ornam Place before a Dr. Bliss owned it. A barn on the property was moved to Camp Comfort.		
MAP NUMBER: 12A	DATE BUILT:	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Garage		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Elizabeth Kent Gay
DESCRIPTION: A modern, two-bay, gabled garage sheathed in vertical board. It does not contribute to the historic district.		
MAP NUMBER: 13	DATE BUILT:	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Garage		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION: A two-bay, gabled garage with synthetic siding and gable-front barn doors. It does not contribute to the historic district.		
MAP NUMBER: 14	DATE BUILT: c.1960	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Store		NEGATIVE FILE NUMBER:
COMMON NAME: Maple Corner Store		OWNER: Howard Siegrist
DESCRIPTION: A modern, gable-front store with clapboard covering on the first floor and T-111 on the second. It does not contribute to the historic district.		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 15	DATE BUILT: c.1820	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER: Marion Anderson

DESCRIPTION: This plain Cape type house is trimmed with fairly deep returning eaves, cornerboards and half-length/sidelights above paneled bases. Windows include 12/8 sash; fixed 12 lights in the gable peaks. There is a west gabled wing.

MAP NUMBER: 15A	DATE BUILT:	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Barn/Apartment		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION: A gabled barn with an apartment on the second floor; new clapboard siding and two garage bays on the north facade.

MAP NUMBER: 16	DATE BUILT: c.1848	SURVEY NUMBER: 1205-27
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-290
COMMON NAME:		OWNER: The Lunts

DESCRIPTION: A Classic Cottage trimmed with peaked lintel boards above 6/6 sash and the Christian cross entrance door, three-quarter-length sidelights and sideboards. A long south wing has a modern picture window, an open shed-roofed porch and modern overhead doors.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:



Dam

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Maple Corner Dam,
82-A-291 N
Gina Campoli



#1

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Remick House,
1205-27 #1 NW
82-A-291 Gina Campoli



#2

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Remick Barn,
1205-27 #2 W
82-A-290 Gina Campoli



#1A

82-A-291


Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Remick Carriage
Shed, 1205-27 #1A N
82-A-291 Gina Campoli



#4, #3

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD:Community Hall,
1205-27 #4;Fitch Barn,1205-27 #3 N
82-A-291 Gina Campoli



#3

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Fitch Barn,
1205-27 #3 NE
82-A-290 Gina Campoli



#5

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Maple Corner
School, 1205-27 #5 E
82-A-290 Gina Campoli



#4

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Community Hall,
1205-27 #4 E
82-A-290 Gina Campoli



#7

82-A-290


Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Gallagher House,
1205-27 #7 E
82-A-290 Gina Campoli



#5, #6

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Maple Corner
School and Gay House, 1205-27#5,6
82-A-290 E Gina Campoli



#8, #8A

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Bullock House and
Barn, 1205-27 #8,8A NW
82-A-290 Gina Campoli



#8

82A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Bullock House,
1205-27 #8
82-A-290
Gina Campoli NW



#9

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Fitch House,
1205-27 #9 N
82-A-290 Gina Campoli



#9

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Fitch House,
1205-27 #9 N
82-A-290 Gina Campoli



#11B, #11

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Lamphere Barn,
1205-27 #11B, 11
82-A-290

Gina Campoli^N



#11, #11A

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Lamphere Barn,
1205-27 #11, 11A N
82-A-290 Gina Campoli



#15

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Anderson House,
1205-27 #15 W
82-A-290 Gina Campoli



#12

82-A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Gay House, 1205-27
#12 NW
82-A-290 Gina Campoli



#16

82A-290

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Lunt House,
1205-27 #16 W
82-A-290 Gina Campoli

Listed on State Register

VT
Date

12/15/1983

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	W. side of T.H.5 opposite intersection with T.H.25, approx. 1 mile N. of Maple Corner
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	George Rossiter
ADDRESS:	Felt Road Ireene, N.H. 03431
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER:	1205-28
NEGATIVE FILE NUMBER:	79-A-97 (6)
UTM REFERENCES:	Zone/Easting/Northing 18/700000/4917375
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15' Series
PRESENT FORMAL NAME:	Rossiter House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Summer Home
ORIGINAL USE:	Dwelling
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular Greek Revival
DATE BUILT:	c.1850

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½ plus attic

Number of Bays: 5x2 Entrance Location: Central Front

Approximate Dimensions: 25x37

THREAT TO STRUCTURE:	
No Threat <input checked="" type="checkbox"/>	Zoning <input type="checkbox"/> Roads <input type="checkbox"/>
Development <input type="checkbox"/>	Deterioration <input type="checkbox"/>
Alteration <input type="checkbox"/>	Other: <input type="checkbox"/>

LOCAL ATTITUDES:	
Positive <input checked="" type="checkbox"/>	Negative <input type="checkbox"/>
Mixed <input type="checkbox"/>	Other: <input type="checkbox"/>

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The high kneewall and steeply-pitched roof of this Classic Cottage indicate that this is a late Greek Revival house. Corner pilasters and a full entablature (with returns) frame the structure. Windows have peaked window heads. The front door is obscured by wooden storm sash. A porch with hip roof extends across the south end (gable). It has square (modern) posts. A dormer on the rear slope has close eaves and a steep gable roof. Sash is 2/2 and 6/6.

RELATED STRUCTURES: (Describe)


A horse barn in fair condition.

STATEMENT OF SIGNIFICANCE:

This house is typical of those built in the mid 1800's in Central Vermont. It retains its original Greek Revival detailing and is a good example of its type.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Rossiter House, 1205-28
79-A-97 Betsy Bouton



T.H. 5
& 1

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Intersection of
T.H. 5 and T. H. 1 N
82-A-291 Gina Campoli



T.H. 2
& 5

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Maple Corner HD: Intersection of TH
2 and TH 5 N
82-A-291 Gina Campoli

Listed on State Register

VT ACHP

Date:

12/18/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	End of T.H.65, .25 miles west of the County Road.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Margaret Burkis
ADDRESS:	Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

- Structural System
1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:
- Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3x4

Approximate Dimensions: 25x28

SURVEY NUMBER:

1205-29

NEGATIVE FILE NUMBER:

79-A-97 (#10)

UTM REFERENCES:

Zone/Easting/Northing

18/699650/4918500

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Burkis House

ORIGINAL FORMAL NAME:

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1840

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The windows and doors of this house were obscured by storm batten when it was surveyed. The house has boxed eaves, returns and wide corner boards. Window and door trim is plain. Granite foundation stones have mitred corners. Both doors have very plain hoods with convex slopes.

RELATED STRUCTURES: (Describe)


A small building with attached outhouse.

STATEMENT OF SIGNIFICANCE:

This house is an example of vernacular farm dwellings built in Calais in the 19th century.

REFERENCES:

MAP: (Indicate North in Circle)



.25 MILE TO
COUNTY ROAD



T.H. 65

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-#97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Burkis House, 1205-29
79-A-97 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	End of T.H.22, West of the Dugar Brook Road (T.H.#9)
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Robert Holt
ADDRESS:	48 Deerfield Dr. Montpelier
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: Central front

Approximate Dimensions: 34x26

SURVEY NUMBER:

1205-30

NEGATIVE FILE NUMBER:

79-A-97 (16 & 17)

UTM REFERENCES:

Zone/Easting/Northing

18/701000/4919675

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Holt House

ORIGINAL FORMAL NAME:

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1810

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has a roof with cropped eaves, a molding return and a granite foundation. A screened porch has replaced sheds. The original exterior walls were covered with clapboards; they are now shingled. On the interior, several partitions and the original accordian lath have been removed. Windows have 12/8 sash with metal sills. The four panel door has a Norfolk latch.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This house with central chimney, cooking fireplace and Dutch oven replaced an earlier log structure on this property on Dugar Brook, which took the name of an early resident on this farm. A charcoal pit on the property once provided the fuel for area blacksmiths. Few houses from this early period of Calais history retain their original chimneys.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-~~A~~-97

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Robert Holt House, 1205-30
79-A-97 Betsy Bouton

Listed on State Register
VT AL 12/15/1989
Date

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Apple Hill
	East side of T.H.28, 1 mile south of T.H.9.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Stuart & Sue Savage
ADDRESS:	RD, East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: Central eave

Approximate Dimensions: 40x30

SURVEY NUMBER:

1205-31
NEGATIVE FILE NUMBER: 79-A-52
UTM REFERENCES: Zone/Easting/Northing 18/702350/4917700
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Savage House
ORIGINAL FORMAL NAME:
PRESENT USE: Dwelling
ORIGINAL USE: Dwelling
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Cape
DATE BUILT: Prior to 1820

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has been sympathetically reworked, but it is difficult to determine exactly which elements are original. It has a central chimney (rebuilt), horizontal plank wainscot, built in corner cupboard, and windows with 12/12 sash. The eaves are cropped. The roof line has been extended in the rear to cover a porch. The kitchen occupies a former woodshed.

RELATED STRUCTURES: (Describe)

A hand dug well with laid up stones is on the property.


STATEMENT OF SIGNIFICANCE:

This house is one of the oldest in Calais. It retains much of its original Cape massing and is now a year round residence after years of seasonal use.

REFERENCES:

Sue Savage

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

Stone walls

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-52

Survey

Vt. Div. for Historic Preservation
Washington Calais 5/79
Savage House, 1205-31 E
79-A-52 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	T.H.#1 in Gospel Hollow at intersection with T.H.27.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	David & Joanne Murray
ADDRESS:	RFD 1 Town St., Montpelier, VT 05602
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER:	1205-32
NEGATIVE FILE NUMBER:	79-A-51
UTM REFERENCES:	Zone/Easting/Northing 18/701450/4915875
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15' Series
PRESENT FORMAL NAME:	Murray House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Residence
ORIGINAL USE:	Residence
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular
DATE BUILT:	c.1848 (over door)

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 4x2 & ell

Approximate Dimensions: 20x28

Entrance Location: Central eave

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:

Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The door in the Classic Cottage mass has a transom light. The ell wing roof extends over a full width porch. Architectural details are limited to wide corner boards, boxed cornice and returns. Stove type chimneys stand on ridge on either end of the main mass. Sash is 2/2, with a 6/6 window in the east gable peak. There may originally have been a second window to the right of the front door; this would be the typical configuration, although there are other houses in the area with similar fenestration.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This house was lived in by Rev. Orrin Davis, minister of the Church in Gospel Hollow beginning in 1860. The house stands across from the old fair grounds or trotting park (note Beer's Map). The brick yard, which produced the bricks for the Kent museum and several other houses in the area, was located across T.H.1 and up the hill toward Kent's Corner.

REFERENCES:

- 1. , Maps: Beers & Walling

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton
ORGANIZATION:

Vt. Div. for Historic Preservation
DATE RECORDED:

April 1979

OLD TROTTING
PARK



79-A-51

Vt. Div. for Historic Preservation
Washington County Calais 4/79
Murray House, 1205-32
79-A-51 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-33

NEGATIVE FILE NUMBER:

79-A-52

UTM REFERENCES:

Zone/Easting/Northing

18/702525/4915800

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

Calais Town Hall

ORIGINAL FORMAL NAME:

The Davis Church

PRESENT USE: Town Meeting Hall

ORIGINAL USE: Church

ARCHITECT/ENGINEER:

Possibly a Calais architect

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

1868

COUNTY: Washington
 TOWN: Calais
 LOCATION: "Gospel Hollow" south side of
 T.H.1 near intersection with T.H.3.

COMMON NAME:

Calais Town Hall

FUNCTIONAL TYPE: Church

OWNER: Town of Calais & Ladies Home

ADDRESS: Mission

Calais, VT

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete

Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 2

Number of Bays: 3 on side

Entrance Location: Center second floor

Approximate Dimensions: 44x35

front

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This church has a simple 2-stage square bell tower and spire on the front ridge of the roof; each stage has corner boards and an entablature. A small gabled entrance porch has replaced the one which originally extended across the front at the second floor level. Wide corner boards, boxed eaves and returns show Greek Revival style influence. First floor has 12/12 windows while the second floor windows which light the meeting room are large 20/20 windows. Both have shutters. A low addition protrudes from the rear of the church.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This building is used for Town Meetings and for occasional other uses. The church was organized in 1810 by Rev. Orrin Davis and this building was built in 1868.

(During spring-summer 1981, work was being carried out on the foundation of the church.)

REFERENCES: A Greek Revival plan for a meeting house is in the Research Library at Old Sturbridge Village done by a Calais gentleman . Hemenway

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

A brook winds around structure.

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Davis Church/Calais Town Hall W
1205-33
79-A-52

Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-34

NEGATIVE FILE NUMBER:

79-A-104 #1

UTM REFERENCES:

Zone/Easting/Northing

18/701850/4915875

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Herriott House

ORIGINAL FORMAL NAME:

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.1 (The Brook Rd.), 3/4 mile south of T.H.9 intersection

COMMON NAME:

The Brook House

FUNCTIONAL TYPE: Dwelling

OWNER: Dr. Frank Herriott

ADDRESS: RD

East Calais

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
 Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1835

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 36x25

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has modern outside end chimneys. Windows have 6/6 sash. The outstanding feature of the house is a front door with five panels, transom light of seven panes, and 2/3 sidelights. The recessed doorway has a finished granite sill and steps. The shallow pitch of the roof and overhanging eaves seem inconsistent; the roof may have been reworked at some point.

RELATED STRUCTURES: (Describe)

Modern ell and walk to 2 car garage.
Millstone in yard.


STATEMENT OF SIGNIFICANCE:

This house is one of the few old houses which remain of the bustling hamlet in this part of Calais called Gospel Hollow after the dominant structure, "The Davis Church" (1205-33). In the early and mid 19th century, hydro power from the brooks powered a number of small mills including a grist mill, saw mill and a starch factory owned by Kent & Bancroft. A large store was moved from this property to become a hall for the Grange in Maple Corners. (See 1205-27). The house retains much of its early appearance, including a typical Greek Revival door.

This was once the location of a spa. Stone walls, dams and foundations remain.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Brook
- Stone foundations

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Cameron/Fair House, 1205-35
79-A-104 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1988

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-35

NEGATIVE FILE NUMBER:

79-A-104 #2 & 3

UTM REFERENCES:

Zone/Easting/Northing

18/702575/4917000

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Fair House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1840

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.1, just south of intersection with Dugar Brook Rd. (T.H.9).
COMMON NAME:	Cameron Place
FUNCTIONAL TYPE:	Dwelling
OWNER:	Donald Fair
ADDRESS: RD	East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 36x24

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The interior of this house has been extensively reworked. Most windows have 2/2 sash, but one with 12/8 remains in the gable. The house has corner boards, boxed eaves with returns. The elaborate front door with six panels has a transom light, corner blocks and shaped granite steps.

Six panel doors show bird's eye maple graining. A box lock with brass knob is marked "Carpenter & Co. Patentees." A coat of arms is a crown with "WR".

A 2-bay porch on the wing has double posts and floor of huge slate slabs. An arched carriage bay occupies the far left side of the wing.

It displays transitional Cape Cod/Classic Cottage massing.

RELATED STRUCTURES: (Describe)

Modern barn across the street.


STATEMENT OF SIGNIFICANCE:

This place was owned by a carpenter. It is referred to as the Alley Cameron place. There was a brick yard on the property. It is a good example of a typical Greek Revival farmhouse from the mid 19th century.

REFERENCES:

Roy Fair

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Brook/Herriot House 1205-34
79-A-104 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:
 1205-36

NEGATIVE FILE NUMBER:
 79-A-104 #4

UTM REFERENCES:
 Zone/Easting/Northing

18/703725/4917300
 U.S.G.S. QUAD. MAP:
 Plainfield Quad., 15' Series

PRESENT FORMAL NAME:
 Rinen House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: School

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:
 After 1873

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.1, opposite
 T.H.5.

COMMON NAME:
 North Calais School

FUNCTIONAL TYPE: School

OWNER: Ramon & Kathryn Rinen
 ADDRESS: 115 Long Beach Rd.
 Nissequoque, N.Y. 11780

ACCESSIBILITY TO PUBLIC:
 Yes No Restricted

LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: Irregular Entrance Location: Left, gable front
 Approximate Dimensions: 24x34

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The gable-front school building is framed by corner boards with capitals, and a full entablature with returns. There is a bank of 4 large windows on the southwest side of the building.

The front door of this school is protected by a gable roofed entrance porch. A small square belfry with a spire rests on the front part of the roof ridge. The basic shape of the structure has been expanded to the rear with a shed roofed addition. Other additions extend north. The gable end has a louvred triangular opening in the tympanum.

The interior has a patterned metal ceiling.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

North Calais was a small industrial center powered by the water held in Mirror Lake (otherwise called #10 Pond & Wheelock Pond) during the 19th century and early 20th century. This school was used to educate the children of the community.

REFERENCES:

Beers Map.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Old North Calais School, 1205-36
79-A-104 Betsy Bouton

Listed on State Register
VT ACHP 12/5/1989
Date: _____

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: In North Calais, opposite the old school, east of intersection TH 1 and TH 5.
COMMON NAME: Scribner Dam
FUNCTIONAL TYPE:
OWNER: Franklin Scribner
ADDRESS: Calais, Vermont
ACCESSIBILITY TO PUBLIC: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER: 1205-37
NEGATIVE FILE NUMBER: 80-A-30, 82-A-291
UTM REFERENCES: Zone/Easting/Northing 18/702850/4917325
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
PRESENT FORMAL NAME: Scribner Dam
ORIGINAL FORMAL NAME:
PRESENT USE: Dam
ORIGINAL USE: Dam
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:
DATE BUILT: c.1850, c.1940

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: _____ Other: _____
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure: Stone and Concrete Dam
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other: _____

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other: _____

Number of Stories: _____

Number of Bays: _____ Entrance Location: _____

Approximate Dimensions: _____

THREAT TO STRUCTURE: No Threat <input type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input checked="" type="checkbox"/> Alteration <input type="checkbox"/> Other: _____

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other: _____

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Dry laid field stone and concrete dam.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

An example of a small-scale farm-related stone dam with concrete wing walls.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY: Betsy Bouton

ORGANIZATION: VT Div. for Historic Preservation

DATE RECORDED: May, 1980



82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Scribner Dam, 1205-37 N
82-A-291 Gina Campoli

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	The East side of T.H.33, 1/4 mile south of T.H.#5.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Franklin, Frieda & Carlie Scribner
ADDRESS:	Calais, Vt.
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION: Obscured

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon Plank
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4x3

Approximate Dimensions: 30x26

Entrance Location: Off center eave

SURVEY NUMBER:	1205-38
NEGATIVE FILE NUMBER:	79-A-105 #2
UTM REFERENCES:	Zone/Easting/Northing 18/703000/4916825
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15' Series
PRESENT FORMAL NAME:	Scribner House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Residence
ORIGINAL USE:	Residence
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	vernacular
DATE BUILT:	c.1830

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:

Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This 3/4 house has corner boards, but no eaves returns. The roof may have been reworked at one time to yield the wide eaves overhang.

Sash is now 2/2. Two shed-roofed dormers with paired windows have been added to the front roof slope.

RELATED STRUCTURES: (Describe)


Two attached sheds are in poor condition and now detached from the house.

STATEMENT OF SIGNIFICANCE:

This plank house has the fenestration of a 3/4 house, a type which has a high incidence in the town of Calais. The setting with sugar maple roadside trees and stone walls is scenic.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Apple orchard
- Stone walls
- Maple trees

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Scribner House, 1205-38
79-A-105 Betsy Bouton



#10

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: Singleton Barn,
1205-39 #10 E
82-A-291 Gina Campoli



#11

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: Fagginer-Auer
House, 1205-39 #11 E
82-A-291 Gina Campoli



map #9 - ~~A~~ Calers Historic District
North Calais



#9

80-F-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
N. Calais HD: Store #9 E
80-A-30 Betsy Bouton



#7

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: Pierce Barn, S
1205-39 #7
82-A-291 Gina Campoli



#8

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: Anderson House, S
1205-39 #8
82-A-291 Gina Campoli



#5

80-A-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
N. Calais HD: Pierce Place #5
80-A-30 Betsy Bouton



#6

80-7-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
N. Calais HD: Freeman-Walker House W
80-A-30 #6 Betsy Bouton



#2

79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
North Calais HD: Bates House,
1205-39, #2
79-A-104

Betsy Bouton



#4

79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
North Calais HD: Old Red Shop,
1205-39, #4
79-A-104

Betsy Bouton



#2

79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
North Calais HD: Bates House,
1205-39, #2
79-A-104 Betsy Bouton



Mill
Dam

79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
North Calais HD: 1205-39, mill dam
79-A-104 Betsy Bouton



North
Calais
Dam

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: North Calais Dam
82-A-291 E Gina Campoli



#1

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
North Calais HD: Bushway House,
1205-39 #1 N
82-A-291 Gina Campoli

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 8	DATE BUILT: c.1900	SURVEY NUMBER:
FUNCTIONAL TYPE: Shop	NEGATIVE FILE NUMBER: 104 #15 (79-A)	
COMMON NAME: Pumpkin Hollow	OWNER: Wendy Anderson	

DESCRIPTION:

This building was used as a harness shop by W.F. Ainsworth (c.1903). It is a gable roofed, 1½ story building about 16' x 34'. It originally had a 3 x 2 bay exterior. It now has a large screened front porch and a shed dormer. It is now used as a dwelling.

MAP NUMBER: 9	DATE BUILT: c.1880	SURVEY NUMBER: 1205-39
FUNCTIONAL TYPE: Store	NEGATIVE FILE NUMBER: 80-A-30	
COMMON NAME: North Calais Store	OWNER: Paul Singleton, East Calais	

DESCRIPTION:

A 4 x 2 bay, 2½ story building with a 2 story porch across the eave side facing the road. The porch is in poor condition. The structure is framed by cornerboards and an entablature with cornice returns. There are paneled doors in the first and 4th bays on the first floor, and in the central bay of the second floor. Sash is 2/2. (A copy of an old photo of the store was given by the owner and is included in the survey.)

MAP NUMBER: 10	DATE BUILT: c.1900	SURVEY NUMBER: 1205-39
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 82-A-291	
COMMON NAME:	OWNER: Paul Singleton (title in question)	

DESCRIPTION:

A gable roof barn now used as a cabinet shop. The eave, roadside wall, has two double doors. Windows have 6/6 sash. The exterior is covered with horizontal board siding.

MAP NUMBER: 11	DATE BUILT: c.1880	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 82-A-291	
COMMON NAME:	OWNER: Wm. and Lisa Fagginger -Auer	

DESCRIPTION:

A four bay front, 1½ story house with an ell. The ell has a recessed porch. The ell roof now extends to cover the front of the ell. The windows and door have pedimented window heads. Gable end includes a raking window and a small, two window shed dormer on the front roof slope.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 12	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Sugarhouse, or woodshed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Wm. and Lisa Fagginger - Auer
DESCRIPTION:		

A small wooden building with a gable roof covered with corrugated sheet metal.

MAP NUMBER: 13	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Garage		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Wm. and Lisa Fagginger - Auer
DESCRIPTION:		

One car garage with board and batten siding. It does not contribute to the historic district.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1870	SURVEY NUMBER: 1205-39
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 82-A-291	
COMMON NAME:	OWNER: Kenneth and Doris Bushway	
DESCRIPTION:		
<p>A 1½ story Classic Cottage house type with an ell; north facade screened in and sleeping porch. Details include molded returning cornice, corner pilasters and cornice window heads. The front door has two etched glass panels. A bracketed hood with added support posts has applique detail on the overscaled scroll brackets</p> <p>1A.</p> <p>A modern one car garage and workshop is noncontributory to the historic district.</p>		
MAP NUMBER: 2	DATE BUILT: c.1840	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER: 79-A-104 (9-11)	
COMMON NAME:	OWNER: William and Gertrude Bates,	
DESCRIPTION: East Calais.		
<p>This 1½ gable-roofed house has two principal facades, to complement its corner location. Its 5-bay east facade is framed by corner boards, a molded cornice (which returns on the south end of the house) and a plain frieze. The central double-leaf door with rectangular glass panels was probably added in the 1870's. It is sheltered by a nearly flat-roofed entrance porch with cornice, frieze and simple round posts and balusters.</p> <p>The north, gable-end of the house is executed in a temple-front design with a projecting second story (with recessed porch) supported by plain round posts (without capitals) creating a recessed porch on the first story.</p> <p>A 1½ story gabled wing extends from the south end of the main block.</p>		
MAP NUMBER: 2	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>Attached to it is a gabled ell of similar height. Both have exposed basements on their rear facades and both are clapboarded and have irregular fenestration. Sash is 2/2 and 6/6.</p>		
MAP NUMBER: 3	DATE BUILT: c.1840	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 79-A-104	
COMMON NAME:	OWNER: Norman Bryant and Clyde Dailey	
DESCRIPTION:		
<p>A low 1½ story house with buildings attached in the rear. The fine bay front is faced with a hip-roofed porch having paired posts with ornate cut-out capital heads, and a shingled porch wall. Two shed-roofed dormers with paired windows rest on the front roof slope.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 4	DATE BUILT: c.1845	SURVEY NUMBER:
FUNCTIONAL TYPE: Commercial	NEGATIVE FILE NUMBER: 79-A-104	
COMMON NAME: Old Red Shop	OWNER: Bryant and Dailey	

DESCRIPTION:

A 1½ story, 4 x 2 bay commercial building, this has three extra large windows (6/6 and 12/12) and large double doors on the front facade. These are protected by a full-width shed roof extension supported by frame braces.
The structure was used as a millinery shop for many years.

MAP NUMBER: 5	DATE BUILT: c.1850	SURVEY NUMBER: 1205-59
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 80-A-30	
COMMON NAME:	OWNER: Gwen and Winston Pierce	

DESCRIPTION:

Reportedly, this house was built to house the workers who were employed to build the brick tavern and inn which stood to the west of it. (note old photo). House is a 3 x 5 bay, 2½ story building with two successively smaller clapboarded wings extending from the rear. Doors and windows have peaked heads. The entrance door on the gable end has 5/6 sidelights and a 5-paned door. The corner pilasters, boxed cornice and returns are Greek Revival details. The foundation stones are granite. One is twelve feet long. Most sash is 2/2. To the left of the front door, two windows were removed and replaced with a 5-part window of modern design capped by a peaked head. A cinder block chimney now rises on the west facade.

MAP NUMBER: 6	DATE BUILT: 1845	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 80-A-30	
COMMON NAME: Freeman Walker House	OWNER: Walter and Gail Dowling	

DESCRIPTION:

A 1½ story frame and clapboard house with additions on the east side. Part of these sheds served as a store and handled boat rentals on Mirror Lake. House has boxed eaves (no returns); a steeply-pitched wall dormer, wood shingle roof, beaded corner boards and a recessed porch in the wing. A bay window of recent construction is on the south wall.

MAP NUMBER: 7	DATE BUILT: c.1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Gwen and Winston Pierce	

DESCRIPTION:

A gable roofed banked barn with board and batten siding. The front, gable side has two carriage bays with braced corners. This barn was the carriage and horse barn which served the large brick inn which once stood across the street. (Note old photos)

North Calais Historic District
Continuation Sheet
Survey Number: 1205-39

BOUNDARY DESCRIPTION

The boundary of the North Calais Historic District begins at Point A, located at a point where the east bank of the brook joins the southern bank of Mirror Lake. Thence the boundary proceeds in a southeasterly direction along the east bank of the brook to Point B, located at the intersection of Town Highway 1. Thence the boundary proceeds in a southerly direction along a northerly extension of the east property line of the Singleton property (#9), crossing Town Highway 1, and proceeding along said property line to Point C, the southeast corner of the Singleton property (#9). It thence proceeds in a southwesterly direction along the rear (south) property line of said property to Point D, the southwest corner of said property. It thence proceeds in a northerly direction along the west property line of the Singleton property (#9) and a northerly extension thereof, crossing Town Highway 17 to Point E, at the northern edge of the right--of-way of Town Highway 17. Thence the boundary proceeds in a westerly direction along said edge of said right-of-way to Point F, at the intersection of the eastern edge of the right-of-way of Town Highway 17. Thence it proceeds in a northerly direction along the eastern edge of the right-of-way of Town Highway 17 to Point G, at the intersection of the north bank of the brook. It thence proceeds in a westerly direction along the northern bank of the brook, passing south of the Bates House (#2) to Point H, located at the intersection of a southerly extension of the western property line of the Bushway property (#1). The boundary thence proceeds in a northerly direction along said extension, crossing Town Highway 1, and continuing along said property line to Point I, the northwest corner of the Bushway property (#1). Thence the boundary proceeds in an easterly direction along the rear (north) property lines of #1, 3, 4, 5, and 6 and an easterly extension of said rear property lines across a dirt drive to the bank of Mirror Lake, at Point J. Thence the boundary proceeds in a southeasterly direction along said bank to Point A, the point of beginning.

Listed on State Register

VT ACHP

Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	On Route #1 at the outlet from Mirror Lake
NAME OF DISTRICT:	North Calais Historic District
TYPE OF DISTRICT:	Residential
PHYSICAL CONDITION OF STRUCTURES:	Excellent 80 % Good 15 % Fair % Poor 5 %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:

North Calais was a busy mill settlement in the 19th century. Today, all that remains of the mill is a complex maze of stone foundations and dam walls, valuable as a resource from which the industrial history of the community may be reconstructed. A number of non-mill buildings, dwellings, store buildings and barns today comprise the village.

The water power available from #10 pond (now Mirror Lake) was used as early as 1800 for saw and grist milling and beginning in 1871, it was used for the manufacture of woolen goods, wool carding and cloth dressing. Other products of North Calais included carriages, wooden clocks, cast bells, coffins and caskets. Wooden fifes were also made by the Marsh brothers.

THREAT TO STRUCTURES:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:


SURVEY NUMBER: 1205-39
NEGATIVE FILE NUMBER(S): 79-A-104 (9-16), 80-A-30
UTM REFERENCES: Zone/Easting/Northing A 18/703650/4918225 B 18/703300/4918000 C 18/703300/4918175 D 18/703500/4918250
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX:
TYPES OF STRUCTURES:
PRESENT USE:
ORIGINAL USE:
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



NORTH CALAIS HISTORIC DISTRICT



BOUNDARY DESCRIPTION:

The boundary line is described on a separate sheet of paper.

REFERENCES:

Heminway; Vrest Orton, Weston, Vermont owns Doten photo collection.

RECORDED BY:
Betsy Bouton

ORGANIZATION:
Vt. Div. for Historic Preservation

DATE RECORDED:
May, 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
North Calais HD: Pumpkin Hollow,
1205-39 #8
79-A-104 Betsy Bouton

Listed on State Register

VT ACHP

Date: 12/15/1987

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-40

NEGATIVE FILE NUMBER:

79-A-106 (19A & 20A)

UTM REFERENCES:

Zone/Easting/Northing

18/703450/4918475

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Memorial Hall

ORIGINAL FORMAL NAME:

Memorial Hall

PRESENT USE: Community Hall

ORIGINAL USE: Community Hall

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

1886

COUNTY: Washington
TOWN: Calais
LOCATION: On a spit of land on the southern end of Mirror Lake

COMMON NAME:

Memorial Hall

FUNCTIONAL TYPE: Meeting Hall

OWNER: Stowe Post Womens Relief Corps

ADDRESS: #36, Calais, VT

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 7x2

Approximate Dimensions: 56x30

Entrance Location: Far left and right bays off porch

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:

Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This vernacular structure is framed by corner pilasters and an entablature with cornice returns. However, it takes its style from its Queen Anne porch. The two story porch on the east side of the building has turned balusters and posts with simple brackets. 2/2 sash windows have molded cornice heads.

The interior retains a ladies' and a mens' parlor with round oak type stoves and circa W.W.I wallpaper. Building also contains a stage and dance floor.

RELATED STRUCTURES: (Describe)

A granite and bronze marker lists the man from Calais who fought in the Civil War.

STATEMENT OF SIGNIFICANCE:

This building represents the enthusiastic and dedicated participation of the men of Calais in the Civil War. It has served as a social center since it was built.


The setting of this structure is very picturesque. It is the site of a park. An incident in which 10 people drowned off the point was the subject of a ballad in the Flander's Collection.

REFERENCES:

MAP: (Indicate North in Circle)



MIRROR LAKE



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Mirror Lake

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-40

79-A-106#19A

Vermont Div. for Historic Preservation
Washington County, Calais 5/79
Memorial Hall, 1205-40 NW
79-A-106 Betsy Bouton

NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
<u>Book I</u>			
Kent's Corner-Old West Church Hist. Dist.	1205-1	79-A-120 80-A-30	
Bailey-Moser House	1205-2	79-A-105	
Balentine Barn	1205-3	79-A-106	
Lynch House	1205-4	79-A-52	
Old District #1 School-The Mill House	1205-5	79-A-52	
Old Sparrow Place-Sloan House	1205-7	79-A-52	
Fowler House	1205-8	79-A-52	
Bliss Tavern-Scott House	1205-9	79-A-52	
Leonard-Graham Farm	1205-10	79-A-52	
Liff Farm	1205-11	79-A-51	
Adamant Methodist Church	1205-12	79-A-51	
Adamant Community Club	1205-13	79-A-105	
Morreale House	1205-14	79-A-51	
LaFountain House	1205-15	79-A-51	
Aaron Tucker-Morse House	1205-16	79-A-52	
Aaron Tucker Farm-Morse Farm	1205-17	79-A-97	
Old Bruce Place-Bradley House	1205-18	79-A-51	
Laqueur House	1205-19	79-A-51	
Levi Robinson House-Cherington Farm	1205-20	79-A-51	
Old Van Ornam House-Ott House	1205-21	79-A-97	
George Kent Farm-Patrick Henry Farm	1205-22	79-A-98, 97	
Old Wheeler Place-Stevenson House	1205-23	79-A-98	
Wheeler-Persons Farm Gitana/Khona House	1205-24	79-A-98	
Old Wheelock Place	1205-25	79-A-98 82-A-290	
Bennett Farm-Murphy House	1205-26	79-A-97	
Maple Corner Historic District	1205-27	80-A-30	
Rossiter House	1205-28	79-A-97	
Burkis House	1205-29	79-A-97	

NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
Holt House	1205-30	79-A-97	
Savage House	1205-31	79-A-52	
Murray House	1205-32	79-A-51	
Davis Church-Calais Town Hall	1205-33	79-A-52	
Brook-Herriott House	1205-34	79-A-104	
Cameron Place-Fair House	1205-35	79-A-104	
North Calais School-Rinen House	1205-36	79-A-104	
Scribner Dam	1205-37	80-A-30 82-A-291	
Franklin/Scribner House	1205-38	79-A-105 79-A-104	
North Calais Historic District	1205-39	80-A-30	
Memorial Hall	1205-40	79-A-106	
Comolli House	1205-41	79-A-106	
Altman House	1205-42	79-A-106	
Laing House	1205-43	79-A-106	
The Old Foster Homestead-Backman House	1205-44	79-A-104	
Backman House	1205-45	79-A-104	
Old Short School-Converse House	1205-46	79-A-98	
Neal Converse Farmstead	1205-47	79-A-120 80-A-30	
Flora George Farm	1205-48	79-A-52	
Maciejowski House	1205-49	79-A-98	
Lyman/Hsich House	1205-50	79-A-98	
Cliche House	1205-51	79-A-98	
Legare Farm	1205-52	79-A-98	
The Clough Place Pelton House	1205-53	79-A-98	
The Pekin School-Weller House	1205-54	79-A-52	
Bloom House	1205-55	79-A-104	
Slayton-Converse House	1205-56	79-A-52 79-A-105	
Old Lilley Farm-Tuller House	1205-57	79-A-106	

BOOK II

NAME OF SITE	SITE NO.	NEGATIVE FILE NO.	N.R.
Jacks-Woodard House	1205-58	79-A-105	
Tucker House	1205-59	79-A-120	
Thurston House	1205-60	79-A-98	
Old Peck Place-Knox House	1205-61	79-A-104 79-A-105	
Fifer's Ride-Brassage House	1205-62	79-A-104	
East Calais Historic District	1205-63	83-A-409 79-A-119	
Judge Charles Dana Place-Clark/Duke House	1205-64	79-A-120	
Batten Farm	1205-65	79-A-106	
Meiklejohn House	1205-66	79-A-106 79-A-106	
Ainsworth-Balentine Farm	1205-67	79-A-119	
Old McCarthy Place-Hayden House	1205-68	79-A-119	
Old Wilbur Place-Rolland House	1205-69	79-A-119	
Dutton House-Sunshine Cottage-Leach House	1205-70	80-A-30	
Leonard-Shedd Farm	1205-71	79-A-120	
Old Bliss Place-Pearce House	1205-72	79-A-106	
Ward House	1205-73	79-A-120	
Smithouse-Dennison/Makepeace Home	1205-74	79-A-120	
George House	1205-75	79-A-105	
Luce House	1205-76	79-A-105	
Max Gray Farm	1205-77	79-A-105	
Geisler Barn	1205-78	79-A-106	
Tonks House	1205-79	79-A-105	
Grand View Farm (Round Barn)-Grout House	1205-80	79-A-105	
Ides Homestead -Balles House	1205-81	79-A-105	
Scribner Hexagonal Silo	1205-82	79-A-105	
Bugbee Farm-Scribner House	1205-83	79-A-105	
Rockwood Farm-Hawkstead Farm	1205-84	79-A-105	
Madeline Wilkinson House	1205-85	79-A-105	
#6 School-Blachly House	1205-87	79-A-105	

Calais References

Hemenway, Abby Maria, Vermont Historical Gazetteer, Montpelier: Vermont Watchman and State Journal Press, 1882, Vol. IV, pp 127-173.

Hewitt, Arthur Wentworth, The Old Brick Manse, Harper & Row, New York, 1966.

Kelton, Lovel, Diaries and Journal (copy at VHS library)

Kent, Dorman B.F. History of Calais Vermont. 1875 manuscript.

Kent, Dorman B.F. History of Calais, The Vermonter; White River Junction: Charles R. Cummings, 1914, p. 163-172, 191-201.

The Vermonter, White River Junction: Charles R. Cummings, 1914 p.171.

Maps

Beer's Atlas, 1873

Walling Wall Map, 1858

Interviews

Elbridge, Toby - Adamant

Rachel Dwinell Rose

Neal Converse

Greg Belcher

Kristina Bielenberg

Elizabeth Kent Gay

Olivia Gay

Listed on State Register

VT ACHP

Date: 12/15/89

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-41

NEGATIVE FILE NUMBER:

79-A-106 (8& 9)

UTM REFERENCES:

Zone/Easting/Northing

18/702900/4919725

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Camolli Summer House

ORIGINAL FORMAL NAME:

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.#10, 1/2 mile
west of intersection with T.H.12.

COMMON NAME:

FUNCTIONAL TYPE: Dwelling

OWNER: Rigo Comolli

ADDRESS: RFD
E. Calais, 05650

ACCESSIBILITY TO PUBLIC:
Yes No Restricted

LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 30x23

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

Winter address
21 Merchant
Barre, VT

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has corner boards and molded cornices with returns. The front door has a granite sill and modern steps of granite (Mr. Comolli is a granite manufacturer). The gargoyles on the sides of the steps came from a Connecticut church. The central entrance has a six panel door with 2/3 sidelights, fluted pilasters, and an entablature head.

An enclosed porch runs along the east side of the house.

RELATED STRUCTURES: (Describe)

Small garage.


STATEMENT OF SIGNIFICANCE:

This house was built when the road was a Boston to Montreal post road. It retains its original interior and exterior details which make it a fine example of vernacular Greek Revival architecture. Its shallow roof pitch and central (now stove) chimney are Cape features and indicate that the house was probably an early Greek Revival structure which retained the earlier house type design, but was embellished with ornament from the emerging "modern" Greek Revival style.

REFERENCES:

Owner.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Gardens

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



29-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Comolli House, 1205-41
79-A-106 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	End of T.H.13, .6 mile west of T.H.12.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Adeline Altman
ADDRESS:	Box 51 East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon Horizontal plank
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½ plus attic

Number of Bays: 5x2 Entrance Location: Central eave

Approximate Dimensions: 34x34

SURVEY NUMBER:

1205-42

NEGATIVE FILE NUMBER:

79-A-106 (10 & 11)

UTM REFERENCES:

Zone/Easting/Northing

18/702750/4919000

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Altman House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: "

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

Ormsbee

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1840

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The windows are 6/6 sash with wooden lintels and sills set into brick walls. The front door is an eight panel door with 3/4 sidelights and granite lintel and sill. The molded cornice and frieze return on the gable ends Brick Classic Cottage
The interior has four panel doors with brown china or wooden knobs. Rooms have chair rails. Brass turn screw hardware similar to that in Murphy, fair and Kent Museum was used.

RELATED STRUCTURES: (Describe)


Shed.

STATEMENT OF SIGNIFICANCE:

The brick for this house came from the North Calais brick works. It is one of a small number of brick farmhouses which were built in the first half of the 19th century in Calais. It is a good example of a brick Classic Cottage type.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Gardens

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Altman House, 1205-42
79-A-106 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.1, 1/4 mile North of North Calais
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	George & Helen Laing
ADDRESS:	13 Allerton Ave. Brattleboro, VT 05301
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4x2 & wing Entrance Location: Off center, front

Approximate Dimensions: 28x16 & wing

SURVEY NUMBER:

1205-43

NEGATIVE FILE NUMBER:

79-A-106 (13 & 14)

UTM REFERENCES:

Zone/Easting/Northing

18/703700/4918450

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Laing House

ORIGINAL FORMAL NAME:

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: vernacular

DATE BUILT:

c.1850

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This three quarter house has corner boards, simple cornice with returns and plain fascia. The combination of high kneewall and shallow roof pitch is unusual. The off-center door is unadorned.

The recessed side wing has a central carriage bay opening which has been partially infilled with a porch wall. The wing has two on-ridge chimneys. Sash is mainly 1/1, with some 12/12 sash in the wing.

RELATED STRUCTURES: (Describe)


A clapboarded 1½-story carriage and horse barn with irregular fenestration and several appendages has been adapted for garage use.

STATEMENT OF SIGNIFICANCE:

This house is a good example of a vernacular three-quarter house type which was used more frequently in Calais than in surrounding towns in the mid 19th century.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land
- Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

View of Mirror Lake

RECORDED BY:
Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-7-106

Vt. Div- for Historic Preservation
Washington County Calais 6/79
Laing House, 1205-43
79-A-106 Betsy Bouton



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Laing House, 1205-43
79-A-106 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.1, 1 mile North of N. Calais (near Woodbury town line).
COMMON NAME:	The Old Foster Homestead
FUNCTIONAL TYPE:	Dwelling
OWNER:	Forest Davis & Pris. Backman
ADDRESS:	East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: Central eave

Approximate Dimensions: 28x36 plus e11

SURVEY NUMBER:

1205-44

NEGATIVE FILE NUMBER:

79-A-104 (5-7)

UTM REFERENCES:

Zone/Easting/Northing

18/704550/4919540

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Backman House

ORIGINAL FORMAL NAME:

PRESENT USE: Two-family dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1840

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The brick portion of this house is composed of brick veneer which is fastened to its backing with anchor bolts (iron spikes) placed in ten course intervals. Windows of 6/6 sash have granite lintels and sills. The front door has a wide granite surround, sill and three steps. The door has eight panels, a brown china knob and 3/4 sidelights. The full entablature returns on the gable ends. Two shed dormers with paired windows protrude from the front roof slope. Chimney is new. The large wooden ell has a 4-bay front porch with turned posts and brackets.

The interior of the brick portion retains original carved window and door surrounds in the front parlor. The original wallpaper remains in the front hall.

RELATED STRUCTURES: (Describe)

1935 Barn
Machinery Shed


STATEMENT OF SIGNIFICANCE:

This handsome Greek Revival farmhouse is one of the few remaining brick structures in Calais which date from the mid 19th century. The brick and granite represent the use of local building materials to form a masonry version of the traditional wooden dwelling. The method of securing the brick veneer to the frame with partially exposed iron bolts is unusual.

REFERENCES:

George Foster diary is in possession of Forest Davis.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land
- Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential
- Commercial
- Agricultural
- Industrial
- Roadside Strip Development
- Other:

Maple-lined road.

RECORDED BY:

Betsy Bouton
ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Old Foster Homestead/Bachman House
1205-44
79-A-104

Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.#1, 1 mile north of N. Calais.
COMMON NAME:	
FUNCTIONAL TYPE:	
OWNER:	Pris. Backman
ADDRESS:	RD East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System Fieldstone

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: Central eave

Approximate Dimensions: 142' on road

SURVEY NUMBER: 1205-45
NEGATIVE FILE NUMBER: 79-A-104 #8
UTM REFERENCES: Zone/Easting/Northing 18/704275/4919375
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Backman House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Greek Revival
DATE BUILT: c.1840

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has a boxed cornice with returns, plain frieze and corner boards, and a tipped window on the south end. The central recessed door is topped by a simple cornice and frieze. Sash is 6/6, except in the paired windows of the gabled wall dormers which now rise through the cornice on the front facade; the dormer windows have 2/2 sash.

Attached to the south end of the main block is a series of gable-roofed wing. The one closet to the house has a recessed porch. Beyond are attached barns and a wood shed.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This house and its connecting sheds and barn is an excellent example of continuous architecture which enabled the resident farmer to reach his barn without going outside. Except for the gabled wall dormers, the house retains its original Greek Revival appearance. It is situated on a dirt road lined with old maple trees, contributing to the strong sense of the past which the structure evokes.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Bachman House, 1205-45
79-A-104 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	South side of T.H.46 between its intersections with T.H.50 and T.H.60.
COMMON NAME:	The Old Short School
FUNCTIONAL TYPE:	School
OWNER:	Neal Converse
ADDRESS:	RFD 2 Plainfield, VT
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other: Rafters 23" between
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1

Number of Bays: 2x4

Approximate Dimensions: 28x32

Entrance Location: Left and right front

SURVEY NUMBER:

1205-46

NEGATIVE FILE NUMBER:

79-A-98 #19

UTM REFERENCES:

Zone/Easting/Northing

18/701625/4911350

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Converse House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: School

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

1833

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This building has cornerboards, a boxed cornice with returns and a plain frieze. The gable end has a triangular, louvred opening in the tympanum. The two doors have flush surrounds with lip-molded lintels; they served as separate boys' and girls' entrances to the school. There are four windows evenly spaced along the north wall. A fixed four-light window now occupies the space between the front doors.

A modern shed is attached to the south side of the structure.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This one room school is typical of those built in the first half of the 19th century at crossroads locations to serve area children. This school served generations of the Slayton, Short and Converse families.


REFERENCES:

Neal Converse

MAP: (Indicate North in Circle)



CONVERSE ROAD (T.H. 46)



1205-49

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-798

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Old Short School/Converse House,
1205-46
79-A-98 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER: 1205-47

NEGATIVE FILE NUMBER:
 79-A-120 #2 82-A-325

UTM REFERENCES:
 Zone/Easting/Northing
 18/702150/4910925

U.S.G.S. QUAD. MAP:
 Plainfield Quad 15' series

PRESENT FORMAL NAME:
 Hersey House

ORIGINAL FORMAL NAME:
 Old Shortt Homestead

PRESENT USE: Unoccupied

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:
 Unknown

BUILDER/CONTRACTOR:
 Unknown

PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor

STYLE: Vernacular

DATE BUILT:
 c. 1825

COUNTY: Washington

TOWN: Calais

LOCATION: North side of Town Highway
 46, 1 mile West of Vt. Rt. 14.

COMMON NAME:
 Neal Converse Farmstead

FUNCTIONAL TYPE: Dwelling

OWNER: Harold & Gloria Hersey

ADDRESS: RFD
 Plainfield, Vermont

ACCESSIBILITY TO PUBLIC:
 Yes No Restricted

LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other: Rafter
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5 x 4

Approximate Dimensions: 38 x 28

Entrance Location: Central Eave

THREAT TO STRUCTURE:
 No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:
 Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Plain gabled block, transitional Cape/Classic Cottage. Moderate kneewall open box cornice with no returns, cornerboards, sculpted end bargeboards (later addition). Windows (2/2) and doors plainly trimmed. Deteriorated twin stove chimneys in the center of the ridge.

RELATED STRUCTURES: (Describe)

1. Detached small woodframe gabled late 19th century house. It is within very close proximity to the main house. Clapboarded, wood shingle roof, trimmed with returning box cornice, cornerboards. Porch east facade shed roof, square posts, balustrade. Burned by fire department, 1983.

~~STATEMENT OF SIGNIFICANCE:~~
RELATED STRUCTURES: (DESCRIBE)

2. Clapboarded woodframe barn c. 1890. Low pitch gable roof. Open eaves, wide frieze board. There is a square cupola with louvered vents and a pyramidal roof.
3. Open tractor shed, shed roof, deteriorated.
4. Small gabled garage, wood shingles, large swinging doors on the gable end.
5. Small gabled garage, wood shingles, large swinging doors on the gable end.


STATEMENT OF SIGNIFICANCE:

This plain house has a relatively early form and massing with few stylistic details. The outbuildings post-date the house.

REFERENCES:

Neal Converse

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-47

#1

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Hershey House 1, 1205-47 N
82-A-325 Gina Campoli



79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Short/Converse/Hersey House, 1205-47
79-A-120 Betsy Bouton



1205-47
#2

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Hershey Barn 2, 1205-47 W
82-A-325 Gina Campoli

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of TH 50, 1/2 mile north of TH 46.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100 % Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

SURVEY NUMBER:	1205-48
NEGATIVE FILE NUMBER(S):	79-A-52, 80-A-30
UTM REFERENCES:	Zone/Easting/Northing A 18/702600/4911750 B C D
U.S.G.S. QUAD. MAP:	Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY	
COMMON NAME:	Flora George Farm
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	Slayton Farm
TYPE OF COMPLEX:	
TYPES OF STRUCTURES:	Dwelling and Farm
PRESENT USE:	
ORIGINAL USE:	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>


STATEMENT OF SIGNIFICANCE:

This property was originally settled by a member of the Slayton family who came from Massachusetts in the 1790's. It remained in the family for four generations. The original cabin was located across the road from the present house. The farm remained active until the late 1970's and it retains its mid 19th century barns and dwelling.

The house originally had a central chimney and oven. The front door is made from butternut wood; the parlor had elaborate moldings and decorative woodwork.

THREAT TO STRUCTURES: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



TOWN HIGHWAY 50

SHORTT
CEMETERY

BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Flora George as per the deeds recorded in the office of the town clerk.

REFERENCES:

Owner, Flora George

RECORDED BY:
Betsy Bouton

ORGANIZATION:
Vermont Div. for Historic Preserv

DATE RECORDED:
May 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1850	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-52 #3
COMMON NAME:		OWNER: Flora George
DESCRIPTION: This 1½ story, 5 x 2 bay house with large central cross gable has a granite foundation and post and beam construction. Some of its typical Greek Revival style characteristics are panelled corner pilasters, peaked window heads and molded cornice with returns and frieze. The central recessed door has 4/5 sidelights flanked by panelled pilasters and is capped by a pedimented head. The ell has triangular dormers and a recessed porch. The main block is similar in detail to the Maciejowski House (#1205-49), suggesting that they may have been constructed by the same builder.		
MAP NUMBER: 2	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 79-A-52 #4
COMMON NAME:		OWNER: Flora George
DESCRIPTION: This barn is 92 feet long. It was formed in the late 19th century when two 30' x 40' foot barns were joined by a center section and topped by a ventilator cupola. A milk house and sawdust shed were 20th century additions.		
MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Shed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION: Small, storage shed		
MAP NUMBER: 4	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Ash house		NEGATIVE FILE NUMBER: 80-A-30
COMMON NAME:		OWNER:
DESCRIPTION: This small house is used to store ashes until they can be used on the garden for fertilizer. This may have been originally used to smoke meat. A similar structure is in the rear of Frank Ward's house (survey #73).		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 5	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

The Short cemetery is an old one with a relationship to this house.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:



79-47-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Slayton-George Farm, 1205-48 N
79-A-52 Betsy Bouton



1205-48

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Flora George Farm, 1205-48 N
82-A-325 Gina Campoli



79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Slayton-George Farm, 1205-48 W
79-A-52 Betsy Bouton



80-A-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
George smokehouse #4 1205-48 S
80-A-30 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1985

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-49

NEGATIVE FILE NUMBER:

79-A-98 #20

UTM REFERENCES:

Zone/Easting/Northing

18/701700/4910375

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Maciejowski House

ORIGINAL FORMAL NAME:

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.60, 1/4 mile south of T.H.46 (Converse Rd.)

COMMON NAME:

FUNCTIONAL TYPE: Dwelling

OWNER: John & Virginia Maciejowski

ADDRESS: RFD, Plainfield

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
 Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1850

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other:

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 32x22

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This Classic Cottage has a tipped window, and full entablature with returns. Greek Revival style details include wide paneled pilasters on the corners and door surround. The door has 4/5 sidelights. Window heads are peaked. Sash is now 2/2. Central chimney. Attached to the south end of the main block is a clapboarded wing with recessed porch and a barn/shed with rectangular bay openings.

RELATED STRUCTURES: (Describe)

Small workshop.

STATEMENT OF SIGNIFICANCE:

This house is a good example of a mid 19th century Greek Revival style farmhouse. Its details and continuous architecture plan have been well preserved. In 1858, the house was owned by the Bennett family. Its detail is strikingly similar to that of the Slayton Farm (1205-48), suggesting that the two houses may have been constructed by the same builder.


REFERENCES:

Walling Map.

MAP: (Indicate North in Circle)



1205-49




WORKSHOP



1/4 MILE TO
T.H. 46
(CONVERSE
ROAD)

TOWN HIGHWAY 60

STONE
FOUNDATIONS



SURROUNDING ENVIRONMENT:

- Open Land
 - Woodland
 - Scattered Buildings
 - Moderately Built Up
 - Densely Built Up
 - Residential Commercial
 - Agricultural Industrial
 - Roadside Strip Development
 - Other:
- Complex of stone foundation walls across road from house.

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Maciejowski House, 1205-49
79-A-98 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1988

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: East side of T.H.60, 3/4 mile south of T.H.46.
 COMMON NAME:
 FUNCTIONAL TYPE: Dwelling
 OWNER: Dorothy Lyman & LanHui Hsieh
 ADDRESS: RFD, Plainfield
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

SURVEY NUMBER:
1205-50
 NEGATIVE FILE NUMBER:
79-A-98 #21
 UTM REFERENCES:
Zone/Easting/Northing
18/701925/4910225
 U.S.G.S. QUAD. MAP:
Plainfield Quad., 15' Series
 PRESENT FORMAL NAME:
Lyman/Hsieh House
 ORIGINAL FORMAL NAME:
 PRESENT USE: Dwelling
 ORIGINAL USE: Dwelling
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Vernacular Greek Revival
 DATE BUILT: c.1850

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other: Greenhouse
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 3x3 Entrance Location: Right front
 Approximate Dimensions: 22x36 & wing

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Gable-front house with wide corner boards, molded cornice with returns, and plain fascia on eaves elevations. The sidehall door is slightly recessed in a wide flushboard surround, and has 3/4 sidelights. A louvred triangular vent (with small window) is located in the tympanum. Sash is 2/2. A shed-roofed dormer protrudes from the south roof slope.

Attached to the rear of the main block is a gabled wing with gabled dormer on the south roof slope and an attached greenhouse. Behind it is an attached shed.

RELATED STRUCTURES: (Describe)


Small barn with appendages, including milkhouse.

STATEMENT OF SIGNIFICANCE:

This temple front house with sidehall plan is one of a small number (see #4, 16, 23) of this type which remain in Calais. Like the others, it has Greek Revival style characteristics. This one has wide corner boards representing pilasters and a recessed porch typical of the style.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton
ORGANIZATION:

Vt. Div. for Historic Preservation
DATE RECORDED:

May 1979



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Lyman/Hsieh House, 1205-50
79-A-98 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of Vt.#14, 1/6 mile north of T.H.38 & 46 intersection
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Bruce Cliche
ADDRESS:	North Montpelier
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 5x4

Approximate Dimensions: 30x36

Entrance Location: central eave & side of gable end.

SURVEY NUMBER:

1205-51

NEGATIVE FILE NUMBER:

79-A-98 (10-12)

UTM REFERENCES:

Zone/Easting/Northing

18/703825/4910875

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Cliche House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular Federal

DATE BUILT:

c.1810

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Structure was built into the slope of the hill. Doors have granite sills and semi-elliptical fan lights. Windows have 2/2 sash and granite sills. Gable roof has cornice with returns and molded raking eaves. A wooden shed/garage forms an ell with the brick section of the house; it has a rectangular bay opening.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This is one of the few brick houses in Calais which were built in the early 19th century. Its construction was adapted to fit the landscape, and it is a good example of vernacular Federal design.

REFERENCES:

MAP: (Indicate North in Circle)



1/6 MILE TO
T.H. 46 AND
T.H. 38



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Cliche House, 1205-51
79-A-98 Betsy Bouton



79-~~A~~-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Cliche House, 1205-51
79-A-98 Betsy Bouton

Listed on State Register

VT ACHP

Date: 2/10/88

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of Rt.14, 3/4 mile north of intersection with T.H.38 & 46.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	
Excellent	% Good 100%
Fair	% Poor %
LEVEL OF SIGNIFICANCE:	
Local	<input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

SURVEY NUMBER: 1205-52
NEGATIVE FILE NUMBER(S): 79-A-98
UTM REFERENCES: Zone/Easting/Northing A 18/703800/4911425 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Legare Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Agricultural
TYPES OF STRUCTURES: Dwelling & Farm
PRESENT USE: Agricultural
ORIGINAL USE: "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Eaton Family
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

STATEMENT OF SIGNIFICANCE:

This farm complex is located on a prominent site on Vermont Route 14.



Although the brick farmhouse may have been first constructed in the early 19th century, its present appearance dates from c.1860. If an earlier structure was reworked at that time, the roof was probably raised substantially during the remodeling; the proportions of the brick block are mid-19th century Greek Revival. The Greek Revival appearance of the house is enhanced by the wooden cross gables supported on square paneled columns which match the pilasters that frame the corners of the main block and flank the door.

It is one of the finest Greek Revival houses in Calais.

THREAT TO STRUCTURES:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/>
Development <input type="checkbox"/> Deterioration <input type="checkbox"/>
Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/>
Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Merrill Legare as per the deeds recorded in office of the town clerk.

REFERENCES:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input checked="" type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1820,1866	SURVEY NUMBER: 1205-52
FUNCTIONAL TYPE: Farmhouse	NEGATIVE FILE NUMBER: 79-A-98	
COMMON NAME:	OWNER: Merrill Legare	
DESCRIPTION: A 1½-story brick house of 7 course American bond with granite foundation and sills. It is about 34' square with wooden cross gables which project to cover a front entrance porch with four square columns. Greek Revival details include paneled pilasters and wide frieze. The front door has 2/3 sidelights and paneled reveals. The cornice has brackets with pendants; the brackets may have been added in the 1870's. Interior originally had three corner fireplaces. One is still useable.		

MAP NUMBER: 2	DATE BUILT: c.1860	SURVEY NUMBER: 1205-52
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 79-A-98	
COMMON NAME:	OWNER: Merrill Legare	
DESCRIPTION: A large gable roof barn with vertical board siding over hewn beams. A bridge to second floor is gone. A large shed has been added to the north and a milk house on the south side.		

MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION: Modern garage.		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Legare Farm, 1205-52
70-A-98 Betsy Bouton



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Legare Farm, 1205-52

79-A-98

Betsy Bouton

Listed on State Register
VT ACHP 12/15/1989
Date:

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of Vt. Route 14, north of intersection with Pekin Brook Rd. (T.H.3)
COMMON NAME:	Clough Place
FUNCTIONAL TYPE:	Dwelling
OWNER:	Joan Pelton
ADDRESS:	Waterbury, VT 05676 Box 82, RD 2
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 & wing Entrance Location: Central eave

Approximate Dimensions: 38x27

SURVEY NUMBER:

1205-53

NEGATIVE FILE NUMBER:

79-A-98

UTM REFERENCES:

Zone/Easting/Northing

18/703550/4911975

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

Pelton House

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

Eaton family

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1830

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: This Classic Cottage has wide corner boards and an eave board resting on top of windows. Most windows have 2/2 sash except the tipped window and right wing window which have 12/12 sash. A gabled dormer on the wing has one 8/12 window. The front door has 2/3 sidelights. The transom is covered. The wing porch has one hexagonal post.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This dwelling is on property first settled by the Eaton family in 1816. It has undergone little alteration since it was constructed c.1830.

Dorman Bridgeman Eaton, a lawyer, moved to NYC in 1850. He was active in Civil Service reform.

REFERENCES:

Hemenway, George Clough
p.160

MAP: (Indicate North in Circle)



1205-53

VERMONT ROUTE 14

PEKIN BROOK ROAD (T.H. 3)

SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Eaton/Clough/Pelton House, 1205-53
79-A-98 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	North side of T.H.36 just east of T.H.3.
COMMON NAME:	The Pekin School
FUNCTIONAL TYPE:	School
OWNER:	Dwight & Barbara Weller
ADDRESS:	Plainfield, RFD
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: Irregular

Approximate Dimensions: 24x38

Entrance Location: Left front

SURVEY NUMBER:

1205-54

NEGATIVE FILE NUMBER:

79-A-52

UTM REFERENCES:

Zone/Easting/Northing

18/702450/4913200

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Weller House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: School

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1850

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The front of this building has a bank of three large 12/12 windows and a small modern window in the gable. The roof has boxed eaves and returns. The front entrance is covered by a braced gable hood. A shed extension contains an open porch.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:


Pekin was an important agricultural section of Calais so named because Pekin wheat was grown here. The one room school provided an education for the farm children in this part of town and has associations for many Calais residents who went there to school.

The school is noted on the Walling Map of 1858, and in the 1870's served School District No.14.

REFERENCES:

1858 Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-#-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Pekin School/Weller House, 1205-54
79-A-52 N Betsy Bouton

Listed in State Register

VT ACHP

Date:

12/13/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-55

NEGATIVE FILE NUMBER:

79-A-104 #18

UTM REFERENCES:

Zone/Easting/Northing

18/702975/4913225

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Bloom House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1830

COUNTY: Washington
TOWN: Calais
LOCATION: South side of T.H.36, the Peck Hill Rd., 3/4 mile east of T.H.3.
COMMON NAME:
FUNCTIONAL TYPE: Dwelling
OWNER: Edith Bloom
ADDRESS: East Calais
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System Fieldstone concrete

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other: Rafter frame
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2
Number of Bays: 5x2
Approximate Dimensions: 38x22
Entrance Location: Central eave

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: This vernacular Cape type house has no kneewall and a shallow roof pitch. The front door has a transom light. Windows have 2/2 sash. Roof has boxed eaves and returns.

The chimney is new.

The interior of the house retains some early features: old mantel, pegged cellar stairs, and four panel doors.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This house is typical of the farm dwellings built in Vermont in the early part of the 19th century. It retains most of its original exterior appearance. In 1858, this house was the home of J.P. Laird. In the 1870's, it was owned by C. Short.

REFERENCES:

Owner
1858 Walling Map, Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Grown up farm land
- Barn foundation

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-~~7~~-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Bloom House, 1205-55
79-A-104 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: West side of T.H.33 (Converse Rd.) just north of T.H.3.
 COMMON NAME:
 FUNCTIONAL TYPE: Dwelling
 OWNER: Alice Converse
 ADDRESS: RFD 2, Plainfield
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 5x2
 Approximate Dimensions: _____

SURVEY NUMBER:
 1205-56
 NEGATIVE FILE NUMBER:
 79-A-52
 UTM REFERENCES:
 Zone/Easting/Northing
 18/702000/4913800
 U.S.G.S. QUAD. MAP:
 Plainfield Quad., 15' Series
 PRESENT FORMAL NAME:
 Converse House
 ORIGINAL FORMAL NAME:
 Slayton House
 PRESENT USE: Dwelling
 ORIGINAL USE: Dwelling
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 Built by a Slayton according to owner
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Greek Revival
 DATE BUILT: c.1850

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house is rich in late Greek Revival style details. It has corner pilasters, a full entablature with returns, and a central entrance with a recessed door with 5/6 sidelights set in a surround composed of paneled pilasters and a fully pedimented head. Window heads are peaked. The wing roof extends to form a porch roof. Shed dormers have been inserted in the roof of the main mass and wing. A modern porch has been added to the rear.

RELATED STRUCTURES: (Describe)

A cluster of 19th century barns and other farm buildings are adjacent to the farmstead.

STATEMENT OF SIGNIFICANCE:


This farmhouse is a good example of a 1½-story house with Greek Revival style details.

This farm property is the site of an early mill to grind the Pekin wheat which was grown in this valley. Several millstones have been found. One is now used as a grave marker in the Robinson Cemetery.

REFERENCES:

Owner - Alice Converse

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-52

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Slayton-Converse House, 1205-56 N
79-A-52 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.33, just north of T.H.3.
COMMON NAME:	Old Lilley Farm
FUNCTIONAL TYPE:	Dwelling
OWNER:	Wayne & Ellen Tuller
ADDRESS:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon Horizontal Plank
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other: wing
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 & wing Entrance Location: central eave

Approximate Dimensions: 40x30 plus wing

SURVEY NUMBER:	1205-57
NEGATIVE FILE NUMBER:	79-A-105 #4, 79-A-106 #3
UTM REFERENCES:	Zone/Easting/Northing 18/702100/4913900
U.S.G.S. QUAD. MAP:	Plainfield Quad. 15' Series
PRESENT FORMAL NAME:	Tuller House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Dwelling
ORIGINAL USE:	Dwelling
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular Gothic Revival
DATE BUILT:	c.1860

THREAT TO STRUCTURE:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

In form, this house is a Classic Cottage, but its detail is vernacular Gothic Revival. The front door has lancet arches which were originally filled with stained glass. The knob is of silvered glass. A label drip molding around the door opening and lancet arch patterns on the corner pilasters are other details indicative of the Gothic Revival style; the brackets on the door head may have been added later in the 1870's. A deep entablature runs under the eaves, broken by a shed-roofed wall dormer on the right front.

The recessed wing has similar entablature detail, two shed-roofed wall dormers on the front roof slope, a large rectangular opening on the end of the wing, and a later porch infilling the corner of the wing and the main block.

RELATED STRUCTURES: (Describe)

Large modern barn.


STATEMENT OF SIGNIFICANCE:

This house is one of the few in Calais which have Gothic Revival style details. The house's combination of the Classic Cottage form with Gothic Revival detailing is quite unusual. The horizontal plank construction (see 1205-39 #16) was normally used in conjunction with saw mill operation. (A saw mill is shown on the Walling Map of 1858 on the nearby brook.)

REFERENCES:

Owners.

MAP: (Indicate North in Circle)



APPROX. 1/4 MILE TO T.H. 3 ↓

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other: Stone foundations from old barn.

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Lilley-Tuller House, 1205-57
79-A-106 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-58

NEGATIVE FILE NUMBER:

79-A-105 #3

UTM REFERENCES:

Zone/Easting/Northing

18/702100/4914400

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular

DATE BUILT:

c.1796 (possibly oldest in Calais)

COUNTY: Washington

TOWN: Calais

LOCATION: West side of T.H.33, 1 mile north of T.H.3.

COMMON NAME:

The Jacks House

FUNCTIONAL TYPE: Dwelling

OWNER: Charles & Dorothy Woodard

ADDRESS: RD 2

Plainfield

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

GENERAL DESCRIPTION:

Structural System Fieldstone

1. Foundation: Stone Brick Concrete Concrete Block

2. Wall Structure

a. Wood Frame: Post & Beam Balloon

b. Load Bearing Masonry: Brick Stone Concrete

Concrete Block

c. Iron d. Steel e. Other:

3. Wall Covering: Clapboard Board & Batten Wood Shingle

Shiplap Novelty Asbestos Shingle Sheet Metal

Aluminum Asphalt Shingle Brick Veneer Stone Veneer

Bonding Pattern: Other:

4. Roof Structure

a. Truss: Wood Iron Steel Concrete

b. Other: Rafter

5. Roof Covering: Slate Wood Shingle Asphalt Shingle

Sheet Metal Built Up Rolled Tile Other:

6. Engineering Structure:

7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys

Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel

Jerkinhead Saw Tooth With Monitor With Bellcast

With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 36x28

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Alteration Other:

South wall foundation giving way

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

With massive (renovated) central chimney, cropped and flush eaves, and a shallow roof slope, this house is typical of Cape design. The central entrance has a 6-pane transom light and Christian cross door. Sash is 12/12. Windows on the front elevation are located directly under the eaves. Windows on the sides have simple casings with molded heads. A door with similar surround is located off center on the east gable end. Two small 9/6 windows are found in the east gable.

The central chimney has a cooking fireplace and two others. There is a half cellar. A closet door has a pewter knob.

RELATED STRUCTURES: (Describe)

Old barn, 50x40, has vertical sheathing.

STATEMENT OF SIGNIFICANCE:


This is probably the oldest house in the town of Calais. Its condition is excellent with many architectural details: four panel doors with latches, wooden paneling and ceiling on interior, transom lights and Carpenter box lock (see Donald Fair House #1205-35) on exterior door. The extent of 20th century reworking is uncertain.

According to tradition, the smoke house room behind the three fireplaces in the central chimney was used to hide from Indians. In the mid 19th century, the house was owned by the Ainsworth family.

REFERENCES:

- Owners
- Walling Map
- Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
 - Scattered Buildings
 - Moderately Built Up
 - Densely Built Up
 - Residential Commercial
 - Agricultural Industrial
 - Roadside Strip Development
 - Other:
- Grown up agricultural

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Jacks/Woodard House, 1205-58
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of Vt. Rt.14, 3/4 mile north of intersection with T.H.3.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Elbirdse Tucker
ADDRESS:	E. Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5

Approximate Dimensions: _____

Entrance Location: Central eave

SURVEY NUMBER:

1205-59

NEGATIVE FILE NUMBER:

79-A-120 #3

UTM REFERENCES:

Zone/Easting/Northing

18/703800/4913250

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

Tucker House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1860

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has a deep entablature with returns and paneled corner pilasters. The central door of this house has five panels and white china knob. The surround originally had a pedimented head, now straight. The 5/6 sidelights, paneled pilasters, and paneled reveals remain. The 2/2 windows have peaked heads. There is a tipped window on the south gable end. The south wing has a gabled dormer with 1/1 window, recessed porch, and corner pilasters. The north wing is similar. An off-center chimney on the front roof slope of the main block replaced 2 interior end chimneys.

RELATED STRUCTURES: (Describe)


Attached garage and barn.

STATEMENT OF SIGNIFICANCE:

This house was built as a two family house with matching wings, making it an unusual example of Classic Cottage design. Its Greek Revival detailing has been well-preserved.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton
ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Tucker House, 1205-59
79-A-120 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1987

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of Vt.#14, 1 mile north of Pekin Brook Rd. (T.H.3)
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Andrew & Eilleen Thurston
ADDRESS:	E. Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 4x2

Approximate Dimensions: 18x25

Entrance Location: eave-off center

SURVEY NUMBER:	1205-60
NEGATIVE FILE NUMBER:	79-A-98 #16
UTM REFERENCES:	Zone/Easting/Northing 18/703750/4913600
U.S.G.S. QUAD. MAP:	Plainfield Quad. 15' Series
PRESENT FORMAL NAME:	Thurston House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Dwelling
ORIGINAL USE:	Dwelling
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Vernacular
DATE BUILT:	c.1840

THREAT TO STRUCTURE:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This modest 3/4 house with porch in the rear has few decorative details. Its three-quarter form is ornamented with peaked window and door heads and a later decorative barge board on the north gable end. Sash is now 1/1, and there is a central on-ridge chimney.

RELATED STRUCTURES: (Describe)


STATEMENT OF SIGNIFICANCE:

This structure was moved from Kent's Corner. It is a good example of a vernacular Greek Revival 3/4 house. Calais has a substantial number of houses of this type built in the first half of the 19th century.

REFERENCES:

Harry Graham

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:


Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-98

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Thurston House, 1205-60
79-A-98 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1985

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.36, 1/4 mile south of Vt.14.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:


The outstanding feature of this farm complex is the three story barn, reportedly moved from Woodbury by oxen. The house is a typical mid 19th century dwelling with attached sheds. It has an Italianate style front door with a hood.

SURVEY NUMBER:	1205-61
NEGATIVE FILE NUMBER(S):	79-A-104 (21), 79-A105 (1)
UTM REFERENCES:	Zone/Easting/Northing A18/703350/4913800
	B C D
U.S.G.S. QUAD. MAP:	Plainfield Quad, 15' Series
COMPLEX INFORMATION ONLY	
COMMON NAME:	Old Peck Place
PRESENT FORMAL NAME:	Gordon & Nancy Knox
ORIGINAL FORMAL NAME:	
TYPE OF COMPLEX:	Farm
TYPES OF STRUCTURES:	Dwelling & Barn
PRESENT USE:	
ORIGINAL USE:	Farm
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

THREAT TO STRUCTURES:	No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:
-----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
------------------	-------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Gordon and Nancy Knox as per the deeds recorded in office of the Calais town clerk.

REFERENCES:

Harry Graham

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input checked="" type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1850	SURVEY NUMBER: 1205-61
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-104 #20A	
COMMON NAME: The Old Peck Place	OWNER: Gordon & Nancy Knox	
DESCRIPTION: This is a 5x2 bay, 1½-story house with an ell and attached sheds. The ell has a recessed porch. A modern shed dormer has been added. The central eave entrance door is double-leaf with glass panels and has an Italianate style bracketed hood which was probably an alteration to the original structure.		
MAP NUMBER: 2	DATE BUILT: c.1860	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER: 79-A-105 (1)	
COMMON NAME:	OWNER: Gordon & Nancy Knox	
DESCRIPTION: This 3-story barn is set into the slope of the hill so that a covered bridge from the road level provides access to the second story. Hay was stored in the top level so that it could be lowered to the livestock area below. Manure was removed from the first floor.		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Old Peck Place/Knox House, 1205-61
79-A-105 Betsy Bouton



79-A-104

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Old Peck Place/Knox House, 1205-61
79-A-104 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.35, 1/2 mile northwest of T.H.36.
COMMON NAME:	Fifer's Ride
FUNCTIONAL TYPE:	Dwelling
OWNER:	Anne Brassage
ADDRESS:	18 LaForge Rd. Darien, Conn.
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block 9 course
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other: Barn

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 4x1

Approximate Dimensions: 22x30 plus wing

Entrance Location: Off center eave

SURVEY NUMBER:

1205-62

NEGATIVE FILE NUMBER:

79-A-104 (19 & 20)

UTM REFERENCES:

Zone/Easting/Northing

18/702800/4914275

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15' Series

PRESENT FORMAL NAME:

Brassage House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Federal

DATE BUILT:

1820

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This 3/4 house has a molded cornice on the eaves sides which returns on the gable ends, which have nearly flush raking cornice moldings. The off-center Christian cross door is topped by a curvilinear transom light (see sketch below). (The transom is very similar to the transom over the side entrance on the Kent Tavern - #1205-1#1). The slightly recessed windows have 9/6 sash. There are now two chimneys on the main block. The slate roof has a band of lighter shingles on the front slope of the roof.

Attached to the north end of the main block is a clapboarded wing with frieze windows and two elliptically-arched carriage bay openings framed by pilasters and molded arch heads. Connected to the wing at right angles is a barn with vertical board sheathing and sliding barn doors.



RELATED STRUCTURES: (Describe)

Modern barn.

STATEMENT OF SIGNIFICANCE:

According to the owner, two brothers returned from the War of 1812 and built mirror image houses. The house on the west fell down in the 1930's. The remaining house is a very good example of an early 19th century brick farmhouse of the 3/4 type.


REFERENCES:

MAP: (Indicate North in Circle)



FOUNDATION
OF MATCHING
HOUSE

TOWN HIGHWAY 35



1/2 MILE TO
T.H. 36 ↓

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



1205-62

79-A-104

Vt. Div. for Historic Preservation
Washington Calais 5/79
Fifer's Ride-Brassage House
1205-62
79-A-104 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	Intersection of TH 4 and 5 along Vt #14, 4½ miles north of North Montpelier.
NAME OF DISTRICT:	East Calais Historic District
TYPE OF DISTRICT:	Commercial, residential
PHYSICAL CONDITION OF STRUCTURES:	Excellent 80 % Good 20 % Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	


STATEMENT OF SIGNIFICANCE:

The nucleus for the early crossroads settlement of East Calais was a dam site on the Kingsbury Branch. This site was used for a saw-mill and grist-mill prior to 1800. About 1812, Nathaniel Davis acquired the mills and property. Among the enterprises he started were mills for carding wool and dressing cloth, a triphammer shop for making scythes and hoes and a shop for the manufacture of cut-nails. The nail factory business was shortly displaced by cabinet work, clover-mill and potash. Davis started a store to serve industry workers. His daughter, Dolly married Samuel Rich of North Montpelier who took over the mills and built the Dwinell Homestead (#19) in 1836. At that time, the road east passed between this and the Jackman House (#20).

The district now consists of 32 structures: a grist mill, a Greek Revival Church, a store, a post office, a small number of houses built prior to 1850 and a greater number built after the Civil War when East Calais enjoyed a period of growth and prosperity. It retains the appearance of a mid to late 19th century village, with much of its well-detailed Greek Revival, Italianate, Gothic Revival, and Queen Vnne architecture still extant.

SURVEY NUMBER:	1205-63
NEGATIVE FILE NUMBER(S):	79-A-119 (6-21)
UTM REFERENCES:	Zone/Easting/Northing A 18/705000/4915700 B 18/705000/4915550 C 18/704800/4915250 D 18/704550/4115475
U.S.G.S. QUAD. MAP:	Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY	
COMMON NAME:	
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
TYPE OF COMPLEX:	
TYPES OF STRUCTURES:	
PRESENT USE:	
ORIGINAL USE:	
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
ACCESSIBILITY TO PUBLIC:	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Restricted <input type="checkbox"/>
THREAT TO STRUCTURES:	LOCAL ATTITUDES:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

See continuation sheet.

REFERENCES:

Hemenway, Houghton Cate, Rachel Rose

RECORDED BY:
Betsy Bouton

ORGANIZATION:
VT Div. for Historic Preservation

DATE RECORDED:
May, 1979

BOUNDARY DESCRIPTION

The boundary line of this historic district begins at a Point A on the south bank of the Kingsbury Branch at the intersection with the east boundary of the property (#16) owned by Ethel Barrows. Then the line follows said boundary line in a direction crossing Route 14 and continuing along the east property line of the Batchelder property (#17) to Point B, at the southeast corner of said property. Thence the boundary proceeds in a southwesterly direction along the rear property lines of the properties owned by Batchelder, (#17) Brechin (#18) Dwinell (#19); crossing TH 5 and continuing along the rear lot lines of the properties owned by Jackman, (#20), Isaak, (#21), Bancroft, (#22), and Sayers, (#23), Miller and Seeling, (#24), Benjamin (#25), Gray (#26) and Lamb (#27) to Point C, the southwest corner of the Lamb property (#27). From this point, the boundary follows the Lamb south property line in a northwesterly direction, crossing TH #4 and continuing along the northwesterly boundary of the property (#1) owned by Johnathan Coggeshall to the east edge of the right-of-way of Vermont Route #14, Point D. It proceeds in a northeasterly direction along said edge of said right-of-way to Point E, located at the intersection of a southerly extension of the west property line of the Gerrish property (#8). Thence the boundary proceeds in a northerly direction along said property line to Point F, at the south bank of the Kingsbury Branch. Thence it proceeds in an easterly direction along the south bank of the Kingsbury Branch to Point G, located at the intersection of a southerly extension of the west property line of the Wilbur property (#11). Thence it proceeds in a northerly direction along said extension, crossing the Kingsbury Branch, and continuing along the west property lines of the Wilbur property (#11), the Sanders property (#28) and the Bowen's Electric property (#29) to Point H, at the northwest corner of the Bowen's Electric property (#29). Thence it proceeds in an easterly direction along the north property line of said property to Point I, at the intersection of the western edge of the right-of-way of TH 5. It thence proceeds in a southeasterly direction along said edge of said right-of-way of TH 32. It thence proceeds in a northeasterly direction along said extension and said edge of said right-of-way to Point K, the northeast corner of the Recreation Center property (#30). It thence proceeds in a southerly direction along the rear (east) property lines of the Recreation Center property (#30), and the Cates properties (#31,32, and 12) crossing the Kingsbury Branch to Point L, at the intersection of the rear (north) property lines of the Clark (#14), Roy (#15), and Barrows (#16) properties to Point A, the point of beginning.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: c.1870	SURVEY NUMBER: 1205-63
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119 #9
COMMON NAME:		OWNER: Jonathan Coggeshall
DESCRIPTION:		

This is a 1½ story house with temple front, side hall plan and an ell spanned by a 20th century porch. The front door has four panels, a brown glass knob and a paneled, canted reveal. Windows with 2/2 sash have label stops with applied molding detail. Trim includes boxed cornice with return, deep frieze and architrave, and cornerboards with raised panels.

A 2½ story apartment is being built on the rear of the property.

MAP NUMBER: 2	DATE BUILT: c.1867	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119, #8
COMMON NAME:		OWNER: Chet Briggs and Karen Lane
DESCRIPTION:		

This 2½ story house, built by Ira Dwinell with a temple front side hall plan has a small ell, wing, and attached barn. The wooden detail is exceptional. The corners of the building are ornamented with wooden quoins on the first story and paneled pilasters on the second. Windows with 2/2 sash have label drops and cornice heads. The front door has a granite sill and steps. The surround has cornice head, gothic arch shaped paneled reveals and sidelights. The interior retains an ornamental staircase.

MAP NUMBER: 2A	DATE BUILT: c.1910	SURVEY NUMBER:
FUNCTIONAL TYPE: Garage/shed		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME:		OWNER: Chet Briggs and Karen Lane
DESCRIPTION:		

This plain gable front garage has swinging barn doors, 2/2 sash and a gable peak hayloft opening.

MAP NUMBER: 3	DATE BUILT: c.1870	SURVEY NUMBER: 79-A-292 #6
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME:		OWNER: Ila Fifield
DESCRIPTION:		

A small one-story cottage does not contribute to the historic district.

82-A-291

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 4 | DATE BUILT: c.1870 | SURVEY NUMBER:
 FUNCTIONAL TYPE: Residence | NEGATIVE FILE NUMBER: 82-A-292
 COMMON NAME: | OWNER: Donald and Linda Coburn

DESCRIPTION:
 This is a 3 x 3 bay, two story block-like, Italianate house with hip roof and belvedere. Trim includes a cornice with paired brackets. The windows, with 2/2 sash, have cornice window heads and paired bracket feet. The square belvedere has 2/2 windows and a cornice with paired brackets. The door has a hip roofed door hood with very elaborate heavy brackets and parted brackets under the hood.
 4A. A small, 2-bay, gable front, horse barn has been converted for use as a two car garage.

MAP NUMBER: 5 | DATE BUILT: 1850 | SURVEY NUMBER:
 FUNCTIONAL TYPE: Church | NEGATIVE FILE NUMBER: 79-A-119 #2
 COMMON NAME: The Community Church of East | OWNER:

DESCRIPTION: Calais
 This Greek Revival style church has corner pilasters and a deep entablature and three oversize (20/20) windows on each eaves side. The front has a pedimented gable with triangular louver in the tympanum. On the front facade, two entrance doors with flanking pilasters supporting cornice heads, flank a large, central, 20/20 window. A square bell tower rests on the front ridge and consists of a square base with corner pilasters, cornice and frieze, a louvered second stage with pilasters, cornice and frieze and a spire. Atop the first and second stages, corner pinnacles are joined by rails to form open balustrades; the pinnacles give the tower a Gothic appearance.

MAP NUMBER: 6 | DATE BUILT: c.1870 | SURVEY NUMBER:
 FUNCTIONAL TYPE: Store | NEGATIVE FILE NUMBER: 79-A-120
 COMMON NAME: East Calais Post Office | OWNER: David and Elaine Novalr

DESCRIPTION: P.O. Box 15, Old Saybrook, CT 06475
 A 2½ story, gable front store with two story ell, 1 story wing and attached garage. The 2 story front porch has deeply chamfered posts, staggered butt and diamond-patterned shingling and curvilinear bargeboarding between posts on the 2nd story. A polygonal window bay protrudes from the west side of the building's wing. It contains the P.O. customer area and is entered by a door off the porch. The main block's central entrance door is flanked by a large 2/2 window.

6A. A two car garage is on the property.

MAP NUMBER: 7 | DATE BUILT: c.1860 | SURVEY NUMBER:
 FUNCTIONAL TYPE: Residence | NEGATIVE FILE NUMBER: 79-A-120 #1
 COMMON NAME: | OWNER: Allen and Helen Macke

DESCRIPTION:
 This house has a temple front with side hall plan. Wide cross gables give all elevations a gable-front. Windows have peaked heads with applied curvilinear decorative detail. The front door has peaked head and deep paneled reveals. Other details are paneled corner pilasters, boxed cornice, with returns, segment of full entablature at each corner, raking fascia boards and a wood shingle roof.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 8	DATE BUILT: c.1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-119 #7	
COMMON NAME:	OWNER: Wendell and Shirley Gerrish	
DESCRIPTION:		
<p>3-bay, 1½ story gable front main block with gabled ell give this house an L-plan. A porch with circular corner spans the ell. This porch has a turned balustrade, posts and cut out valance. Left sidehall door has full sidelights, a fully pedimented head, pilasters and panelled reveals. Windows with 2/2 sash have peaked window heads and applied wooden decorative detail; window and door detail on the ell is the same.</p>		
<p>8A. There is a small, 2 level, gable-roofed, clapboarded carriage barn on the property.</p>		
MAP NUMBER: 9	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Neal and Hazel Tassie	
DESCRIPTION: This clapboarded structure consists of two primary gable front blocks joined by a flat roofed ell; shed and porch additions flank either end. The 3 bay left gable-front block is 2½ stories high, has corner pilasters and cornice returns, and has a central entrance and righthand polygonal bay on the first story. An entrance porch sheltering the left two bays continues to a set of exterior stairs which dog-legs from the left end of the porch around the corner of the building to ascend to the second floor; the porch posts are chamfered as are the posts which support the shed roof over the exterior stairs. The second floor has a full width screened porch with vertical plank porch wall.		
<p>The smaller 1½ story, 3 bay, righthand gable front block has cornerboards, an entablature with returns and a central entrance. Joining it to the larger</p>		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION: (Map number 9, continued)		
<p>main block is a recessed 3-bay, 2 story ell with a full width first floor porch. Two small 1/1 windows mark the second story.</p> <p>A shed roofed porch extends from the smaller gable-front block on the right, and two shed roofed additions extend from the left of the large main block.</p>		
MAP NUMBER: 10	DATE BUILT: 1871	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 79-A-119 #13	
COMMON NAME:	OWNER: Martha Calcagni	
DESCRIPTION:		
<p>A 1½ story house with temple front and sidehall plan, has an ell with a continuous shed dormer. Modern "colonial", gabled entrance porches have been added to main block and ell. The front door has paneled pilasters in the surround, 5/6 sidelights and deep paneled reveals. The house has a cornice with paired "S" scroll brackets with pendants, 6/6 window sash, paneled corner pilasters, an entablature with returns, and an asbestos shingled wall surface.</p>		
<p>A modern, flat-roofed garage has been added to the end of the ell.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 11	DATE BUILT: c.1830	SURVEY NUMBER: 82-A-292
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Helen Wilbur	

DESCRIPTION:

A 1½ story, woodframe, Cape-like mass over a high brick foundation. The original use of this structure next to the Kingsbury Branch was probably industrial.

MAP NUMBER: 11A	DATE BUILT: c. 1900	SURVEY NUMBER: 82-A-292
FUNCTIONAL TYPE: Shed/Garage	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Helen Wilbur	

DESCRIPTION:

This garage has a large barn door opening and a hayloft door on the gable front. It is lighted by a row of 2/2 sash. A detached shed roofed shed (#11B) is to the rear.

MAP NUMBER: 12	DATE BUILT: 1840?	SURVEY NUMBER:
FUNCTIONAL TYPE: Mill	NEGATIVE FILE NUMBER: 79-A-119 #16, & 17	
COMMON NAME: Moscow Mills	OWNER: Houghton and Lorraine Cate	

DESCRIPTION:

This three story grist mill originally used water power to grind corn and oats. Grain was hoisted to the third floor from where it traveled by shoots to lower levels where it could be ground and bagged. The building contains a small stone mill which was used for Jonny Cake meal, and a steel mill manufactured by Sprout, Waldon & Co., Muncy P.A. pat. Oct. 6, 1903, last used in the 1940's. Jones scales from Binghamton N.Y. are in the floor. At one time, belts from downstairs were operated by a diesel engine. Presently the mill is used as a grain store and contains a storeroom and office.

MAP NUMBER: 13	DATE BUILT: 1964	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Clem and Marjorie Batchelder	

DESCRIPTION:

Box 14, Plainfield

This ranch type house was built on the site of a sawmill. It does not contribute to the historic character of the district.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 14	DATE BUILT: 1939	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 83-A-409	
COMMON NAME:	OWNER: Ronald and Linda Clark	

DESCRIPTION:

Wood shingled, Bungaloid, 1½ story house. Gable end oriented towards the road. Overshot porch protects main entrance on north facade. Shed dormers also on north facade and 1 story shed roofed wing on rear. Wide eaves trimmed with a few brackets and exposed rafter tails.

MAP NUMBER: 15	DATE BUILT: 1898	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 83-A-409	
COMMON NAME:	OWNER: Ruth Roy	

DESCRIPTION:

1½ story L-plan with entrance in ell. Gable front section is trimmed with a returning cornice and 2-part frieze. 2/2 sash and c.1940 enclosed porch spanning the ell. Similar to #16 in form and massing.

MAP NUMBER: 16	DATE BUILT: c.1880	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 83-A-409	
COMMON NAME:	OWNER: Ethel Barrows	

DESCRIPTION:

1½ story L-plan with the entrance in the ell and corner of the main block. Gable front trimmed with corner pilasters, a 2 part frieze, returning cornice, cornice caps above the 2/2 sash and recessed paneled panels beneath the first story windows. An open porch with square posts and a dragonal board rail wraps around the ell. Exposed basement in rear. Similar to #15 in form and massing.

MAP NUMBER: 17	DATE BUILT: 1867	SURVEY NUMBER: 82-A-292
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 79-A-119 #14	
COMMON NAME:	OWNER: Roy and Eleanor Batchelder	

DESCRIPTION:

This quintessential Italianate structure has a 3 x 3 bay, 2 story portion with a hip roof. A long, gabled ell extends the rear. Windows have 2/2 sash and cornice window heads. The building's ornamentation includes a scroll sawn bracketed cornice and a denticulated and paneled frieze. The front and side facades have polygonal bay window. To the left of the front bay is a bracketed door hood. The hood and bays have cornices and friezes ornamented in the same manner as the roof cornice. The door has double leaves with glass panels. The west facade has a porch trimmed similarly.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 18	DATE BUILT: 1890	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119 #15
COMMON NAME:		OWNER: Russell and Albertine Brechin
DESCRIPTION:		
<p>This house was built by D.B. Dwinell. It has two stories with a flat roof, an unusual massing for its date. The wing is under renovation. The three bay front has a one story porch with turned posts and cut-out brackets. The windows have $2/2$ sash. The west facade has a two story polygonal bay window. The house has a vertical board, bracketed frieze and a vertical board band around the base of the house. There is a band of staggered but shingles between floors. A one story 2 x 1 bay porch with turned posts runs from the side bay window to the rear along the wing.</p>		
MAP NUMBER: 19	DATE BUILT: 1836	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119
COMMON NAME: The Dwinell Homestead		OWNER: Dwinell Homestead Ass. Inc.
DESCRIPTION:		
<p>This is a $2\frac{1}{2}$ story house with a five bay front. A long ell with a porch extends to the rear and for some years contained the office of the Calais town clerk, a Dwinell. The south door has six panels, a transom and $\frac{1}{2}$ length sidelights. The cornice head is denticulated and the pilasters, paneled. A polygonal porch extends around the northwest corner of the house. It has turned posts, and balustrade and sawn brackets. The corner boards are beaded. A large gable-roofed, clapboarded barn is part of the Dwinell property. It is $2\frac{1}{2}$ stories, built into a slope.</p>		
MAP NUMBER: 19A	DATE BUILT: c.1850	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 79-A-119
COMMON NAME: Dwinell Barn		OWNER: Dwinell Homestead Ass. Inc.
DESCRIPTION:		
<p></p>		
MAP NUMBER: 20	DATE BUILT: 1835	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME: Jackman House		OWNER: Charlotte Jackman
DESCRIPTION:		
<p>This $2\frac{1}{2}$ story house has a 5 bay front. The front had a six panel door with $2/3$ sidelights. A large front porch has turned posts. A central gable wall dormer has been added to the house. Exterior details include $2/2$ sash windows, boxed eaves and return and beaded corner boards. The interior has architrave moldings and chair rails.</p> <p>The Jackman property also contains a small barn with a large modern over head garage door.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 20A	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME: Jackman Barn		OWNER: Charlotte Jackman

DESCRIPTION:

MAP NUMBER: 21	DATE BUILT: c. 1850	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119
COMMON NAME:		OWNER: Luella Isaak, East Calais

DESCRIPTION:

This is a 1½ story 5 x 4 bay house with a large central front gabled dormer which extends to house a recessed porch on the upper story. The balcony porch is supported by four square columns. House has cornice with returns, deep frieze which continues on the porch dormer, and wide corner pilasters. Window sash of 6/6 and 1/1 have peaked window heads. The central front door has a denticulated pediment head and paneled reveals. The rear ell is a lower 1½ stories, and has a box cornice, frieze board, and peaked window heads.

MAP NUMBER: 22	DATE BUILT: 1879	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 79-A-119
COMMON NAME:		OWNER: Carl and Sarah Bancroft

DESCRIPTION:

This is a 1½ story house with an attached ell and carriage barn. The front facade is divided into three bays by paneled pilasters which visually support a paneled frieze. Windows and doors are framed by pilaster boards with entases under cornice moldings. The four panel doors have tall upper panels. The front door has full sidelights and paneled reveals. Corner blocks above the door have incised heart motifs. A hipped roof porch on the ell has slender, square, chamfered posts.

MAP NUMBER: 23	DATE BUILT: c. 1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Store		NEGATIVE FILE NUMBER: 79-A-119 #20
COMMON NAME: Sayer's General Store		OWNER: Willie and Wilma Sayers

DESCRIPTION:

This is a temple front, 2½ story building with a recessed 2-story porch and asbestos siding. The porch has octagonal posts. Windows with 2/2 and 6/6 sash have peaked window heads on the front facade, rectangular on the sides. A wing to the rear has a porch with turned posts and also contains garage doors. To the east side an ell and garage with false front have been added. These are now used for storage.

Beers map pictures scales in front of the store in 1873.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 24	DATE BUILT: c.1870	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Marianne Miller and Gustave See	
DESCRIPTION:		

This is a 3 x 3 bay, 2 story, Italianate style house with a gabled ell. The main hipped roof has a double bracketed entablature with paneled frieze, heavily molded architrave, applique designed to look like dentil course and a belvedere trimmed with a scaled down version of main cornice. The entire structure has a high granite foundation, aluminum siding, and ²/₂ sash. The front entrance includes a double leaf door with glass panels.

MAP NUMBER: 25	DATE BUILT: 1858	SURVEY NUMBER: 82-A-292
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Wesley and Beatrice Benjamin	
DESCRIPTION:		

This 1½ story house with an ell wing and attached horse/carriage barn has decorated bargeboards with acorn pendant and open tear drop design and is sheathed in aluminum siding. The off-center gable front door has Gothic arch paneled reveals. The glass panels of the double leaf doors repeat the design. The three bay side porch has square chamfered posts with capitals and brackets pierced with stars. Above the porch is a gabled wall dormer.

MAP NUMBER: 26	DATE BUILT: 1870	SURVEY NUMBER: 82-A-292
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER: 79-A-119 (10)	
COMMON NAME:	OWNER: Forrest Strad Gray	
DESCRIPTION:		

This is a 1½ story house with a 3 bay gable front and 4 bay ell attached to sheds and a barn/garage. ²/₂ sash windows have peaked heads. The front door has a flat-roofed entrance porch with cornice and chamfered posts. Decorative wooden detail includes boxed eaves and returns, "Marshfield Applique" between architrave and frieze boards, and pilasters "panelled" with ½ round molding. Door detail includes pointed arch panels in sidelight position flanked by pilasters with molding trim similar to the main pilasters. The barn is greatly deteriorated.

MAP NUMBER: 27	DATE BUILT: c.1875	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence	NEGATIVE FILE NUMBER: 82-A-291	
COMMON NAME:	OWNER: Marguerite Lamb	
DESCRIPTION:		

This five-bay Classic Cottage house has a three-bay entrance porch with hip roof, turned posts and sawn brackets. A side porch is similar. A barn ell with 2 carriage bay openings on the right extends to the rear. The front door has two glass panels in the four panel door. Trim is limited to corner boards, boxed eaves and an entablature with returns.

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 28	DATE BUILT: c.1820	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME:		OWNER: Seever Rogstad
DESCRIPTION:		
<p>This Cape type house, one of the oldest in the village, rests on a granite and stone foundation. It was built on the intended village green. It now has asphalt sheathing, a rear ell and attached barn. Mantels remain in the interior. The parlor mantel has a carved heart motif.</p>		
MAP NUMBER: 29	DATE BUILT: c.1840	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME:		OWNER:
DESCRIPTION:		
<p>A 5 x 3 bay 1½ story gable roofed, clapboarded house. Three bay gabled entrance vestibule now covers entry. Cornerboards</p>		
MAP NUMBER: 29A	DATE BUILT: c.1915	SURVEY NUMBER:
FUNCTIONAL TYPE: Shop/storage		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME: Bowen's Electric		OWNER: Bowen's
DESCRIPTION:		
<p>This gabled structure has a shed roofed addition on the south end, novelty siding and exposed rafter tails.</p>		
MAP NUMBER: 30	DATE BUILT: 1863	SURVEY NUMBER:
FUNCTIONAL TYPE: School/Recreation ctr.		NEGATIVE FILE NUMBER: 82-A-292
COMMON NAME: East Calais School		OWNER: Town of Calais
DESCRIPTION:		
<p>This gabled school has a belfry, wide eave boards, a 2-part frieze, a returning cornice, a louvered triangle shaped tympanum and a porch with pipe posts. The door has a fire pane transom light and a bank of 12/12 windows is on the east gable end.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 31	DATE BUILT: c.1970	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Lorraine and Houghton Cate
DESCRIPTION:		

This modern one-story cottage with gable roof does not contribute to the historic quality of the district.

MAP NUMBER: 32	DATE BUILT: c.1938	SURVEY NUMBER:
FUNCTIONAL TYPE: Residence		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Houghton and Lorraine Cate
DESCRIPTION:		

A gambrel roofed, clapboarded Colonial Revival house with a continuous shed dormer across the front.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		



#2

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Lane House,
1205-64 #2 W
82-A-291 Gina Campoli



#1

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD: 1205-63, #1,
Coggeshall
79-A-119

Betsy Bouton



#2A

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Lane Shed, 1205-64
#2A W
82-A-292 Gina Campoli



#2

79-A-119


Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD: 1205-63, #2, Briggs/
Lane
79-A-119 Betsy Bouton



#4

82-17292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Coburn House, W
1205-64 #4
82-A-292 Gina Campoli



#3

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Fifield House,
1205-64 #3 W
82-A-292 Gina Campoli



#6, #7

79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:,1205-63,#7, Macke;
#6, Post Office
79-A-120 Betsy Bouton



#5

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63, #5Community
Church
79-A-119 Betsy Bouton



#9

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Tassie Building,
1205-64 #9 N
82-A-292 Gina Campoli



#8

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD: 1205-63, #8, Gerrish
79-A-119 Betsy Bouton



#11

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Wilber House,
1205-64 #11
82-A-292

Gina Campoli^W



#10

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63,#10,Calcagni
79-A-119 Betsy Bouton



#12

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63, #Moscow
Mills #12
79-A-119 Betsy Bouton



#11A
#11B

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Wilber Barns, W
1205-64 #11A,11B
82-A-292 Gina Campoli



16
#14,15

83-409

Vt. Div. for Historic Preservation
Washington County, Calais 12/83
E. Calais HD: 1205-63 #16 N
Barrows House 83-A-409
Nancy Boone, John Dumville
Gina Campoli



14+15
#16

83-409

Vt. Div. for Historic Preservation
Washington County Calais 12/83
E. Calais HD: 1205-63, #14, 15 S
83-A-409 Nancy Boone
John Dumville, Gina Campoli



1867

#17

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63,#17
Batchelder
79-A-119 Betsy Bouton



#17

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Batchelder House,
1205-64 #7
82-A-292 Gina Campoli^S



#19

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD: 1205-63, #19, Dwinell
79-A-119 Betsy Bouton



#18

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63, #Brechin #18
79-A-119 Betsy Bouton



#20

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Jackman House, SW
1205-64 #20
82-A-292 Gina Campoli



#19

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63, #19,Dwinell
79-A-119 Betsy Bouton



#22

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63,#22,Bancroft
79-A-119 Betsy Bouton



#21

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63,#21, Isaak
79-A-119 Betsy Bouton



24
#31

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: House, 1205-64 #31
82-A-292 S Gina Campoli



#23

79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
East Calais HD:1205-63,#23,Sayer's
Store
79-A-119 Betsy Bouton



#25

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Benjamin House, SE
1205-64 #25
82-A-292 Gina Campoli



#26

79-A-119

Vt. Div. for Historic Preservation
Washington County calais 6/79
East Calais HD: 1205-63, #26, Gray
79-A-119 Betsy Bouton



#25

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Benjamin House, N
1205-63 #25
82-A-292 Gina Campoli



#26

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Gray House, detail,
1205-6³ #26 N
82-A-292 Gina Campoli



#26

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Gray House, 1205-63
#26 NE
82-A-292 Gina Campoli



#28

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Rogstad House,
1205-64 #28
82-A-292
W
Gina Campoli



#27

82-A-291

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Lamb House, E
1205-64 #27
82-A-291 Gina Campoli



#29A

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Bowen's Electric,
1205-64 #29A N
82-A-292 Gina Campoli



#29

82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: Bowen House,
1205-64 #29 N
82-A-292 Gina Campoli



#30

82A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
East Calais HD: East Calais School,
1205-64 #30 E
82-A-292 Gina Campoli

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.32, just north of East Calais Village.
COMMON NAME:	Judge Charles Dana Place
FUNCTIONAL TYPE:	Dwelling
OWNER:	Stewart Clark, Horace and
ADDRESS:	Clorinda Duke
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2½

Number of Bays: 5x3 Entrance Location: Center front

Approximate Dimensions: _____

SURVEY NUMBER:
1205-64

NEGATIVE FILE NUMBER:
79-A-120 (4)

UTM REFERENCES:
Zone/Easting/Northing

18/704725/4915775
U.S.G.S. QUAD. MAP:
Plainfield Quad., 15' Series

PRESENT FORMAL NAME:
Clark/Duke House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor

STYLE: Vernacular

DATE BUILT:
c.1830

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: _____

This 2½-story house has weatherboard siding, boxed cornice with returns, and beaded corner boards. The central front door has six panels, a transom light and granite steps. There is a partial cellar and granite foundation. Windows have 2/2 sash.

Attached to the north end is a gabled 1-story wing which has undergone alterations.

RELATED STRUCTURES: (Describe)

Small 3-story barn with gable roof is built into a slope to facilitate the loading of hay to the third story by pulley in the rear. A second story door faces the house. The grand floor entrance is next to the road and now has double track doors. Remaining sash on the front facade is 9/6.

STATEMENT OF SIGNIFICANCE:


The house was owned by Judge Charles Dana. It is one of the few 2½-story houses built in Calais in the first half of the 19th century. The barn is typical of those built in the last half of the century.

In 1858 and 1873, the property was owned by H. Stoddard.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-120

Vt. Div, for Historic Preservation
Washington County Calais 6/79
Dana/Clark Farm, 1205-64
79-A-120 Betsy Bouton



79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Dana/Clark Farm, 1205-64
79-A-120 Betsy Bouton

Listed on State Register
 VT ACHP 12/15/1989
 Date: _____

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.Y.32, 1 mile north of E. Calais.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

SURVEY NUMBER: 1205-65 83-A-409
NEGATIVE FILE NUMBER(S): 79-A-106 #15
UTM REFERENCES: Zone/Easting/Northing A 18/704800/4916700 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Batten Farm
PRESENT FORMAL NAME: Gordon and Marion Batten, East Calais
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: Dwelling & Barns
PRESENT USE:
ORIGINAL USE: Agriculture
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR: Foster, Orcutt, Keniston
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>




STATEMENT OF SIGNIFICANCE:
 The current owner, Mrs. Batten, (Keniston) is descended from early settlers on this land. The pioneer cabin has been altered and enlarged to serve family needs. The farm structures represent the toil of generations. The granite foundations are particularly notable. It took two winters to split the stone for the barn foundation. "Lee" Keniston, a machinist in the Lane Shops in Montpelier, helped to build the home farm.
 Enough farm structures remain so that they give visual evidence of the evolution of rural/agricultural life of the 19th and early 20th century in Calais.
 The farm has well preserved stone fences.
 In 1858, the property was owned by W.S. Orcutt. M.C. Kenniston was the owner in 1873.

THREAT TO STRUCTURES: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------


MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



#5.



TOWN HIGHWAY 32



1 mile to East Calais



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Gordon and Marion Batten as per the deeds recorded in office of the town clerk.

REFERENCES:

Owners, the original house had a "date board".

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/> COMPLEX <input checked="" type="checkbox"/>		
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: 1795, 1900s	SURVEY NUMBER: 1205-65
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-106 (#15)
COMMON NAME: Batten House		OWNER: Gordon & Marion Batten 83-A-409
DESCRIPTION:		
<p>The original 1½-story Cape constructed with horizontal planks in the last years of the 18th century has been obscured by 20th century additions which include a 2½ story ell and an enclosed front porch:</p>		
MAP NUMBER: 2	DATE BUILT: c.1900	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 79-A-106 #15
COMMON NAME:		OWNER: Same
DESCRIPTION:		
<p>This 2½-story barn was built with a "square pitch". A covered ramp provides access to the second story. Animals were housed on the first story and manure was dropped to storage in the basement. Pigs were housed with the manure so that they would be kept warm as it heated.</p> <p>This barn replaced an earlier barn which stood in the field. It was built by Horace Duke's father with cantilevered hay floor; horses stood on "porch".</p>		
MAP NUMBER: 3	DATE BUILT: c.1900	SURVEY NUMBER:
FUNCTIONAL TYPE: Cow barn		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Same
DESCRIPTION:		
<p>This structure, with gable roof, was built to dry and store corn. It is now used as a garage and woodshed.</p>		
MAP NUMBER: 4	DATE BUILT: c.1900	SURVEY NUMBER:
FUNCTIONAL TYPE: Wagon shed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER: Same
DESCRIPTION:		
<p>Small, woodframe, gabled shed.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 5	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Small shed		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

Small, gabled, woodframe shed.

MAP NUMBER: 6	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Chicken House		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

A rectangular structure with gable roof used to house chickens.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:



83-409

Vt. Div. for Historic Preservation
Washington County Calais 12/83
Batten Farm 1205-65, #4, #1 N
83-A-409 Nancy Boone
John Dumville, Gina Campoli



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Batten Farm, 1205-65
79-A-106 Betsy Bouton

VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H.16, 1 mile west from Vt. Rt. 14.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:


This small farm complex retains many of its original structures, and is therefore a good example of a mid-19th century farmstead. In 1858, the farm was owned by J. Whiting, and in 1873, by N. Balentine.

SURVEY NUMBER: 1205-66
NEGATIVE FILE NUMBER(S): 79-A-106 (15-18)
UTM REFERENCES: Zone/Easting/Northing A 18/704850/4917900 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME:
PRESENT FORMAL NAME: Donald & Betty Meiklejohn
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Agricultural
TYPES OF STRUCTURES: Dwelling & Farm
PRESENT USE: Seasonal Home
ORIGINAL USE: Farm
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

THREAT TO STRUCTURES: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Donald and Betty Meiklejohn as per the deeds recorded in office of the town clerk of Calais.

Winter address:
622 Maryland Ave.
Syracuse, NY 13210

REFERENCES:

Onwers Beers Map
Walling Map

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: c.1840	SURVEY NUMBER: 1205-66
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 79-A-106 (18)	
COMMON NAME:	OWNER: Donald & Betty Meiklejohn	

DESCRIPTION:

This structure is composed of two adjoining 1½-story sections and a small shed. The gable-front section has a sidehall entrance, cornerboards and cornice returns. Foundations remain where sheds once connected to the corn barn (Map #4). The interior is rudimentary with chair rails and four panel doors. The house may have been built for a hired man according to the owners.

MAP NUMBER: 2	DATE BUILT: c.1860	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 79-A-106 (16)	
COMMON NAME:	OWNER:	

DESCRIPTION:

This 30x40' barn was recently stabilized. The hewn frame, unpainted vertical sheathing and double door on eave side of this gable roof barn make it typical of barns built in the period up until the Civil War.

MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Milkhouse	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

A small gable roofed building for handling milk.

MAP NUMBER: 4	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: "Cow Barn"	NEGATIVE FILE NUMBER: 79-A-106 (17)	
COMMON NAME:	OWNER:	

DESCRIPTION:

A small gable roofed structure with vertical sheathing used to dry and store corn.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		




79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Meiklejohn Farm, 1205-66 #2
79-A-106 Betsy Bouton



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Meiklejohn Farm, 1205-66
79-A-106 Betsy Bouton



79-77-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Meiklejohn Farm, 1205-66 #4
79-A-106 Betsy Bouton

Listed on State Register

VT ACHP

Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	North side of T.H.15 & T.H.16 intersection.
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	
Excellent	% Good 100%
Fair	% Poor %
LEVEL OF SIGNIFICANCE:	
Local	<input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:

The present owner of this property, George Balentine, is a direct descendant of Harvey Ainsworth, who was the first owner of the house. The house has been greatly altered except for the front door, which is an elaborate example of mid 19th century millwork. The barn is a typical late 19th century barn.

In 1873, the house was owned by I.O. Haskell.

SURVEY NUMBER: 1205-67
NEGATIVE FILE NUMBER(S): 79-A-106 #19, 79-A-119 #5, 82-A-292
UTM REFERENCES: Zone/Easting/Northing A 18/704750/4918275 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: George Balentine Farm
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME: Harvey Ainsworth Farm
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: Agricultural & Dwelling
PRESENT USE: Same
ORIGINAL USE: Agricultural
ARCHITECT/ENGINEER: Harvey Ainsworth
BUILDER/CONTRACTOR: OWNER Harvey Ainsworth
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>


THREAT TO STRUCTURES:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to George and Joanne Balentine as per the deeds recorded in the office of the town clerk of Calais.

REFERENCES:

George Balentine, RD 1, East Calais
Walling Map, Beers Map

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1 | DATE BUILT: c.1850 | SURVEY NUMBER: 1205-67

FUNCTIONAL TYPE: House | NEGATIVE FILE NUMBER: 79-A-106 #19, 2

COMMON NAME: Balentine House | OWNER: George & Joanne Balentine 82-A-292

DESCRIPTION: This 1½-story house with boxed cornice, returns and corner pilasters has an ell, attached shed and carriage barn. Both the interior and exterior have been altered. Small 20th century bay windows flank a mid 19th century front door. The 8-panel door has a surround with ½ sidelights with geometric tracery and paneled spandrels, a full-width transom with geometric tracery, reeded door casing and transom bar, pilasters and cornice lintel with frieze.

MAP NUMBER: 2 | DATE BUILT: 1860 | SURVEY NUMBER: 1205-67

FUNCTIONAL TYPE: Barn | NEGATIVE FILE NUMBER: 79-A-119 #5

COMMON NAME: | OWNER:

DESCRIPTION:
This large 2½-story gable roof barn with board and batten sheathing has a stone ramp from the road to the second level.

MAP NUMBER: 3 | DATE BUILT: | SURVEY NUMBER:

FUNCTIONAL TYPE: Barn | NEGATIVE FILE NUMBER: 79-A-119 (5)

COMMON NAME: | OWNER:

DESCRIPTION:
A small 1-story, gable-roofed barn for storage.

MAP NUMBER: 4 | DATE BUILT: | SURVEY NUMBER:

FUNCTIONAL TYPE: Chicken House | NEGATIVE FILE NUMBER:

COMMON NAME: | OWNER:

DESCRIPTION:
A small 1-story gable-roofed building for chickens. It has vertical sheathing in the gable peak.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 5	DATE BUILT: 1930	SURVEY NUMBER:
FUNCTIONAL TYPE: Garage	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION: A one-bay clapboarded garage or workshop.		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Balantine Farm, barn, 1205-67 #2
82-A-292 NW Gina Campoli



82-A-292

Vt. Div. for Historic Preservation
Washington County Calais 10/82
Balantine Farmhouse, 0205-67 #1 NE
82-A-292 Gina Campoli



79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Balentine Farm, 1205-67
79-A-119 Betsy Bouton



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Balentine Farm, 1205-67
79-A-106 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1983

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: T.H.16, 3/4 mile West of T.H.15.
COMMON NAME:
Old McCathy Place
FUNCTIONAL TYPE: Dwelling
OWNER: Harold & Virginia Hayden
ADDRESS: 5009 Greenwood Ave.
Chicago, Ill. 60600
ACCESSIBILITY TO PUBLIC:
Yes No Restricted
LEVEL OF SIGNIFICANCE:
Local State National

GENERAL DESCRIPTION:

Structural System fieldstone
1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
a. Wood Frame: Post & Beam Balloon
b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block 6-course
c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
a. Truss: Wood Iron Steel Concrete
b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:
Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:
Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:
Number of Stories: 1½
Number of Bays: 4x3 Entrance Location: off center gable
Approximate Dimensions: 28x26 and eave facades

SURVEY NUMBER: 1205-68
NEGATIVE FILE NUMBER: 79-A-119 #4
UTM REFERENCES: Zone/Easting/Northing 18/703850/4918100
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Hayden House
ORIGINAL FORMAL NAME:
PRESENT USE: Dwelling (seasonal)
ORIGINAL USE: Dwelling
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
Excellent Good
Fair Poor
STYLE: Vernacular Federal
DATE BUILT: c.1820

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This brick 3/4 house with wooden ell has 12/12 windows with wooden sills and lintels with radiating voussoirs. The off-center gable-end door has architrave molding. The off-center main eave side door has six flat beaded panels with cast latch and a five light transom. Modern stone chimney has been built on the inside end. Sash is 12/12.

Stone fences were built with posts and rails.

RELATED STRUCTURES: (Describe)

Small barn - modern

Garage - modern

STATEMENT OF SIGNIFICANCE:

This house is similar to the house owned by Anne Brassage (1205-62). Few small brick farmhouses from the early part of the 19th century remain in Calais. The four-bay front (3/4 house) type was used frequently in Calais, but was usually executed in wood.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

Stone fences

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
McCarthy-Hayden House, 1205-68
79-A-119 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.15, 1/2 mile north of T.H.16.
COMMON NAME:	Old Wilbur Place
FUNCTIONAL TYPE:	Dwelling/Inn
OWNER:	Thomas and Barbara Rolland
ADDRESS:	East Calais, VT
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

- Structural System
1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2 1/2

Number of Bays: 5x

Entrance Location: Center Front

Approximate Dimensions: _____

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

SURVEY NUMBER:

1205-69

NEGATIVE FILE NUMBER:

79-A-119 (1-3)

UTM REFERENCES:

Zone/Easting/Northing

18/704950/4919000

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Rolland Place

ORIGINAL FORMAL NAME:

R. Wilbur Place

PRESENT USE:

Dwelling

ORIGINAL USE:

Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Vernacular Italianate

DATE BUILT:

c.1870

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Two and one-half story main block with shorter 2½-story east wing. The main block has a central 2-story shed-roofed entrance porch with square posts and balusters. The central double-leaf door has etched glass panels. There is also a door off the second floor of the porch. Corner boards and an entablature frame both the main block and the wing. Sash is 2/2 and the windows have lip-molded lintels. A 1-story shed roof porch spans the wing.

RELATED STRUCTURES: (Describe)

Large gabled barn with board and batten siding and a covered ramp entrance to the upper story. Gabled-roofed additions were made to the east and west sides of the main mass. Circa 1870.

STATEMENT OF SIGNIFICANCE:

This property was once operated as an inn as well as a farm. The large barn is well-preserved, and together with the house, forms an intact multiple-use complex from the third quarter of the 19th century.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-~~A~~-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Wilbur-Rolland Farm, 1205-69
79-A-119 Betsy Bouton



79-A-119

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Wilbur-Rolland Farm, 1205-69
79-A-119 Betsy Bouton

Listed on State Register

VT ACHP

Date:

2/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of Vt.14, 1/4 mile north of southern road to Woodbury Lake
COMMON NAME:	Sunshine Cottage
FUNCTIONAL TYPE:	Dwelling
OWNER:	Roderick & Joan Leach
ADDRESS:	Woodbury, VT
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon Plank
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Approximate Dimensions: 24x34

Entrance Location: Central eave

SURVEY NUMBER:

1205-70

NEGATIVE FILE NUMBER:

80-A-30

UTM REFERENCES:

Zone/Easting/Northing

18/705800/4918650

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Leach House

ORIGINAL FORMAL NAME:

Dutton House

PRESENT USE: Seasonal Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1850

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The interior of this plank house has four panel doors with latches.

The exterior has strong Greek Revival style details which include: 6/6 window sash, deep fascia, molded cornice & returns, corner pilasters and a central 8-panel door with geometric surround and corner block motif and central tablet. It is in greatly deteriorated condition.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This house is a good example of Greek Revival Classic Cottage. The eight panel door with 2/3 sidelights has a distinctive wide molded surround with corner blocks and overhead tablet. In 1858, the house belonged to G.L. Dutton, and in 1873, to Mrs. A.W. Dutton.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



Woodbury
Calais

Route 14

SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
Grown up agricultural

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



80-A-30

Vt. Div. for Historic Preservation
Washington County Calais 11/79
Sunshine Cottage 1205-70 W
80-A-30 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of Town Highway #19 about 3/4 mile northeast of Vermont Route 14
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good 100% Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

SURVEY NUMBER:	1205-71
NEGATIVE FILE NUMBER(S):	79-A-120, #11 82-A-325
UTM REFERENCES:	Zone/Easting/Northing A 18 / 706450 / 4917800 B C D
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15'
COMPLEX INFORMATION ONLY	
COMMON NAME:	Shedds Place
PRESENT FORMAL NAME:	Warner and Edith Shedd Farm
ORIGINAL FORMAL NAME:	Gilbert Leonard Farm
TYPE OF COMPLEX:	Agricultural
TYPES OF STRUCTURES:	Dwelling and Barns
PRESENT USE:	
ORIGINAL USE:	Farm
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	Gilbert Leonard
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

STATEMENT OF SIGNIFICANCE:

This property belonged to the Leonard family over a long period of time. The present house was started on May 13, 1854 (written on house) by Gilbert Leonard. According to the present owners, he went off to fight in the Civil War and built the large barn when he returned. For many years, it stood next to the original pioneer cabin which was dismantled in the mid-20th century and provided replacement floor boards for the present Kent Museum.

The interior of the house retains four panel doors with latches, false mantels, a spring in the ell entrance hall and a brass works clock by Boardman built into the kitchen wall.


The house with good Greek Revival style details and barn with ramp to the second floor are typical of the time when they were built.

The present owners are the fourth recorded for the property.

THREAT TO STRUCTURES:	No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:
-----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
------------------	-------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Warner and Edith Shedd as per the deeds recorded in the office of the Town Clerk.

REFERENCES:

Warner and Edith Shedd, Ralph Weeks

RECORDED BY:

Betsy Bouton

ORGANIZATION:

VT Div. for Historic Preservation

DATE RECORDED:

June, 1979

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
 (Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 1	DATE BUILT: 1854	SURVEY NUMBER: 1205-71
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-120, #11
COMMON NAME: Old Leonard Place		OWNER: Warner and Edith Shedd

DESCRIPTION:
 This 1-1/2 story, 5 x 3 bay Classic Cottage has a long rear ell. The 6/6 sash windows have peaked window heads and original shutters. The central eave entrance door has a cornice head, 5/6 sidelights, granite steps and reeded pilaster surround. Corner pilasters and a deep entablature with returns frame the main block.

MAP NUMBER: 2	DATE BUILT: c.1867	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 82-A-325
COMMON NAME:		OWNER:

DESCRIPTION:
 This is a large three-story, gable roof barn with a ramp from the road level to the second story. An ell extends at right angles at the lower level.

MAP NUMBER: 3	DATE BUILT: 1972	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:
 Non-contributing.

MAP NUMBER: 4	DATE BUILT: 1975	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:

DESCRIPTION:
 Non-contributing.

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



1205-71

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Warner and Edith Shedd Farm Barn 1
1205-71
82-A-325 W Gina Campoli



79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Leonard/Shedd Farm, 1205-71
79-A-120 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	North side of Town Highway 18, 1/2 mile west of intersection with Town Highway 21
NAME OF DISTRICT:	
TYPE OF DISTRICT:	
PHYSICAL CONDITION OF STRUCTURES:	Excellent % Good % Fair % Poor %
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:	

STATEMENT OF SIGNIFICANCE:

This mid-19th century house and barns forming a U-shaped barnyard is a good example of typical mid-19th century construction and configuration.

This was once the home of Sylvia Bliss, a poet.


In 1858 and 1873, the house was owned by C. B. Marsh.

SURVEY NUMBER: 1205-72
NEGATIVE FILE NUMBER(S): 79-A-106 (5-7)
UTM REFERENCES: Zone/Easting/Northing A 18 / 706825 / 4917000 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad., 15'
COMPLEX INFORMATION ONLY
COMMON NAME: Anthony and Anna Pearce
PRESENT FORMAL NAME: The Old Bliss Place
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Farm
TYPES OF STRUCTURES: House and Barns
PRESENT USE:
ORIGINAL USE: Agricultural
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>


THREAT TO STRUCTURES:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



T.H. 18



STONEWALL TOPPED BY GRANITE SLABS

FOUNDATIONS

STAIRS

OLD ROAD

.5m. T.H. 21

BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Anthony and Anna Pearce as per the deeds recorded in the office of the Town Clerk of Calais.

REFERENCES:

RECORDED BY:
Betsy Bouton

ORGANIZATION:
VT Div. for Historic Preservation

DATE RECORDED:
May, 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1850	SURVEY NUMBER: 1205-72
FUNCTIONAL TYPE: Dwelling		NEGATIVE FILE NUMBER: 79-A-106
COMMON NAME:		OWNER: Anthony and Anna Pearce
DESCRIPTION:		
<p>This 1½ story, 5 x 2 bay Classic Cottage has a wing with a roof extending to cover a porch. Windows with 6/6 sash have cornice heads. Pilasters are formed with appliqued board strips. The front door has four panels and a white knob. The surround has a cornice head, pilasters, nearly full-length sidelights and paneled reveals and an entablature. The interior of this house has butternut and rosewood grained woodwork.</p>		
MAP NUMBER: 2	DATE BUILT: c.1880	SURVEY NUMBER: 1205-72
FUNCTIONAL TYPE: Stable		NEGATIVE FILE NUMBER: 79-A-106
COMMON NAME:		OWNER: Anthony and Anna Pearce
DESCRIPTION:		
<p>This small gable-roofed barn has vertical board and batten sheathing and a two-bay, recessed harnessing porch.</p>		
MAP NUMBER: 3	DATE BUILT: c.1880	SURVEY NUMBER: 1205-72
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER: 79-A-106
COMMON NAME:		OWNER: Anthony and Anna Pearce
DESCRIPTION:		
<p>This is a large, three-story, banked barn with a gable roof, vertical board and batten sheathing and a ramp to the second story. The ground level on the eave side has three corner-braced openings.</p>		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:



1205-72
#2

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
The Old Bliss Place, Barn #2,
1205-72
82-A-325 W Gina Campoli



79-A-106

Vt. Div. for Historic Preservation
Washington County Calais 6/79
Sylvia Bliss/Pearse Farm, 1205-72
79-A-106 Betsy Bouton



1205-72
#3

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
The Old Bliss Place, Barn #3,
1205-72
82-A-325 N Gina Campoli

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-73

NEGATIVE FILE NUMBER:

79-A-120

UTM REFERENCES:

Zone/Easting/Northing

18 / 605300 / 4915250

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15'

PRESENT FORMAL NAME:

Ward House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Greek Revival

DATE BUILT:

c. 1850

COUNTY: Washington
 TOWN: Calais
 LOCATION: East of cemetery on Toww Highway 4 in East Calais, 1/2 mile east of the village
 COMMON NAME: The White House on the Hill
 FUNCTIONAL TYPE: Dwelling
 OWNER: Francix X. Ward
 ADDRESS: East Calais, Vermont
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure (E11)
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other: (Breezeway)

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1-1/2 plus attic

Number of Bays: 5 x 3

Approximate Dimensions: 32' x 22'

Entrance Location: Central Eave and Off-Center Gable

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:

Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A central chimney, one of two originals, remains in this Classic Cottage together with a brick arch in the summer kitchen. The interior was damaged by fire. Some chair rail or wainscot remains. The front hall has Greek Revival style corner blocks in the woodwork. The parlor windows have deep paneled aprons. The exterior detail includes: entablature with returns, corner pilasters and peaked window heads. The six-panel front door has half-length sidelights and transom lights.

RELATED STRUCTURES: (Describe)

Small smokehouse similar to Flora George's (#48).


STATEMENT OF SIGNIFICANCE:

Dr. Asa George physician in Calais, 1824-1880, was a long time resident of this house. It is a good example of mid-19th century rural residential design.

REFERENCES:

The Vermonter, p. 17.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

VT Div. for Historic Preservation

DATE RECORDED:

May, 1979

← 1/2 mile to East Calais



79-A-120

Vt. Div. for Historic Preservation
Washington County Calais 6-/79
Gilman/Ward House, 1205-73
79-A-120 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	T.H.4, 1/4 mile west of T.H.38.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	C. Dennison & Cornelia Makepeace
ADDRESS:	(live in British Columbia or Massachusetts)
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2 plus attic

Number of Bays: 5x3

Approximate Dimensions: 32x22

Entrance Location: Central eave

SURVEY NUMBER:

1205-74

NEGATIVE FILE NUMBER:

79-A-120 #7

UTM REFERENCES:

Zone/Easting/Northing

18/704300/491

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Makepeace House

ORIGINAL FORMAL NAME:

E. Smith House

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Poor

STYLE: Greek Revival

DATE BUILT:

c.1855

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This house has some 6/6 sash windows, but most are 12/12 modern sash. Detail includes an entablature with returns, and paneled pilasters. The windows have peaked heads with cornice molding trim.

The front, central eave, door has 4/5 sidelights, pedimented head and pilastered surround.

Attached to the main block are a shed wing and barn at right angles to the wing; both have board and batten siding. The wing has polygonal shaped carriage openings and the barn is detailed with a returning cornice and paneled pilasters.

RELATED STRUCTURES: (Describe)


- 2. An open, 2-bay garage.
- 3. Small barn.
- 4. Outbuilding.

STATEMENT OF SIGNIFICANCE:

This house is a good example of a Greek Revival Classic Cottage. It was owned by E. Smith in 1858 and 1873.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:
- Abandoned
- Apple orchard

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

June 1979



79A-120


Vt. Div. for Historic Preservation
Washington County Calais 6/79
Makepeace House, 1205-74
79-A-120 Betsy Bouton



1205-74

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Makepeace House, 1205-74 SW
82-A-325 Gina Campoli



1205-74

82-A-325

Vt. Div. for Historic Preservation
Washington Calais 11/82
Makepeace Attached Barn, 1205-74
82-A-325 W Gina Campoli

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER:

1205-75

NEGATIVE FILE NUMBER:

79-A-105 (11)

UTM REFERENCES:

Zone/Easting/Northing

18/705075/4913275

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

George House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Greek Revival vernacular

DATE BUILT:

c.1840

COUNTY:	Washington
TOWN:	Calais
LOCATION:	E (inside) sharp curve on T.H.37, 1/3 mile west of T.H.38 & 39.
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Philip & Shirley George
ADDRESS:	RFD Plainfield
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other: wing
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Central eave

Approximate Dimensions: 34x26

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: Classic Cottage type.

The front door has five panels, a transom light, and a wide board surround which matches the structure's wide corner boards. The eaves are boxed with returns. A deep fascia board emulates an architrave and frieze. The recessed porch on the wing has square posts with capital-like heads. Entablature detailing on the wing is similar to the main house. The far right bay of the wing serves as a garage, with sliding track door.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

This is a good example of a vernacular Greek Revival farmhouse. Probably built c.1840, it retains the shallow roof pitch of earlier Cape dwellings, but shows simple Greek Revival detailing in the "modern" fashion. It is much plainer than the fully-developed Greek Revival Classic Cottages built in the area in the 1850's. In 1858 and 1873, the property belonged to A.P. Wheelock. A school stood across the road (T.H.37) in the 19th century, on the road (now no longer traveled) to present day Route 14.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
George House, 1205-75
79-A-105 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of T.H. 37, 3/4 mile west of T.H. 38 & T.H. 39 intersection
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Margaret Luce
ADDRESS:	East Calais
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5x2 Entrance Location: Central eave

Approximate Dimensions: 36x28

SURVEY NUMBER:

1205-76
NEGATIVE FILE NUMBER: 79-A-105 (12)
UTM REFERENCES: Zone/Easting/Northing 18/705175/4913750
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Luce House
ORIGINAL FORMAL NAME:
PRESENT USE: Dwelling
ORIGINAL USE: Dwelling
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c.1820

THREAT TO STRUCTURE:	
No Threat <input type="checkbox"/>	Zoning <input type="checkbox"/> Roads <input type="checkbox"/>
Development <input type="checkbox"/>	Deterioration <input checked="" type="checkbox"/>
Alteration <input type="checkbox"/>	Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/>
Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This Cape has a very shallow roof slope, no kneewall, boxed cornice with returns, and cornerboards.

It has 2/2 sash window with plain heads set almost directly under the eaves. There are now two interior end chimneys, but the house probably originally had a central chimney. Interior has four panel doors.

Attached to the south end of the main block is a wing composed of a series of sheds with gable roofs and horizontal plank and vertical board siding.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

✓ based

This house, on a Cape plan with low roof pitch and lack of a kneewall, is typical of those constructed in the area in the first quarter of the 19th century. It has had few alterations.

In 1858, the house was owned by Mrs. P. Pierce, and in 1873, by W. Lilley.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Luce House, 1205-76
79-A-105 Betsy Bouton

Listed on
 VT ARCH
 Date: 12/15/89

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-77

NEGATIVE FILE NUMBER:

79-A-105 (5 and 6)

UTM REFERENCES:

Zone/Easting/Northing

18/704950/4912125

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Gray House

ORIGINAL FORMAL NAME:

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1845

COUNTY: Washington
 TOWN: Calais
 LOCATION: West side of T.H.38, 3/4 mile south of intersection with T.H.37 and T.H.39
 COMMON NAME: Max Gray Farm
 FUNCTIONAL TYPE: Dwelling
 OWNER: Max and Eunice Gray
 ADDRESS: RFD Plainfield, VT
 ACCESSIBILITY TO PUBLIC: Yes No Restricted
 LEVEL OF SIGNIFICANCE: Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other: Pair of cross gables on ell

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 5x2

Entrance Location: Center front

Approximate Dimensions: _____

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

LOCAL ATTITUDES:

Positive Negative Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: This Classic Cottage has a relatively shallow roof pitch, a deep entablature with returns, and corner pilasters. The windows have peaked heads and 2/2 sash. The central front door has a plain surround and two panels of frosted glass; the door is a later replacement. The rear ell has similar entablature and window head detailing and a pair of steep cross gables flush with the wall of the facade. A 3x1 bay modern shed-roofed porch with wrought iron posts and concrete, built up floor shelters the ell entrance.

RELATED STRUCTURES: (Describe)
A circa 1860 gable-roofed barn with multiple levels and numerous additions. Vertical board siding. Built on a slope.

STATEMENT OF SIGNIFICANCE:

The house is a well-preserved early Classic Cottage. Together with the barn, it forms a typical mid-19th century farm complex. The cross gables on the ell may have been added at a later date, perhaps in the 1860's.
The property was owned by C.S. Gray in 1858 and 1873.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
MaxGray Farm, 1205-77
79-A-105 Betsy Bouton



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Max Gray Fram, 1205-77
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
District Complex Survey Form


COUNTY: Washington
TOWN: Calais
LOCATION:
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent % Good % Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:
STATEMENT OF SIGNIFICANCE:

This large farm has an important place in the historic, agricultural, landscape of Calais. The barn is an exceptional, well-preserved example of the large dairy barns built throughout Vermont during the last years of the nineteenth century.

SURVEY NUMBER: 1205-78
NEGATIVE FILE NUMBER(S): 79-A-106 #4
UTM REFERENCES: Zone/Easting/Northing A 18/705075/4912425 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Old Frank Cate Farm
PRESENT FORMAL NAME: Richard and Patricia Geisler Farm
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX:
TYPES OF STRUCTURES: Dwelling and Agricultural
PRESENT USE: Farm
ORIGINAL USE: Farm
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

THREAT TO STRUCTURES: No Threat <input type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:	LOCAL ATTITUDES: Positive <input type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to Richard and Patricia Geisler as per the deeds recorded in the office of the town clerk.

REFERENCES:

Horace Duke is the local authority on barn building.

RECORDED BY:
Betsy Bouton

ORGANIZATION:
VT Div. for Historic Preservation

DATE RECORDED:
May, 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1850	SURVEY NUMBER: 1205-86
FUNCTIONAL TYPE: Dwelling	c.1910	NEGATIVE FILE NUMBER: 83-A-409
COMMON NAME:	OWNER: Richard and Patricia Geisler	
DESCRIPTION:		
<p>A 1½ story house with several additions. It has a front shed dormer, a gambrel roof wing c.1910, and a polygonal (1 story) bay window in the central eave position. Trim on the main block includes corner pilasters, a 2-part frieze and returning cornice. The wing is spanned by a porch with a blaustrade rail and square columns.</p>		
MAP NUMBER: 2	DATE BUILT: c.1890	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn		NEGATIVE FILE NUMBER:
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>A woodframe gable roof barn with a bell. Vertical board sheathing.</p>		
MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Garage		NEGATIVE FILE NUMBER:
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>A small gabled garage.</p>		
MAP NUMBER: 4	DATE BUILT: c.1915	SURVEY NUMBER:
FUNCTIONAL TYPE: Milkhouse		NEGATIVE FILE NUMBER: 79-A-106
COMMON NAME:	OWNER:	
DESCRIPTION:		
<p>A small gabled milkhouse sheathed in clapboards.</p>		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER: 5	DATE BUILT: 1897	SURVEY NUMBER:
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 79-A-106 #4	
COMMON NAME:	OWNER:	

DESCRIPTION:

A large four story, gable roofed barn with a square ventilator topped by a horse weathervane. This barn is entered by a ramp from the road level to the third level. Beside this entrance is an entrance on the second level to the livestock area. Manure and stable area is on the ground level. An ell is attached to the rear.

Forrest Gray was present at the raising - Tape of his recollection owned by Tina Bielenberg.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	

DESCRIPTION:



79-A-106

Vt. Div. for Historic Preservation
Washington County - Calais 6/79
Cate-Gersler Farm, 1205-78
79-A-106 Betsy Bouton



83-409

Vt. Div. for Historic Preservation
Washington County, Calais 12/83
Geisler Farm 1205-78, NW
83-A-409 Nancy Boone
John Dumville, Gina Campoli

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER:

1205-79

NEGATIVE FILE NUMBER:

79-A-105

UTM REFERENCES:

Zone/Easting/Northing

18 / 705100 / 4912500

U.S.G.S. QUAD. MAP:

Plainfield Quad. 15'

PRESENT FORMAL NAME:

Tonks House

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
 Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT:

c.1860

COUNTY: Washington
 TOWN: Calais
 LOCATION: East Hill, Calais, west side
 of TH 38, .5 miles south of TH 37 and 39
 COMMON NAME:
 FUNCTIONAL TYPE: Residence
 OWNER: Philip and Julia Tonks
 ADDRESS: R.F.D.
 Plainfield, Vermont
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle
Shiplap Novelty Asbestos Shingle Sheet Metal
Aluminum Asphalt Shingle Brick Vener Stone Vener
Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle
Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys
Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel
Jerkinhead Saw Tooth With Monitor With Bellcast
With Parapet With False Front Other:

Number of Stories: 1-1/2

Number of Bays: 3 x 2

Entrance Location: Right Side, Gable End

Approximate Dimensions: 22' x 30' plus ell

THREAT TO STRUCTURE:

No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:

Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The windows have 6/6 sash and plain frames. The door surround, is elaborated with pilasters, an entablature with scalloped wooden applique detail and a crowning enclosed pediment. The door has five panels and the ell includes a recessed porch. A massive new chimney straddles the roof ridge.

RELATED STRUCTURES: (Describe)

Small garage/shed with gable roof.

STATEMENT OF SIGNIFICANCE:

This temple front, sidehall plan house is one of a small number of its type in Calais. The entrance door with pedimented head and sidelights is a good example of the late Greek Revival style. The roof, which lacks any cornice or other decorative detail, was probably reworked at some time.

REFERENCES:

MAP: (Indicate North in Circle)



↑
.5m to T.H. 37 & 39



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other: spectacular view to west

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May, 1979



1205-79

79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Tonks House, 1205-79
79-A-105 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 District Complex Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: East Hill, East side of TH 38, 1/3 mile south of TH 37 and 38.
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent 50% Good 50% Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
THEMES:

SURVEY NUMBER: 1205-80
NEGATIVE FILE NUMBER(S): 79-A-105
UTM REFERENCES: Zone/Easting/Northing A 18/702275/4912600 B C D
U.S.G.S. QUAD. MAP: Plainfield Quad. 15' Series
COMPLEX INFORMATION ONLY
COMMON NAME: Grand View Farm
PRESENT FORMAL NAME: Grout House
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Agricultural
TYPES OF STRUCTURES: Barn, residence and farm
PRESENT USE:
ORIGINAL USE: Farm
ARCHITECT/ENGINEER: Unknown
BUILDER/CONTRACTOR: Unknown
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>

STATEMENT OF SIGNIFICANCE:

This farm complex is composed of a Classic Cottage type farmhouse and one of a dwindling number of round barns in Vermont. The barn, in fair condition, represents a rather widespread experiment in barn construction which was at its peak about 1900. Round barns were designed so that cows faced inward toward silos and hay shoots. (See enclosed article from "Hoard's Dairyman" which discusses a round barn in Grand Isle, Vermont.)

THREAT TO STRUCTURES:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:




LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



EAST HILL RD (T.H. 30)

DRIVE



BOUNDARY DESCRIPTION:

The boundary of this complex is coextensive with that of the property belonging to George and Joan Grout as per the deeds recorded in the office of the Calais town clerk.

REFERENCES:

RECORDED BY:
Betsy Bouton

ORGANIZATION:
VT Div. for Historic Preservation

DATE RECORDED:
May, 1979

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: c.1900	SURVEY NUMBER: 1205-76
FUNCTIONAL TYPE: Barn	NEGATIVE FILE NUMBER: 79-A-105(9,10)	
COMMON NAME: The Round Barn	OWNER: George & Joan Grout 83-A-409	
DESCRIPTION:		

This 3-story, round barn has 6/6 sash windows and clapboard sheathing. A covered ramp built up with earth provides access to the third story. Centered on the peak of the conical roof is a round louvered ventilator.

*Burned 3/87
Curtis Johnson*

MAP NUMBER: 2	DATE BUILT: c.1855	SURVEY NUMBER:
FUNCTIONAL TYPE: Dwelling	NEGATIVE FILE NUMBER: 83-A-409	
COMMON NAME:	OWNER: George and Joan Grout	
DESCRIPTION:		

A 1½ story, 5 x 2 bay Classic Cottage with wing. The roof of the wing has been raised to accommodate a garage. The wing's recessed porch has turned posts and a concrete floor. The main mass of the house includes wide aluminum sheathing, a stone foundation and a recessed front entrance door. There is little door, window or cornice trim due to the addition of synthetic siding.

MAP NUMBER: 3	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE: Shed	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: George and Joan Grout	
DESCRIPTION:		

Machine Shed - long, woodframe block.

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT COMPLEX
(Include individual survey number ONLY if surveyed individually.)

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		



83-409

Vt. Div. for Historic Preservation
Washington County Calais 12/83
Grand View Farm, #18 N
83-A-409 1205-80 Nancy Boone
John Dumville, Gina Campoli



79A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Grout Farm, 1205-80
79-A-105 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: East side of East Hill (T.H.38)
 1/3 mile north of T.H.37 & T.H.39 inter-
 section.
 COMMON NAME:
 Ides Homestead
 FUNCTIONAL TYPE: Dwelling
 OWNER: Roy and Beverly Balles
 ADDRESS: RFD
 Plainfield
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

SURVEY NUMBER:
 1205-81
 NEGATIVE FILE NUMBER:
 79-A-105 (13)
 UTM REFERENCES:
 Zone/Easting/Northing
 18/705725/4913550
 U.S.G.S. QUAD. MAP:
 Plainfield Quad., 15' Series
 PRESENT FORMAL NAME:
 Balles House
 ORIGINAL FORMAL NAME:
 PRESENT USE: Dwelling
 ORIGINAL USE: Dwelling
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Vernacular
 DATE BUILT:
 1820

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other: Rafter frame
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other: front
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel ell
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 1½
 Number of Bays: 5x3 Entrance Location: Central eave
 Approximate Dimensions: 40x36

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This Cape has a central chimney with cooking oven and fireplace. Eaves are cropped. A shed dormer is on the rear roof slope. Windows have 2/2 sash. There are now two small 1-light modern windows on the rear of the left side. The large ell, which contains a garage, has a gambrel roof.

RELATED STRUCTURES: (Describe)

An hexagonal silo (in poor condition) now belongs to Ed & Sue Scribner. (See #1205-82).

STATEMENT OF SIGNIFICANCE:

This is one of the few houses in Calais which dates from the first quarter of the 19th century still retaining a central chimney, oven and cooking fireplace. It is a good example of Cape architecture.

The house was owned by I. Ide in 1858 and 1873.

REFERENCES:

Owner
Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Ides Homestead/Bolles House,
1205-81
79-A-105 Betsy Bouton

Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY: Washington
 TOWN: Calais
 LOCATION: East side of East Hill Rd.
 (T.H.38) 1/3 mile north of T.H.37 & 39
 intersection.
 COMMON NAME:
 FUNCTIONAL TYPE: Silo
 OWNER: Ed & Sue Scribner
 ADDRESS:
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

SURVEY NUMBER:
 1205-82
 NEGATIVE FILE NUMBER:
 79-A-105 (14 & 15)
 UTM REFERENCES:
 Zone/Easting/Northing
 18/705725/4913550
 U.S.G.S. QUAD. MAP:
 Plainfield Quad., 15' Series
 PRESENT FORMAL NAME:
 Scribner Silo
 ORIGINAL FORMAL NAME:
 PRESENT USE: None
 ORIGINAL USE: Feed storage
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 STYLE: Functional
 DATE BUILT: c.1900

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Asbestos Shingle Sheet Metal
 Aluminum Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Bay Window Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 4
 Number of Bays: Entrance Location:
 Approximate Dimensions: 15x15

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: sf2 no botal

The silo is constructed of horizontal planks nailed one on top of the others, on an octagonal plan. The octagonal hipped roof is sheathed in wood shingles.

RELATED STRUCTURES: (Describe)

Barn foundation.

STATEMENT OF SIGNIFICANCE:

This wooden silo gives character to the rural, agricultural landscape. There are few octagonal silos remaining in the state. It was originally associated with an adjoining barn; all that remains of the barn is its stone foundation. The silo was part of the agricultural complex of the Ides Homestead, 1205-82.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Scribner Octagonal Silo, 1205-82
79-A-105 Betsy Bouton

Barboursville
 Listed on State Register
 VT ACHP
 Date: 12/15/1989

STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	West side of East Hill Rd. (T.H.38), 1 mile north of T.H.37 & 39 intersection.
COMMON NAME:	The Bugbee Farm
FUNCTIONAL TYPE:	Dwelling
OWNER:	Ed & Sue Scribner
ADDRESS:	RD 2, Plainfield
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1 1/2

Number of Bays: 3 bay front Entrance Location: Right side, gable end

Approximate Dimensions: 20'-front facade of main block

SURVEY NUMBER:	1205-83
NEGATIVE FILE NUMBER:	79-A-105 (16) 83-A-409
UTM REFERENCES:	Zone/Easting/Northing 18/705925/4914100
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15' Series
PRESENT FORMAL NAME:	Scribner House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Dwelling
ORIGINAL USE:	Dwelling
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Greek Revival w/Italianate elements
DATE BUILT:	c.1858

THREAT TO STRUCTURE:	No Threat <input type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input checked="" type="checkbox"/> Alteration <input type="checkbox"/> Other:
----------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

LOCAL ATTITUDES:	Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
------------------	-------------------------------------------------------------------------------------------------------------------------

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

The main block is flanked by two shorter 1½-story ells, [redacted]
This house has an ornate bracketed cornice with plain fascia, paneled pilasters and peaked window heads. The front door has a peaked head, 2/3 sidelights, paneled reveals and granite sill. A central door and full-width porch appear to have been removed from the right (north) ell. Interior has ornate woodwork, fireplace and some c.1870's wallpaper.

RELATED STRUCTURES: (Describe)

Large cowbarn-c.1940 "Quonset hut" roof. Noncontributing to the historic district.
Small horse barn - modern
Granite fence posts - now curbing

STATEMENT OF SIGNIFICANCE:

This house may have been constructed c.1858, as D. Fay is listed as owning a residence on the site in 1858. By 1873, W.C. Bugbee was listed as the owner.
The house is a good example of a Greek Revival gable-front house with side-hall plan. The brackets were probably added in the 1870's to give the house a "modern" Italianate appearance.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Bugbee/Scribner Farm, 1205-83
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/18/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East Hill (T.H.38), 1/3 mile south of T.H.4.
COMMON NAME:	Hawkstead Farm
FUNCTIONAL TYPE:	Dwelling
OWNER:	David & Brenda Hawkins
ADDRESS:	RD 2, Plainfield
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 2

Number of Bays: 5x4

Entrance Location: Central front

Approximate Dimensions: 40x40

THREAT TO STRUCTURE:

No Threat Zoning Roads Development Deterioration Alteration Other:

SURVEY NUMBER:

1205-84

NEGATIVE FILE NUMBER:

79-A-105 #17

UTM REFERENCES:

Zone/Easting/Northing

18/706575/4914750

U.S.G.S. QUAD. MAP:

Plainfield Quad., 15' Series

PRESENT FORMAL NAME:

Hawkins House

ORIGINAL FORMAL NAME:

Rockwood Farm

PRESENT USE: Dwelling

ORIGINAL USE: Dwelling

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Poor

STYLE: Federal

DATE BUILT:

1823 on name board

LOCAL ATTITUDES:

Positive Negative

Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

This square house with hipped roof retains its original lines, although a wing was added at some time to the south end of the main block.

The front door, with six panels and cast iron latch, is an outstanding feature. This doorway has a fan light with radiating muntins and 1/2-length sidelights which have eight panes. Window sash is now 1/1 and 2/2. The aluminum siding may have obscured additional cornice, pilasters and window head detail. The original Federal style mantels are preserved.

RELATED STRUCTURES: (Describe)

A gambrel roofed barn.

STATEMENT OF SIGNIFICANCE:

According to the owner, two brothers built this house and another similar one. This house is the only Federal style hipped-roof house remaining in Calais.

In 1858, the house was owned by S.O. Tucker, and in 1873, by C.W. Tucker.

REFERENCES:

- Owner
- Walling Map
- Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-7-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Hawkstead Farm/Hawkins House,
1205-84
79-A-105 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of T.H.18 on East Hill, 1/4 mile north of T.H.4 intersection
COMMON NAME:	
FUNCTIONAL TYPE:	Dwelling
OWNER:	Madeline Wilkinson
ADDRESS:	RFD, Plainfield
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Post & Beam Balloon
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Other:
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:
- Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:
- Number of Stories: 1 1/2
- Number of Bays: 5x2 Entrance Location: Central eave
- Approximate Dimensions: 30x26

THREAT TO STRUCTURE:
No Threat Zoning Roads
Development Deterioration
Alteration Other:

SURVEY NUMBER: 1205-85
NEGATIVE FILE NUMBER: 79-A-105
UTM REFERENCES: Zone/Easting/Northing 18/706600/4915280
U.S.G.S. QUAD. MAP: Plainfield Quad., 15' Series
PRESENT FORMAL NAME: Wilkinson House
ORIGINAL FORMAL NAME:
PRESENT USE: Dwelling
ORIGINAL USE: Dwelling
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular
DATE BUILT: c.1835

LOCAL ATTITUDES:
Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A shallow roof pitch and lack of a kneewall indicate that this house dates from the early part of the 19th century.

Window and door casings have peaked heads. Sash is now 2/2. Corner boards and cornice with deep fascia frame the main block. The house has a full cellar. The central chimney has been reworked.

Wilkinson House

RELATED STRUCTURES: (Describe)

Horse barn - c.1900
Garage - 1930's.

STATEMENT OF SIGNIFICANCE:

According to the owner, Miss Wilkinson, the wing of this house was built as a milkroom. The older Cape form of the house, along with the spartan Greek Revival detail, indicate that it was probably built c.1835.

In 1858 and 1873, the property was owned by C.H. French.

REFERENCES:

Owner
Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-17-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
Wilkinson House, 1205-85
79-A-105 Betsy Bouton

Listed on State Register
VT ACHP
Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	E. Hill, E. side of T.H.18, 3/4 mile north of T.H.4 intersection.
COMMON NAME:	#6 School
FUNCTIONAL TYPE:	School
OWNER:	Alice Blachly
ADDRESS:	RD Marshfield
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input checked="" type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER:	1205-87
NEGATIVE FILE NUMBER:	79-A-105 #19
UTM REFERENCES:	Zone/Easting/Northing 18/706950/4916000
U.S.G.S. QUAD. MAP:	Plainfield Quad., 15' Series
PRESENT FORMAL NAME:	Blachly House
ORIGINAL FORMAL NAME:	
PRESENT USE:	Dwelling
ORIGINAL USE:	School
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE:	Greek Revival
DATE BUILT:	c.1850

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer
Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1

Number of Bays: 2x4

Approximate Dimensions: 20x28

Entrance Location: Boys & Girls
on gable end.

THREAT TO STRUCTURE:
No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES:
Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Architectural details include entablature with boxed cornice, returns, and deep double eave board representing architrave and frieze. 6/6 windows are set in surrounds with peaked heads. The school number is painted on a triangular panel in the gable tympanum. An enclosed porch with novelty-sided porch wall and hipped roof now spans the front facade.

RELATED STRUCTURES: (Describe)

A small garage has gable roof, novelty sheathing and double doors.

STATEMENT OF SIGNIFICANCE:

One room schools have had important social as well as educational functions in rural communities.

This schoolhouse is typical of those built during the mid 19th century. It appears on maps of 1858 and 1873 at this location.

REFERENCES:

Walling Map
Beers Map

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Betsy Bouton

ORGANIZATION:

Vt. Div. for Historic Preservation

DATE RECORDED:

May 1979



79-A-105

Vt. Div. for Historic Preservation
Washington County Calais 5/79
#6 School/Blachly House, 1205-87
79-A-105 Betsy Bouton

Listed on State Register

VT ACHP

Date:

12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Washington
TOWN:	Calais
LOCATION:	East side of County Road, 1.3 miles north of Maple Corner.
COMMON NAME:	
FUNCTIONAL TYPE:	Residence
OWNER:	Rob Apple
ADDRESS:	Calais, Vermont
ACCESSIBILITY TO PUBLIC:	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 5 x 3

Approximate Dimensions: 24 x 18

Entrance Location: Center Eaves side

SURVEY NUMBER: 1205-89

NEGATIVE FILE NUMBER: 84-A-11

UTM REFERENCES:
Zone/Easting/Northing
18/700100/4918625

U.S.G.S. QUAD. MAP:
Plainfield, Vermont 15'

PRESENT FORMAL NAME:
Apple House

ORIGINAL FORMAL NAME:

PRESENT USE: Residence

ORIGINAL USE: Residence

ARCHITECT/ENGINEER: Unknown

BUILDER/CONTRACTOR: Unknown

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good Fair Poor

STYLE: Vernacular Greek Revival

DATE BUILT: c.1870

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Alteration Other:

LOCAL ATTITUDES:

Positive Negative
Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

A later version of a Greek Revival Classic Cottage with a relatively steep pitched roof and high kneewall punctuated by multi-paned kneewall windows. Greek Revival style trim includes a returning cornice, 2-part frieze board and corner pilasters. The modern multi-paned windows have louvered shutters and the main entrance includes an Italianate, double arch paned door with plain surrounds. Prominent on the east, gabled wing is a steeply pitched wall dormer. A greenhouse has recently been added to the front first story of the wing and a garage opening is on the east end.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

The Apple House illustrates a late Classic Cottage type farmhouse with its steep roof and high kneewall. Although there are many quintessential Greek Revival Classic Cottages in Calais, there are few showing this later form. The house is in good condition and has had few intrusive alterations.

REFERENCES:

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

VT Div. for Historic Preservation

DATE RECORDED:

January 5, 1984



84-A-11

Vt. Div. for Historic Preservation
Washington County Calais 1/84
Apple House, 1205-89
84-A-11 Gina Campoli

Listed on State Register

VT ACHP

Date: 12/15/1989

STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Washington
TOWN: Calais
LOCATION: East side of County Road .3 miles north of Maple Corner.
COMMON NAME:
FUNCTIONAL TYPE: Residence
OWNER: Alice Barker ADDRESS: Calais, Vermont
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE: Local <input type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>

SURVEY NUMBER: 1205-88
NEGATIVE FILE NUMBER: 84-A-11
UTM REFERENCES: Zone/Easting/Northing 18/699750/4916700
U.S.G.S. QUAD. MAP: Plainfield, Vermont 15'
PRESENT FORMAL NAME: Barker House
ORIGINAL FORMAL NAME:
PRESENT USE: Residence
ORIGINAL USE: Residence
ARCHITECT/ENGINEER: Unknown
BUILDER/CONTRACTOR: Unknown
PHYSICAL CONDITION OF STRUCTURE: Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/>
STYLE: Vernacular Greek Revival
DATE BUILT: c.1860

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone Brick Concrete Concrete Block faced
- Wall Structure
 - Wood Frame: Post & Beam Balloon
 - Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - Iron d. Steel e. Other:
- Wall Covering: Clapboard Board & Batten Wood Shingle Shiplap Novelty Asbestos Shingle Sheet Metal Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Other:
- Roof Structure
 - Truss: Wood Iron Steel Concrete
 - Other:
- Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:
- Engineering Structure:
- Other:

Appendages: Porches Towers Cupolas Dormers Chimneys Sheds Ells Wings Bay Window Other:

Roof Style: Gable Hip Shed Flat Mansard Gambrel Jerkinhead Saw Tooth With Monitor With Bellcast With Parapet With False Front Other:

Number of Stories: 1½

Number of Bays: 3 x 4

Approximate Dimensions: 16 x 25

Entrance Location: Right gable front

THREAT TO STRUCTURE: No Threat <input checked="" type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:

LOCAL ATTITUDES: Positive <input checked="" type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION: no base

This small, plainly trimmed temple front house has a boxed returning cornice and wide frieze, and corner boards, subtle suggestions of the Greek Revival style. The entrance is flanked by narrow $\frac{3}{4}$ sidelights with plain surrounds and a primitive 2 part cornice above. The windows, primarily $\frac{6}{6}$, have similar cornice moldings and louvered shutters. The rear gabled wing is punctuated by gabled dormers and access is through an open shed porch with recently added, "recycled", Italianate chamfered posts and elaborate scroll brackets. A small, 1 story, shed roofed, novelty sided wing is on the wings north facade.

RELATED STRUCTURES: (Describe)

- 1) Barn c.1880. Small gabled bank barn, vertical board siding and a sliding door on the west eaves side.
- 2) Garage c.1940. Gabled garage, 2 bays, novelty siding, hayloft door is gable.


STATEMENT OF SIGNIFICANCE:

The owner states that this small and plain, yet dignified farmhouse once served as a tenant farmhouse for a large farm across the road. It is an excellent example of the temple front, sidehall type popular in Calais and all of Vermont during the Civil War era.

REFERENCES:

Anne Barker

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Roadside Strip Development
- Other:

RECORDED BY:

Gina Campoli

ORGANIZATION:

VT Div. for Historic Preservation

DATE RECORDED:

January 5, 1984



84-A-11

Vt. Div. for Historic Preservation
Washington County Calais 1/84
Barker House, 1205-88 NE
84-A-11 Gina Campoli